TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48128161
Order No. / Reference: 27097793
Inspection date: 14 Oct 2026

Manufacturer: Volkswagen	Model: Tiguan Allspace 2.0 TDI SCR Comfortline
VIN: WVGZZZ5NZMM099529	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Tiguan Allspace 2.0 TDI SCR Comfortline	
Vehicle Identification number	WVGZZZ5NZMM099529
Mileage (Read)	127,008 km
First registration	26 May 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Pure White
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey-Black
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	2,000 km
Last service on / at	02/2026 at 120,003 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA786020
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	0603 / BZG 13861		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,230 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/45 R19 100V	Summer tires (with run-flat tires) on Light alloy	Pirelli	5mm / 5mm
2)	255/45 R19 100V	Summer tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tires (with run-flat tires) on Light alloy	Pirelli	5mm / 5mm
2)	215/65 R17 99H	Winter tires (with run-flat tires) on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	145/85 R18 103M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Airbag for driver and front passenger including knee airbag on the driver's side (passenger airbag deactivation - knee airbag on driver and front passenger side)
- Exterior mirror housings painted silver
- Chrome applications on mirror adjustment switches, window regulator switches, door pull handles (interior door operation in matte chrome)
- Diesel particulate filter
- Dual-tone signal horn
- Electronic parking brake including Auto Hold function (Volkswagen's Auto Hold function is an extension of the electronic parking brake. The Auto Hold function prevents the vehicle from rolling away unintentionally when stationary or starting off, without the driver having to constantly apply the brakes. In this way, Auto Hold offers maximum driving comfort. - If the ABS wheel speed sensors detect rolling, the braking torque is automatically increased until the vehicle comes to a complete stop.)
- Pedestrian detection
- luggage compartment cover
- Luggage compartment lid with electric opening and closing (adjustable opening angle)
- Halogen dual headlights and turn signals under a common clear glass cover (with LED daytime running lights)
- LED license plate lighting
- Rear headrests (3)
- Front headrests (safety-optimized - adjustable lengthwise and height)
- Reading lights: 2 front and 2 rear
- Manual headlight range adjustment
- Multifunction display "Premium" (with multi-color display)
- Fog lights and cornering lights
- Emergency braking assistant "Front Assist" (detects critical distance situations and helps to shorten the stopping distance - warns the driver visually and audibly in dangerous situations as well as with a preventive brake jolt)
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Rain sensor
- Tire pressure monitoring system
- Gearshift knob in leather
- Power steering
- Seats: Front passenger seat backrest folds down completely
- Seats: Folding tables on the backs of the front seats
- Seats: Comfort seats in the front (passenger seat backrest folds down completely - drawers under the front seats)
- Seats: Front seats with height adjustment
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet (on the rear center console and in the luggage compartment)
- Telephone interface
- Storage compartments in the overhead console
- Airbag, head airbag system including front side airbags (for front and rear passengers)
- Aspherical exterior mirror on driver's side (right exterior mirror, convex)
- Chrome trim on the side windows
- Silver anodized roof rails
- Decorative inserts "Checker Flag Titanium" (for instrument panel and front door panels)
- Parking aid (acoustic warning signals for obstacles in the front and rear area)
- Electronic stability program with counter-steering support (including ABS, ASR, EDS, MSR and trailer stabilization)
- Automatic headlight control, with daytime running lights ("Leaving home" function and manual "Coming home" function)
- Electric windows front and rear
- High beam control Light Assist
- Windscreen made of laminated safety glass, heat and sound insulating
- Luggage compartment lighting (additional, removable and usable as a flashlight)
- Transmission: 6-speed manual transmission
- Rear window heated
- Rear window wiper with intermittent function
- Interior mirror automatically dimming
- Instrument cluster with electronic speedometer (odometer, trip meter, tachometer)
- Paint finish: Solid
- Steering wheel: Multifunction steering wheel in leather
- Light in the front footwell
- front center armrest
- Fatigue detection
- Non-smoking version (storage compartment and 12V socket at the front)
- Emergency call service (no registration required, service is activated upon delivery)
- Upholstery: Cloth
- Radio "Composition" (16.5 cm touchscreen - dual tuner with phase diversity for best possible radio reception - Radio Data System (RDS) - MP3 playback - USB-C interface with Apple compatibility - 4 x 20 watt output power - 3-band tone control - telephone interface)
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear including belt tensioner for the outer rear seats - warning tone and light for unfastened seat belts at the front and rear)
- Seats: Lumbar support in the front
- Seats: Rear bench seat asymmetrically split (longitudinally sliding and folding - with pass-through and center armrest)
- Start-stop system with brake energy recuperation

- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote keys
- Bumper in body color (lower bumper section black - center sections in granite grey metallic)
- Textile floor mats front and rear
- Prepared for "We Connect" and "We Connect Plus"
- Green thermal insulation glazing, sides and rear

Extra equipment

- Foldable towbar (electric release)
- Anti-theft alarm system with safe locking (anti-theft alarm system with interior monitoring, backup horn and tow-away protection, central locking with safe locking, remote control and 2 remote folding keys)
- Wirelessly heated windshield (infrared-reflective)
- Navigation system "Discover Media" incl. "Streaming & Internet" (8 speakers - 20.3 cm touchscreen - dual tuner with phase diversity for best possible radio reception - Radio Data System (RDS) - MP3 playback - USB-C interface with Apple compatibility - 4 x 20 watt output power - map with 2D display - telephone interface - traffic sign recognition - points of interest - DAB+ digital radio reception)
- Package: "Easy Open & Close" package with safe locking (luggage compartment lid with sensor-controlled opening and closing, with remote unlocking - Keyless locking and starting system "Keyless Access" with safe locking)
- Package: R-Line Volkswagen R (LED reading lights, alloy wheels "Sebring" 8.5 J x 19 grey metallic, AirStop tires 255/45 R 19, low rolling resistance, black headliner, aluminum front door sill trims with R-Line logo, black R-style rear spoiler, fog lights, cornering lights, brushed stainless steel pedals and footrest, R-Line leather multifunction sports steering wheel, wheel locks, fabric seat centers (front and outer rear), microfiber side bolsters, R-style bumpers and side skirts, top comfort front seats)
- Windows: Rear side windows and rear window tinted
- 230 volt socket
- Adaptive Cruise Control (ACC) up to 210 km/h and Front Assist emergency braking system (ACC up to 210 km/h, including speed limiter and "Front Assist" - drowsiness detection)
- Chassis: Sport chassis
- Air conditioning "Air Care Climatronic" (3-zone temperature control - allergen filter - rear controls)
- Mesh partition
- Package: "Business Premium" package (2 USB-C ports in the front, 1 USB-C charging port in the rear center console - App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Digital Cockpit Pro, multicolor, various info profiles selectable - Automatically heated windshield washer nozzles - Headlight cleaning system - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Package: Ambient lighting package for R-Line (2 LED reading lights front and 2 rear - ambient lighting (1-color), in the door trims - "Dark Grid" decorative inserts for instrument panel and front door trims - front door sill trims in aluminum, with R-Line logo)
- Panoramic tilt/slide sunroof with panoramic roof at the rear (2 LED reading lights at the front and 2 at the rear - panoramic tilt/slide sunroof with panoramic roof at the rear)
- Wheels: Spare wheel, weight and space saving, 18 inch (on-board tools and jack)
- LED taillights, dark red
- Voice control

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Brightware - lower - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
3	Wheel / tyres	Tyre - front right side - Broken / torn - Replace
4	Vehicle glazing	Door glass - rear right side - Scratch(es) - Replace
5	Rear bumper	Rear bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Trim / covers	Floor mats - Broken / torn - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book (Digitaler Ausdruck)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Side right, Provided by user / customer, from 22 Apr 2022	9.677,01 €

Repainting

No.	Repainting
1	Bonnet, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet	276 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Damage 1: Door - front left side: Brightware - lower - Scratch(es) - Smart repair



Damage 1: Door - front left side: Brightware - lower - Scratch(es) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 3: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 3: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 3: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 4: Vehicle glazing: Door glass - rear right side - Scratch(es) - Replace



Damage 4: Vehicle glazing: Door glass - rear right side - Scratch(es) - Replace



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Paint



Wear and tear 4: Trim / covers: Floor mats - Broken / torn - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Repainting 1: Bonnet



Repainting 1: Bonnet