TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 47778604
Order No. / Reference: 26744908
Inspection date: 25 Sept 2026

Manufacturer: Audi	Model: A3 40 TDI Limousine quattro S tronic advanced
VIN: WAUZZZGY8RA050064	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 40 TDI Limousine quattro S tronic advanced	
Vehicle Identification number	WAUZZZGY8RA050064
Mileage (Read)	39,406 km
First registration	14 Dec 2023
Number of holders	1
Next periodical technical inspection	12/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	All-wheel drive
Type of vehicle	Saloon car
Colour / colour code	ibisweiss (Y9C)
Doors / Seats	4 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	16,800 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY322483
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BWW 00616		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,015 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 94V	Winter tyres on Light alloy	Yokohama	5mm / 6mm
2)	225/45 R17 94V	Winter tyres on Light alloy	Yokohama	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91Y	Summer tyres (Without wheel rim)	Nexen	6mm / 6mm
2)	225/45 R17 91Y	Summer tyres (Without wheel rim)	Nexen	6mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- All-wheel drive "quattro" (driving situation-dependent all-wheel drive of all 4 wheels)
- Traction control ASR
- Audi pre sense front (within system limits, uses a front radar to detect the area in front of the vehicle and warns the driver with visual and acoustic signals to indicate a potential hazard from vehicles ahead, whether moving or stationary – pedestrian and cyclist detection registers, within system limits, when a pedestrian or cyclist is moving on or crossing the road. The system then warns the driver with an acoustic and visual signal)
- Additive-free diesel particulate filter (DPF)
- Electric auxiliary air heater
- Electromechanical parking brake
- Electronic Differential Lock (EDS)
- Electronic Stability Control (ESC)
- Chassis: Standard chassis
- Electric windows front and rear
- Remote key (without Safe-Lock)
- front and rear floor mats
- Speed limiter
- Transmission: S tronic 7-speed
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Paint finish: Solid
- Light and rain sensor
- Non-smoking version
- Wheel: Alloy wheels - 17 inch - multi-spoke (8.0 J × 17, tires 225/45 R 17)
- Radio: MMI Radio plus (10.1-inch color display (1,540 x 720) including MMI touch operation, digital instrument cluster with 10.25-inch color display, Audi music interface with two USB-C ports, each with data and charging function, Bluetooth interface (hands-free calling and audio streaming), passive speakers with 4 speakers in the front and 2 in the rear (80 watts), AM/FM phase diversity, DAB+ speed-dependent volume adjustment, voice control system for controlling infotainment and vehicle functions, WLAN hardware)
- Seats: Standard front seats
- Lane Departure Warning (Within system limits, this helps prevent unintentional lane departures. If the system is activated, operational, and no turn signal has been used, the Lane Departure Warning assists by making corrective steering interventions to prevent crossing detected lane markings. Additional steering wheel vibration can be activated upon driver request. The system is functional from approximately 60 km/h.)
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect remote & control
- Evasive steering assist and turning assist
- Electrically adjustable and heated exterior mirrors
- Exterior mirror housings in body color
- third brake light
- Headliner in steel grey fabric
- Decorative inlays in silk-effect lacquer, platinum grey
- Decorative strips in black glass look
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches (speed, time, mileage, outside temperature, fuel warning with remaining range, shift indicator (for manual and automatic transmissions in manual mode), current radio station or music track, radio and media lists, classic-style display; if available: telephone menu (in conjunction with multifunction steering wheel), trip computer with short- and long-term memory, fuel-saving tips for more economical driving including break recommendations)
- Heated rear window
- Electrically operated child safety lock
- Rear headrests (3)
- Front headrests
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction controls and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with six multifunction buttons. Shift paddles allow manual gear changes.)
- Tire pressure monitoring system
- Tire repair kit
- Headlight
- Electromechanical power steering
- 3-point automatic seat belts
- Seat covers in fabric (seat center panel in fabric - seat side bolsters, front center armrest (if ordered) and headrests in solid black fabric)
- Seats: Rear seat backrest foldable
- Start-stop system
- 12-volt power outlet in the rear
- 12V socket
- Glazing: Green tinted heat-insulating glazing (for rear window, door and side windows - rear window heated, with timer)
- Electronic immobilizer
- Central locking with remote control

Extra equipment

- Audi connect navigation & infotainment
- Audi virtual cockpit
- Cruise control system with preparation for adaptive cruise control
- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Audi drive select
- Deletion of model designation and performance/technology lettering
- Hold assist
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction plus and shift paddles
- Navigation: MMI Navigation plus with MMI touch
- Wheel: Audi new car tire warranty
- Rear view camera
- Seat covers in fabric routine
- Seats: Front sports seats
- Glazing: Sun protection glazing, tinted

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Seat - front	Seat cover - left side - Soiled - Clean
2	Wheel / tyres	Tyres - complete set - Differs from the original configuration - Un- / install
3	Instrument panel	Indicator light (presence) - Specify findings - Perform diagnosis

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Mudguard - right side

Paint coat thickness measurement

Roof	122 µm	Roof rail - left side	133 µm
Roof rail - right side	104 µm	Boot lid / rear door	126 µm
Mudguard - left side	129 µm	Mudguard - right side	155 µm
Bonnet	133 µm	Side panel - rear left side	130 µm
Side panel - rear right side	112 µm	Door - rear left side	131 µm
Door - rear right side	125 µm	Door - front left side	127 µm
Door - front right side	126 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres




Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Seat - front: Seat cover - left side - Soiled - Clean



Damage 1: Seat - front: Seat cover - left side - Soiled - Clean



Damage 2: Wheel / tyres: Tyres - complete set - Differs from the original configuration - Un- / install



Damage 2: Wheel / tyres: Tyres - complete set - Differs from the original configuration - Un- / install



Damage 3: Instrument panel: Indicator light (presence) - Specify findings - Perform diagnosis



Repainting 1: Mudguard - right side



Repainting 1: Mudguard - right side