
MACADAM







BMW 320: L745DD

Vinnumber:	**WBA6N91010FL22686**	Versionname:	**320eA 150kW touring**
First Registrationdate:	**28/04/2021**	Fiscalpower:	
Expertise Mileage:	**148314**	Power Kw:	**120**
Bodytype:		Body colour	**Oxidegrau II metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Hybrid Petrol**	Parking lot	**287**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**No**		

Options

Number of keys total	**2**	Lining leather	
GPS		Rear parking sensors	
Autom climate control		Hook	
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	225 / 50 / 17 / 98 / H / Aluminium	4,2 mm	Bridgestone	Winter
	Right	225 / 50 / 17 / 98 / H / Aluminium	4,8 mm	Bridgestone	Winter
Rear	Left	225 / 50 / 17 / 98 / H / Aluminium	5,5 mm	Bridgestone	Winter
	Right	225 / 50 / 17 / 98 / H / Aluminium	4,8 mm	Bridgestone	Winter

Assistance equipment

Number of charging cables (rapid charge)	**1**

Door FL, Dent(s), Repair and paint (complete)





Bonnet, Stone chip(s), Repair and paint (complete)









Door RR, Dent(s) and scratch(es), Repair and paint (complete)








Door water strip RR, Broken, Replace




Bumper R, Scratch(es), Repair and paint (complete)





Bodywork, Paint measurement, Acceptable



Bodywork, Chemical polution, Polish



