TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48472002
Order No. / Reference: 27211011-1
Inspection date: 27 Oct 2026

Manufacturer: Opel	Model: Astra Sports Tourer 1.5 D Automatik Ultimate
VIN: VXKFCYHZ5R1024852	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Astra Sports Tourer 1.5 D Automatik Ultimate	
Vehicle Identification number	VXKFCYHZ5R1024852
Mileage (Read)	96,836 km
First registration	26 Sept 2024
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Arktisweiß
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	
Last service on / at	09/2026 at 95,028 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB466453
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2525 / ABT 00008		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,940 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 180-degree reversing camera (parking pilot, front and rear parking aid)
- Airbag: Chest-pelvis side airbags, driver and front passenger (side airbag, front passenger can be manually deactivated)
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS) (including brake assist)
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Roof design line, in black
- Diesel particulate filter (DPF) maintenance-free (exhaust aftertreatment via SCR (Selective Catalytic Reduction) catalyst with AdBlue (urea injection). Vehicles with BlueInjection technology require refilling of the AdBlue fluid between regular service intervals. A display in the vehicle informs the driver in good time when refilling is necessary.)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Laminated glass windshields, noise-reducing
- Luggage compartment floor: Flex Floor loading floor, adjustable to two heights
- Automatic speed assistant with stop function
- Cruise control with intelligent speed limiter
- Transmission: 8-speed automatic transmission
- Electric tailgate, sensor-controlled (self-opening and self-closing via foot gesture)
- Back window, heater
- Interior rearview mirror, automatically dimming
- IntelliLux LED Matrix Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking light - High beam: traffic-dependent dimming taking into account preceding and oncoming traffic - Automatic headlight range control - LED daytime running lights - LED taillights - LED turn signals in exterior mirrors - LED fog lights)
- Steering wheel made of vegan synthetic leather, flattened at the bottom (with steering wheel remote control and paddle shifters)
- Center armrest, front and rear (front center armrest with USB port and 2 USB chargers - front and rear cup holders - storage compartments - rear center armrest with pass-through)
- Driver fatigue detection (Based on steering behavior and driving duration, it detects signs of possible driver fatigue and issues a visual and audible warning (3-stage warning).)
- Fog light
- Emergency and breakdown call
- Package: Connected Navigation Package incl. Connect Plus (OTA map updates, TomTom Online Traffic, intelligent voice control with natural language, remote control functions, online POI search)
- Tire pressure monitoring system
- Storage compartments (storage compartment in the center console, in the front doors suitable for 1.5-liter beverage bottles, in the rear doors suitable for 0.5-liter beverage bottles, glove compartment with LED lighting)
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag or seatbelt pretensioner)
- On-board computer
- Roof in carbon black
- Roof rails
- Tachometer
- Electronic brake force distribution (EBD)
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Driver attention warning (incl. driver monitoring camera)
- Driving modes: 3 adjustable
- Forward Collision Warning with Automatic Emergency Braking and Pedestrian Detection (automatic transmission) (The automatic emergency braking system brakes the vehicle or brings it to a standstill - Lane Keeping Assist: warning via indicator light and gentle counter-steering - Traffic Sign Recognition - Driver Alert System - Automatic Speed Assist (activation from 30 km/h to 180 km/h) with stop function; the vehicle is then automatically braked to a standstill and can automatically follow the vehicle in front, even in traffic jams)
- rear window wiper
- Intelli-Drive 1.0 (Forward Collision Warning with Automatic Emergency Braking, Pedestrian Detection, Active Lane Keeping Assist, Traffic Sign Recognition and Driver Alert System, Cross Traffic Alert and Automatic Speed Assist with Stop Function, Blind Spot Warning)
- Cable set for trailer hitch
- Headrests (5) (Height adjustable)
- LED ambient lighting (front doors, adjustable in 8 colors)
- LED interior lighting (including reading lights, front and rear, and trunk lighting)
- Steering wheel heating
- Illuminated makeup mirrors in both sun visors
- Center console with USB port and USB charger (cup holders - storage compartments)
- Multimedia navigation system with Intelli-HUD head-up display and 10" driver information display (10" touchscreen color display, fully glazed; automatic music recognition for audio devices with USB connection; Bluetooth audio streaming; hands-free system; phonebook and call list display; simultaneous pairing of 2 mobile phones; wireless smartphone integration via Apple CarPlay and Android Auto; personalization options; 4x20 watts; favorite station memory (24 per profile); speed-dependent volume control; FM/AM, DAB+, RDS-EON; 2 USB-C ports)
- Electric parking brake

- Astra lettering (Astra lettering on the rear and surround for air intakes in high-gloss black)
- Seats: Easy Fold function (switch for effortless folding down of the rear seat row)
- Seats: Heated seats, multi-stage, driver and front passenger
- 12V power outlet in the center console
- Bumpers with narrow air intake grilles (Opel Vizor with Opel Blitz, both illuminated)
- Electronic immobilizer
- Wireless Charging
- Parkpilot, front and rear parking aid
- Rear seat backrest folds forward in a 40:20:40 split
- Seat belts: Three-point seat belts in all seats (belt force limiter and belt tensioner in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats)
- Lane Keeping Assist
- Start/Stop system (Driving assistant - Reinforced starter - AGM high-performance battery - eco switch to deactivate the start/stop function - Brake energy recuperation)
- Pre-installation for ISOFIX child seat mounting system (incl. top tether attachment points, rear outer)
- Central locking with remote control (and interior switch)

Extra equipment

- Detachable trailer hitch (including trailer stability program TSP)
- Paint finish: Solid
- Security package
- Rubber floor mats
- Air conditioning: Intelli-Air air quality system UEC=
- 18" alloy wheels in 5-spoke TriC CWEA=
- Seats: Ergonomic sports action. F./B. Alc TAY5=WAGH

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - rear left side	Door handle - outside - Scratch(es) - Smart repair
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Boot lid / rear door	Rear spoiler - Scratch(es) - Smart repair
4	Side panel - rear left side	Side panel - Dent / paintcoat damage - Smart repair
5	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
6	Front bumper	Front bumper - Scratch(es) - Paint
7	Rear bumper	Rear bumper - Scratch(es) - Paint
8	Boot lid / rear door	Boot lid (Lack blüht auf) - Paint defect - Repair and paint
9	Roof	Roof - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Side panel - rear right side	Side panel - Scratch(es) - No deduction
5	Roof	Roof rail - left side - dent(s) - No deduction
6	Roof	Roof rail - right side - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Convertible with open roof



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Additional tyres




Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Damage 1: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair



Damage 1: Door - rear left side: Door handle - outside - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work




Damage 3: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Damage 3: Boot lid / rear door: Rear spoiler - Scratch(es) - Smart repair



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair




Damage 4: Side panel - rear left side: Side panel - Dent / paintcoat damage - Smart repair



Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value




Damage 5: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 6: Front bumper: Front bumper - Scratch(es) - Paint



Damage 6: Front bumper: Front bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 7: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Boot lid / rear door: Boot lid (Lack blüht auf) - Paint defect - Repair and paint



Damage 8: Boot lid / rear door: Boot lid (Lack blüht auf) - Paint defect - Repair and paint




Damage 8: Boot lid / rear door: Boot lid (Lack blüht auf) - Paint defect - Repair and paint



Damage 9: Roof: Roof - Scratch(es) - Paint



Damage 9: Roof: Roof - Scratch(es) - Paint



Damage 9: Roof: Roof - Scratch(es) - Paint



Damage 9: Roof: Roof - Scratch(es) - Paint



Damage 9: Roof: Roof - Scratch(es) - Paint




Damage 9: Roof: Roof - Scratch(es) - Paint



Damage 9: Roof: Roof - Scratch(es) - Paint



Wear and tear 5: Roof: Roof rail - left side - dent(s) - No deduction



Wear and tear 5: Roof: Roof rail - left side - dent(s) - No deduction



Wear and tear 6: Roof: Roof rail - right side - dent(s) - No deduction



Wear and tear 6: Roof: Roof rail - right side - dent(s) - No deduction