TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number:	44366956
Order number / reference:	25805062
Inspection date:	12 Mar 2026

Manufacturer: Volkswagen	Model: Tiguan 2.0 TDI SCR DSG Life
VIN: WVGZZZ5NZNW046244	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Tiguan 2.0 TDI SCR DSG Life	
Vehicle Identification number	WVGZZZ5NZNW046244
Mileage (Read)	174,094 km
First registration	29 Jun 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report on hand)	
Power / Engine displacement	110 kw / 1,968 ccm
Fuel type / Cylinder	Diesel / 4
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Deep Black Perleffekt
Doors / Seats	5 / 5
Upholstery type	Alcantara / cloth
Colour of upholstery	Black
Re/Import	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / incomplete	**Next maintenance in**	5,300 km
Key is / should be	2 / 2	**FZG documents**	ZB#1 (S) was available (copy), ZB#2 (B) was not available.
		Letter No.	GJ207241
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0603 / BZG 22640		
Emission standard	EURO6;WLTP;AP;PI/CI; M, N1 I	**Fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99V	Summer tyres on Light alloy	Hankook	7mm / 7mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Hankook	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth for tires on the left is in the first place, for tires on the right is in the second place on the axle in the direction of travel

Equipment

Standard equipment

- Airbag for driver and front passenger including knee airbag on the driver's side (passenger airbag deactivation - knee airbag on the driver's side)
- Electrically adjustable and heated exterior mirrors (driver's side exterior mirror aspherical)
- Brake light, third
- diesel particulate filter
- Parking assistance (warning signals for obstacles in the front and rear areas)
- Automatic headlight control with LED daytime running lights ("Coming home" and "Leaving home" function)
- Electric windows front and rear
- Front windscreen in laminated safety glass, heat and sound insulating
- Rear window heated
- Interior mirror automatically dimming
- License plate lighting in LED technology
- Air conditioning system "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Front headrests (safety-optimized - length and height adjustable)
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters
- Front center armrest
- Fatigue detection
- Emergency call service (no registration required, service activated upon delivery)
- Composition radio (16.5 cm touchscreen, dual tuner with phase diversity for optimal radio reception, Radio Data System (RDS), MP3 playback, USB-C port with Apple compatibility, 4 x 20 watt output, phone interface, DAB+ digital radio reception)
- Wheels: Tires 215/65 R 17, rolling resistance class A
- Drawers under the front seats
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner (3 three-point automatic seat belts at the rear including belt tensioner for the outer rear seats - warning tone and light for unfastened seat belts at the front and rear)
- Seats: Front seats with height adjustment
- Lane keeping assistant “Lane Assist”
- 12-volt power outlet (on the rear center console and in the luggage compartment)
- First aid kit, warning triangle and safety vest
- Green thermal insulation glazing, side and rear
- Airbag: Head airbag system for front and rear passengers including front side airbags
- Adaptive Cruise Control ACC (DSG) (Adaptive Cruise Control ACC "stop & go", with speed limiter - Emergency Brake Assist "Front Assist" (for ACC up to 210 km/h))
- Roof rails black
- tachometer
- Electronic parking brake including auto-hold function
- Electronic stabilization program with counter-steering support (including ABS, ASR, EDS, MSR and trailer stabilization)
- High beam control Light Assist
- Pedestrian detection
- Transmission: 7-speed DSG
- Rear window wiper
- ISOFIX mounting points, also for i-Size child seats (device for attaching 2 child seats to the rear seats)
- Instrument cluster with electronic speedometer (odometer, trip meter, tachometer)
- Headrests (3) rear
- LED reading lights, 2 in the front and 2 in the rear
- LED headlights with LED daytime running lights
- Light in the front footwell
- Manual headlight range adjustment
- Multifunction display "Premium" (with multi-color display)
- Non-smoking version (storage compartment and 12V socket at the front)
- Upholstery: Cloth
- Radio accessories: 8 speakers
- Rain sensor
- Tire pressure monitoring indicator
- Wheels: Light alloy (4) "Tulsa" 7 J x 17 (in Dark Graphite, surface polished - tires 215/65 R 17)
- Leather gearshift knob
- Electromechanical power steering (speed-dependent control)
- Seats: Passenger seat backrest completely foldable
- Seats: Comfort seats in the front
- Seats: Lumbar supports in front
- Seats: Rear bench seat asymmetrically split (longitudinally sliding and folding - with pass-through and center armrest)
- Start-stop system with brake energy recovery
- Power socket: 2 USB-C ports at the front
- Textile floor mats front and rear
- Electronic immobilizer
- Central locking without safe security, with radio remote control, and 2 radio keys

Extra equipment

- "Discover Media" navigation system including "Streaming & Internet"
- Package: Cargo (230V socket in the luggage compartment - luggage compartment lighting - luggage compartment floor height adjustable in 2 stages)
- Package: Cargo Package "Plus" (luggage net - net partition)
- Package: Winter
- Rear view camera
- Seats: ergoActive front seats (ergoActive front seats height-adjustable, seat and backrest tilt adjustable, thigh support longitudinally adjustable - lumbar support in front electrically adjustable and with massage function - seat center panels of the front seats and the outer rear seats in microfleece "ArtVelours" - top comfort seats in front)
- Tailgate with electric opening and closing, adjustable opening angle
- Wheels: Tire Mobility Set
- Windows: Rear side windows and rear window tinted
- Exterior mirrors electrically adjustable, folding, heated, ambient lighting, passenger mirror lowering
- Finish: pearl effect
- Foldable towbar (electric release)
- Package: Business Premium (DSG) (App-Connect incl. App-Connect Wireless for Apple CarPlay and Android Auto - Leather multifunction steering wheel, heated, with shift paddles - Automatically heated front windscreen washer nozzles - Voice control - "Comfort" telephone interface with inductive charging function - Heated front seats)
- Package: Driver assistance package "Plus" (Driving assistant "Travel Assist", lane keeping assistant "Lane Assist" and "Emergency Assist" - parking steering assistant "Park Assist" incl. parking aid - proactive occupant protection system in conjunction with "Front Assist" - lane change assistant "Side Assist" and parking assistant - traffic sign recognition)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) was available, but the vehicle registration certificate Part 2 (title) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and a pit were available for examining the vehicle.
Test drive	A test drive was performed with the described vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Rear of vehicle	Rear of vehicle (Taschenlampe) - Missing - Replace
2	Cab	Insulation lining - Damage caused by marten / rodent - Replace
3	Side panel - rear right side	Sill - Dent / paintcoat damage - Smart repair
4	Door - front right side	Door - Scratch(es) - Smart repair
5	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
6	Braking system	Brake discs - front - Worn - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear commensurate with its age and use.

Order/Scope of order

The order was placed to prepare a sales report for the vehicle described. This includes the following:

- Description of core relevant information about the vehicle
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of previous damage, unrepaired previous damage, repainting
- a brief visual or functional inspection of the equipment details if possible.
  (Functional tests of driver assistance systems are not included in the scope of services!)
- a photo documentation of the vehicle

Basis for the order

This product is based on the Alphabet Fuhrpark GmbH guidelines for vehicle returns and valuations. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on his or her own expertise.

The vehicle inspection takes place in a disassembled state.

Damage or defects that can only be detected during disassembly/diagnosis work or through advanced knowledge remain within the scope of the prognosis risk. An extended risk exists for concealed defects caused by fraudulent deception and not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted according to the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which in their nature and severity slightly exceed normal use but do not constitute unacceptable damage will be documented and identified under signs of use if necessary.

Damage or defects that can no longer be attributed to normal use or wear and tear according to the underlying standard are listed in the product under value-reducing factors.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Damage 1: Rear of vehicle: Rear of vehicle (Taschenlampe) - Missing - Replace



Damage 1: Rear of vehicle: Rear of vehicle (Taschenlampe) - Missing - Replace




Damage 2: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 2: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair



Damage 3: Side panel - rear right side: Sill - Dent / paintcoat damage - Smart repair




Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 5: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 6: Braking system: Brake discs - front - Worn - Replace



Damage 6: Braking system: Brake discs - front - Worn - Replace



Damage 6: Braking system: Brake discs - front - Worn - Replace



Damage 6: Braking system: Brake discs - front - Worn - Replace