TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48556525
Order No. / Reference: 27284444
Inspection date: 6 Nov 2026

Manufacturer: Volkswagen	Model: Transporter T6.1 Lang
VIN: WV1ZZZ7HZMH003313	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 Lang	
Vehicle Identification number	WV1ZZZ7HZMH003313
Mileage (Read)	72,626 km
First registration	16 Nov 2020
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	15,700 km
Last service on / at	09/2026 at 71,662 km		
Key is / should be	4 / 4	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	FU691459
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BXU 54394		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Summer tyres on Light alloy	Hankook	5mm / 5mm
2)	205/65 R16 107T	Summer tyres on Light alloy	Hankook	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 106T	Winter tyres on Steel rim with wheel cover	Bridgestone	5mm / 5mm
2)	215/65 R16 106T	Winter tyres on Steel rim with wheel cover	Bridgestone	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage and stowage boxes
- Airbag for driver and front passenger
- Exterior mirrors, left and right convex
- third brake light
- Electronic Stability Program
- Electric windows, front
- Total weight: Permissible total weight 3000 kg
- Rear wing door closing mechanism with unlocking function from the inside
- Child safety lock, electrically operated
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Soot particle filter for diesel engines
- "Composition Audio" radio with TFT display (monochrome)
- Wheels/Tires: 205/65 R 16 C 107/105 T, optimized for low rolling resistance
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Seat belts: Three-point automatic seat belts
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Storage compartments and boxes: Roof storage space
- Electrically adjustable and heated exterior mirrors
- Hill Start Assist
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Fresh air system with multi-stage fresh air blower
- Transmission: 6-speed transmission
- Heating system with electronic control
- High roof, high rear wing doors without windows
- Headrests (2)
- Headlight range control
- Non-smoking version
- Upholstery: Seat covers in fabric, "Double Grid" design
- Radio: Digital radio reception (DAB+)
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels: Tire Mobility Set
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Start-stop system
- Telephone: Mobile phone interface
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Registration as a truck

Extra equipment

- Floor coverings: 2 rubber floor mats in titanium black
- Floor coverings: Universal floor in the passenger/cargo area (Universal floor in the cargo area with loading edge protection, rear - step lighting in the passenger/cargo area)
- High roof, high rear wing doors with windows, heated (roof storage space - high rear wing doors with window cutouts - high roof made of plastic, in Candy White - mechanical locking/unlocking of the tailgate/ wing door lock with unlocking function from inside - heated rear window - dimmable safety interior mirror - comfort headliner in the driver's cab)
- Light and visibility (interior safety mirror, automatically dimming - daytime running lights with automatic headlight control, "Leaving home" function and manual "Coming home" function - intermittent wiper control with rain sensor for the windshield wipers)
- Package: Comfort Package Plus (2 12V sockets, air conditioning in the driver's cab with electric control, fabric seat covers, "Bricks" design, 1 waste bin for the door pockets in the driver's cab, additional soundproofing measures in the driver's cab, height adjustment for the left single seat in the driver's cab, folding grab handles and storage compartments on the driver's cab seats, sun visor with mirror and airbag label on the passenger sun visor, grab handle for entry on the A-pillar, lumbar support for the left single seat in the instrument panel, dimmable)
- Rigid towbar (including trailer stabilization)
- Seats 1st row: Double passenger seat on the right (with lockable compartment in the seat base)
- Sortimo conversion
- Telephone: Mobile phone interface "Comfort" (with inductive charging function)
- Tire pressure monitoring system for road tires and winter tires
- Wheels/Tires: Tire pressure monitoring system (direct measuring)
- Windows: Rear window (standard glass, heated) with rear window wiper/washer system
- Chassis: Rear suspension reinforced
- Driver assistance systems: Front Assist area monitoring system with City Emergency Braking function
- Fog lights including cornering lights
- Heated seats for the driver's cab, left and right, separately adjustable
- Interior paneling: Side panels in the passenger/cargo area, made of hardboard (half-height in vehicles with window cutouts)
- Multifunction display "Plus" with fatigue detection (Multifunction display "Plus" with black and white display)
- Package: Exterior package (bumpers in body color for standard paint finishes or according to color description for special paint finishes - exterior mirror housings and door handles in body color - radiator grille with two chrome strips)
- ParkPilot in the front and rear areas
- Partition walls: High partition wall with sliding window and 8 lashing rings for securing cargo (partition wall, high, with sliding window - without child safety lock in the passenger compartment - lashing rings for securing cargo, reinforced (ISO 27956))
- Power outlets: 2 12-volt sockets in the dashboard
- Radio navigation system "Discover Media" including "Streaming & Internet" (voice control - 2 USB interfaces (Type C) in the dashboard - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - navigation function/ preparation - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect)
- Total weight: Permissible total weight 3.2 t with reinforced 16" steel wheels (4 steel wheels 6.5 J x 16 - Permissible total weight 3,200 kg - Suspension and damping, for vehicles with 3.2 t permissible total weight - On-board tools and jack, reinforced, for vehicles with 3.2 t GVW)
- Wheels/Tires: On-board tools and jack
- Wheels/Tires: Winter tires (additional) 215/65 R 16 C 106/104 T mounted on 4 steel wheels
- Windows: Laminated glass windshield, heated

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Rear door - left side - Scratch(es) - No deduction
2	Wheel / tyres	Wheelset - complete - Differs from the original configuration - No deduction
3	Screen cleaning	Wiper arm - rear (Kappe Schraube) - Missing - Replace
4	Equipment	Tirefit filler - Expired - Replace
5	Body	Identification plate - Missing - Replace
6	Boot lid / rear door	Rear door - left side (Schweng Mechanismus) - Noise - Perform diagnosis
7	Door - front left side	Door - Malposition - Set / adjust
8	Mudguard - left side	Mudguard - left side - Scratch(es) - Smart repair
9	Door - front left side	Door - Scratch(es) - Smart repair
10	Front bumper	Front bumper - Scratch(es) - Smart repair
11	Engine	Engine - Leaking - Perform diagnosis
12	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
13	Door - front right side	Door - Scratch(es) - Smart repair
14	Fog lamp	Fog lamp - front left side - Broken / torn - Replace
15	Fog lamp	Fog lamp - front right side - Broken / torn - Replace
16	Boot lid / rear door	Rear door - left side (Rost Ansatz-unterhalb) - Dent / paintcoat damage - Repair and paint
17	Sliding door, right	Sliding door (Rost Ansatz- unterhalb) - Scratch(es) - Paint
18	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
19	Rear bumper	Rear bumper - Broken / torn - repair according to calculation

Wear and tear

No.	Component group	Description
1	Body	Partition wall - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.

Die Zulässigkeit des montierten Radsatzes wurde nicht erbracht.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Boot lid / rear door: Rear door - left side - Scratch(es) - No deduction



Damage 3: Screen cleaning: Wiper arm - rear (Kappe Schraube) - Missing - Replace



Damage 3: Screen cleaning: Wiper arm - rear (Kappe Schraube) - Missing - Replace



Damage 4: Equipment: Tirefit filler - Expired - Replace



Damage 6: Boot lid / rear door: Rear door - left side (Schweng Mechanismus) - Noise - Perform diagnosis



Damage 6: Boot lid / rear door: Rear door - left side (Schweng Mechanismus) - Noise - Perform diagnosis



Damage 7: Door - front left side: Door - Malposition - Set / adjust



Damage 7: Door - front left side: Door - Malposition - Set / adjust



Damage 7: Door - front left side: Door - Malposition - Set / adjust



Damage 8: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 8: Mudguard - left side: Mudguard - left side - Scratch(es) - Smart repair



Damage 9: Door - front left side: Door - Scratch(es) - Smart repair



Damage 9: Door - front left side: Door - Scratch(es) - Smart repair



Damage 9: Door - front left side: Door - Scratch(es) - Smart repair



Damage 10: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 10: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 11: Engine: Engine - Leaking - Perform diagnosis




Damage 11: Engine: Engine - Leaking - Perform diagnosis



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 12: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 13: Door - front right side: Door - Scratch(es) - Smart repair



Damage 13: Door - front right side: Door - Scratch(es) - Smart repair



Damage 13: Door - front right side: Door - Scratch(es) - Smart repair



Damage 14: Fog lamp: Fog lamp - front left side - Broken / torn - Replace



Damage 14: Fog lamp: Fog lamp - front left side - Broken / torn - Replace



Damage 15: Fog lamp: Fog lamp - front right side - Broken / torn - Replace



Damage 15: Fog lamp: Fog lamp - front right side - Broken / torn - Replace



Damage 15: Fog lamp: Fog lamp - front right side - Broken / torn - Replace



Damage 16: Boot lid / rear door: Rear door - left side (Rost Ansatz-unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 16: Boot lid / rear door: Rear door - left side (Rost Ansatz- unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 16: Boot lid / rear door: Rear door - left side (Rost Ansatz- unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 16: Boot lid / rear door: Rear door - left side (Rost Ansatz- unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 16: Boot lid / rear door: Rear door - left side (Rost Ansatz- unterhalb) - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door (Rost Ansatz- unterhalb) - Scratch(es) - Paint




Damage 17: Sliding door, right: Sliding door (Rost Ansatz- unterhalb) - Scratch(es) - Paint



Damage 17: Sliding door, right: Sliding door (Rost Ansatz- unterhalb) - Scratch(es) - Paint



Damage 17: Sliding door, right: Sliding door (Rost Ansatz- unterhalb) - Scratch(es) - Paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 18: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Damage 19: Rear bumper: Rear bumper - Broken / torn - repair according to calculation



Wear and tear 1: Body: Partition wall - Scratch(es) - No deduction



Wear and tear 2: Vehicle glazing: Windscreen - Stone chips - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Wear and tear 3: Bonnet: Bonnet - Stone chips - No deduction