TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48508888
Order No. / Reference: 27198956
Inspection date: 30 Oct 2026

Manufacturer: Ford	Model: Transit Connect 200 L1 S&S Trend
VIN: WF0RXXWPGRMD26666	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Connect 200 L1 S&S Trend	
Vehicle Identification number	WF0RXXWPGRMD26666
Mileage (Read)	65,165 km
First registration	14 Feb 2022
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	999 ccm / 3
Power	74 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	42 %
Last service on / at	09/2025 at 51,119 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GH393509
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BHA 00518		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Goodyear	4mm / 4mm
2)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/60 R16 92H	Summer tyres on Steel	Michelin	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS with EBD
- Exterior mirrors, electrically adjustable and heated
- Battery, reinforced
- Rubberized flooring, front
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows
- FordPass Connect
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Front interior lighting with delay function
- Paint finish: Solid
- Cargo area floor protection, plastic, molded
- Steering column, adjustable in height and reach
- Center console, front
- Emergency brake light
- Radio: Ford Audio System 2
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering
- Front seat belts are height-adjustable
- Seats: Seat package 4
- Dust and pollen filter
- Power outlet: 12-volt connection on the front center console
- Front bumper and rear bumper end caps painted in body color
- Partition to the cargo area without window
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Driver's side airbag
- Exterior mirrors, narrow mirror format
- Hill start assist
- On-board computer including outside temperature display
- Tachometer
- Electronic Safety and Stability Program (ESP)
- Ford Easy Fuel
- Heated windshield
- Transmission: 6-speed transmission
- Glove compartment with lid
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Alternator/Generator
- Fog light
- Gasoline particulate filter (GPF)
- Wheels: Tire repair kit
- Sliding door at rear, right
- Side protection strips, plastic
- Safety brake assist
- Automatic door locking mechanism (45 sec.)
- Start-stop system
- Concealed storage compartment on dashboard
- Power outlet: 12-volt connection in storage compartment on dashboard (driver's side)
- Daytime running light
- Child safety lock on sliding doors
- Electronic immobilizer (EPATS)
- Central locking with remote control

Extra equipment

- Rear parking pilot system
- Spare wheel: Steel wheel
- Seats: Seat package 18 (fabric "Capitol/City" in Ebony (black) - Double passenger seat (with storage compartment under smaller seat section), variably foldable and collapsible - Driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - Headrests, height adjustable - Lumbar support, manual (driver's seat) - Warning system for unfastened seat belt for driver)
- Partition wall to the cargo area with pass-through opening and window
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, TMCpro live traffic, detailed 3D visualization, Michelin travel guide for Europe)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Seat - front	Lever seat adjustment - Missing - Replace
2	Rear bumper	Bumper with Parktronic - Scratch(es) - Replace
3	Seat - front	Seat cover - left side - Damaged - Replace
4	Sill - left side	Sill - Scratch(es) - Smart repair
5	Rear bumper	Rear bumper - Scratched - Loss in value
6	Equipment	Vehicle key - Damaged - Replace
7	Interior	Cargo area floor - Damaged - Replace
8	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
9	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Repair and paint
10	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
11	Front bumper	Front bumper - Scratched - Replace
12	Interior	Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Interior	Interior - Soiled - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der Laderaum weißt in Anbetracht der Laufleistung starke Abnutzungsspuren auf.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Damage 1: Seat - front: Lever seat adjustment - Missing - Replace



Damage 2: Rear bumper: Bumper with Parktronic - Scratch(es) - Replace



Damage 2: Rear bumper: Bumper with Parktronic - Scratch(es) - Replace



Damage 3: Seat - front: Seat cover - left side - Damaged - Replace



Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 4: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 5: Rear bumper: Rear bumper - Scratched - Loss in value



Damage 6: Equipment: Vehicle key - Damaged - Replace




Damage 6: Equipment: Vehicle key - Damaged - Replace



Damage 7: Interior: Cargo area floor - Damaged - Replace



Damage 8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 8: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint




Damage 9: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 11: Front bumper: Front bumper - Scratched - Replace



Damage 11: Front bumper: Front bumper - Scratched - Replace



Damage 11: Front bumper: Front bumper - Scratched - Replace



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value



Damage 12: Interior: Cargo space partition (+ verformt / Ladungssicherung!) - Scratched - Loss in value