TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48216215
Order No. / Reference: 27114819
Inspection date: 24 Sept 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG RS
VIN: TMBJK8NX6RY041430	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG RS	
Vehicle Identification number	TMBJK8NX6RY041430
Mileage (Read)	125,170 km
First registration	21 Sept 2023
Number of holders	1
Next periodical technical inspection (read from ZBI)	09/2026
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Candy White (F9E)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	24,700 km
Last service on / at	08/2026 at 119,784 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT128698
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AVI 00128		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,005 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 91Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	225/45 R18 91Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 95H	Winter tyres on Light alloy	Pirelli	6mm / 6mm
2)	205/55 R17 95H	Winter tyres on Light alloy	Pirelli	8mm / 8mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- Storage compartment in the luggage compartment
- Airbag, driver and passenger
- Airbag, head airbags
- Airbag: Center airbag front
- Anti-lock braking system (ABS)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors painted black, door handles in body color
- Heated windshield washer nozzles including 5l washer fluid reservoir
- roof grab handles four
- AERO roof rails in black
- Diesel particulate filter
- Tachometer
- Ice scraper in the fuel filler flap
- Electronic transverse differential lock (XDS+)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front and rear footwell lighting
- Removable luggage roller blind
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior: Design Selection RS
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone)
- Paint finish: Special paint finish, solid color
- LED matrix headlights and dynamic high beam assist (AFS)
- Steering wheel: Height and reach adjustable leather steering wheel with multifunction buttons including paddle shifters
- Multi-collision brake
- Front and rear parking sensors
- Progressive steering
- Radio accessories: 2 USB ports at the front
- Radio accessories: 8 speakers
- Radio accessories: Bluetooth hands-free system
- Radio accessories: Wireless & Wired SmartLink
- Rain sensor and driving light assistant (Easy Light Assist)
- Tire mobility kit
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Rear seat backrest split 60:40, foldable
- Seats: Pockets on the backs of the front seats including smartphone pockets
- SKODA Care Connect
- Sound generator in the interior
- Lane keeping assistant (Lane Assist)
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Glazing: Acoustic glazing in the front side windows and Sunset
- Storage compartments
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Ambient lighting
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist
- Glasses compartment in the headliner
- black headliner
- AERO roof rails in gloss black
- Digital Cockpit Plus
- Third brake light
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC)
- Chassis: Sport chassis
- Dynamic High Beam Assist (Dynamic Light Assist)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Cruise control system (cruise control) including speed limiter
- Heated rear window
- Rear window wiper including windshield washer system
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Black radiator grille frame
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Reading lights two at the front
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Fatigue detection
- Pedals in stainless steel look
- Radio: Infotainment system
- Radio accessories: 2 x USB charging ports in the rear and USB charging port in the rearview mirror
- Radio accessories: Digital radio reception DAB+
- Umbrella and broom compartments in the front doors
- Tire pressure monitoring
- Wheels: 18" Comet alloy wheels, black
- Seat belts
- Seats: Heated front seats
- Seats: Sports seats with integrated headrests in the front and height-adjustable headrests in the rear.
- Seats: Front seats are height-adjustable
- Sun visors with illuminated make-up mirror on driver and passenger side
- 12V socket in the trunk
- Textile floor mats
- Front door sill trims

- Central locking including remote control integrated into the key and EASY Start
- Lashing eyes in the trunk
- Immobiliser

Extra equipment

- Swiveling trailer hitch including trailer stabilization and adapter
- Package: Parking & Lights (for RS) (cornering lights in the fog lights - reversing camera)
- Package: Transport (Combi) (Double-sided boot mat - Media holder - Tablet holder - Waste bin - 3rd vehicle key - Net program in the luggage compartment and cargo elements - Luggage net partition - Variable loading floor)
- Package: Infotainment package Business Columbus (Style, RS, Scout) (Columbus navigation system - Infotainment Online (3-year term) - 3 USB charging ports - Head-Up Display - Adaptive Cruise Control (ACC) - Traveller Assist system)
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)
- Seats: Electrically adjustable Ergo-Sportsi. PWF, PW5

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed. This is due to the following reason.: Ohne beanstandung

Value reducing factors

No.	Component group	Description
1	Trim / covers	Floor mats - Broken / torn - Replace
2	Door - rear right side	Door handle - outside - Scratched - Smart repair
3	Trim / covers	D-pillar - trim - interior, right side - Soiled - Replace
4	Roof	Roof rail - right side - Corrosion - Smart repair
5	Wheel / tyres	Alloy rim - rear left side - Scratched - Loss in value
6	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value
7	Trim / covers	Carpet - front left side - Broken / torn - Loss in value
8	Rear bumper	Rear bumper - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Headlight	Headlight - left side - Stone chips - No deduction
3	Bonnet	Bonnet - Stone chips - No deduction
4	Headlight	Headlight - right side - Stone chips - No deduction
5	Front bumper	Front bumper - Stone chips - No deduction
6	Door - front right side	Door edge - Scratch(es) - No deduction
7	Trim / covers	Boot lining - Scratched - No deduction
8	Trim / covers	Boot lid - interior trim - Scratched - No deduction
9	Front bumper	Spoiler - Scratched - No deduction
10	2nd wheel set	1 alloy rim (nicht Bestandteil der Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der beiliegende Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Trim / covers: Floor mats - Broken / torn - Replace




Damage 1: Trim / covers: Floor mats - Broken / torn - Replace




Damage 2: Door - rear right side: Door handle - outside - Scratched - Smart repair



Damage 2: Door - rear right side: Door handle - outside - Scratched - Smart repair



Damage 3: Trim / covers: D-pillar - trim - interior, right side - Soiled - Replace



Damage 3: Trim / covers: D-pillar - trim - interior, right side - Soiled - Replace



Damage 4: Roof: Roof rail - right side - Corrosion - Smart repair



Damage 4: Roof: Roof rail - right side - Corrosion - Smart repair



Damage 5: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 5: Wheel / tyres: Alloy rim - rear left side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 7: Trim / covers: Carpet - front left side - Broken / torn - Loss in value



Damage 7: Trim / covers: Carpet - front left side - Broken / torn - Loss in value



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint




Damage 8: Rear bumper: Rear bumper - Scratched - Repair and paint



Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction



Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction




Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction



Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction




Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction



Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction



Wear and tear 7: Trim / covers: Boot lining - Scratched - No deduction



Wear and tear 8: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 8: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 8: Trim / covers: Boot lid - interior trim - Scratched - No deduction



Wear and tear 10: 2nd wheel set: 1 alloy rim (nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 10: 2nd wheel set: 1 alloy rim (nicht Bestandteil der Ausstattung) - Scratched - No deduction