TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48250508
Order No. / Reference: 27074897
Inspection date: 21 Oct 2026

Manufacturer: Volkswagen	Model: Touran 2.0 TDI SCR DSG Highline
VIN: WVGZZZ1T1RW024260	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Touran 2.0 TDI SCR DSG Highline	
Vehicle Identification number	WVGZZZ1T1RW024260
Mileage (Read)	106,350 km
First registration	12 Aug 2024
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Delfingrau Metallic (C7Q)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,000 km
Last service on / at	09/2026 at 105,404 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD446720
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BWR 00525		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,230 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95W	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	225/45 R18 95W	Summer tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Continental	3mm / 3mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Continental	7mm / 7mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment with lid on the instrument panel
- Distraction and fatigue detection
- Airbag: Side airbags for the outer seats of the 2nd row.
- Adaptive Cruise Control (ACC) "stop & go", with speed limiter
- third brake light
- Headliner in Storm Grey
- Diesel particulate filter
- Tachometer
- Electronic parking brake including auto-hold function
- Automatic headlight control with daytime running lights
- Windscreen made of laminated safety glass, heat and sound insulating
- Luggage management package (with luggage net that can be fixed to rails)
- Height-adjustable luggage compartment floor
- Glove compartment with cooling option
- Rear window wiper with intermittent function
- Interior mirror automatically dimming
- ISOFIX mounting points on rear seats
- Front headrests
- LED light in the front footwell
- Illuminated makeup mirrors in the sun visors
- front center armrest
- Fog lights and cornering lights
- Emergency braking assistant "Front Assist" (for automatic distance control ACC up to 210 km/h)
- Proactive occupant protection system in conjunction with "Front Assist" and "Side Assist"
- Wheels: Tire Mobility Set omitted
- Gearshift knob in leather
- Headlight cleaning system
- Drawers under the front seats
- Seat belts: 3 three-point automatic seat belts in the rear
- Seats: Front passenger seat backrest folds down completely
- Lane keeping assistant “Lane Assist”
- Start-stop system
- Bumpers in body color
- Textile floor mats
- First aid kit, warning triangle and high-visibility vest
- Prepared for later activation: Discover Media navigation function incl. streaming & internet
- Electronic immobilizer
- Central locking without safe locking, with remote control and 2 remote folding keys
- Storage compartments in the overhead console
- Airbag for driver and front passenger
- Ambient lighting
- Electrically folding exterior mirrors
- Exterior mirror housings and door handles in body color
- Chrome trim on the side windows
- Decorative inlays "Piano Black"
- Digital Cockpit Pro, multicolor (various info profiles selectable)
- Electronic Stability Program (ESP) with counter-steering support
- Pedestrian and cyclist detection as well as active front hood
- luggage compartment cover
- Additional luggage compartment lighting
- Transmission: 7-speed DSG
- Rear window heated
- Interior lights with delayed shut-off and dimming function, 2 LED reading lights front and rear
- Headrests (3) in the 2nd row of seats
- Black radiator grille with chrome strip on the lower slat
- Dynamic headlight range control, with dynamic cornering lights
- Multifunctional camera
- Non-smoking version
- Emergency call service
- Upholstery in microfleece “ArtVelours”
- Radio accessories: Digital radio reception DAB+
- Rain sensor
- Wheels: Tire pressure monitoring system
- Automatically heated front windshield washer nozzles
- Keyless start system without safe locking
- electromechanical power steering
- Seats: 3 individual seats in the 2nd row
- Seats: Folding tables on the backs of the front seats
- Seats: Lumbar support in the front
- Lane change assistant "Side Assist" and parking assistant
- 12V power outlet on the rear of the center console
- Telephone interface
- USB-C interface
- Prepared for "We Connect" and "We Connect Plus"
- Washer fluid level warning light
- Warning tone and light for unfastened front seat belts
- Green thermal insulation glazing

Extra equipment

- Towbar, foldable with electric release
- Chassis: Adaptive chassis control DCC including driving profile selection
- Reversible luggage compartment mat, foldable and removable
- Paint finish: Metallic
- Navigation system "Discover Pro" incl. "Streaming & Internet" (23.4 cm (9.2 inch) touchscreen with voice control and traffic sign recognition - navigation system - USB-C interfaces and a mobile phone interface via Bluetooth - DAB+C - App-Connect Wireless for Apple CarPlay and Android Auto - voice control)
- Package: "IQ.DRIVE" (DSG) assistance package (Dynamic Light Assist - Travel Assist, Lane Assist and Emergency Assist - LED headlights with LED daytime running lights and cornering lights - Dynamic headlight range control with dynamic cornering lights)
- Package: Exterior Design Package "Black Style" for Highline (Exterior mirror housings in black and door handles in body color - roof rails in black - radiator grille in black with chrome strip on lower louvre - bumpers in body color - trim strips in black on the side windows)
- Package: Top package (Highline) (Panoramic tilt/slide sunroof with panoramic roof at the rear - LED taillights - Darkened rear side windows and rear window)
- Radio accessories: "DYNAUDIO Contour Surround" sound system (8+1 speakers - total output 330 watts - digital 16-channel amplifier)
- Wheels: Tire pressure monitoring system
- Rear View reversing camera (displays the rear of the vehicle in real time on the radio/navigation system display)
- Auxiliary heating and ventilation (auxiliary heating and ventilation with radio remote control and timer)
- "Comfort" telephone interface with inductive charging function
- Front USB-C ports (2) (2 USB-C charging ports on the rear center console; charging power up to 45 W)
- Preparation for online services for FleetMan YON
- Anti-theft alarm system (with interior monitoring, backup horn and tow-away protection)
- Heated windscreen (TDI) (Laminated safety glass windscreen, noise-reducing and heated; 180 A three-phase alternator)
- Steering wheel: Multifunction leather steering wheel, heated, with paddle shifters
- Mesh partition
- Package: "Easy Open & Close" package with safe locking (tailgate with sensor-controlled opening and closing, with remote unlocking - keyless locking and starting system "Keyless Access" with safe locking)
- Package: Business Premium incl. Navigation (DSG) (Air Care Climatronic air conditioning - Lumbar support front, electrically adjustable on driver's side, massage function driver's side - Multifunction leather steering wheel with shift paddles - Cargo net partition - Automatically heated windshield washer nozzles front - Headlight cleaning system - Drawer under the right front seat - Microfleece seat center panels "ArtVelours" - Top comfort seats front - Heated front seats - Height-adjustable front seats, ergoActive seat on the driver's side - Washer fluid level warning light)
- Park Assist (automatically steers the vehicle into parallel and perpendicular parking spaces and also parks out of parallel parking spaces)
- Wheels: Light alloy (4) "Marseille" 7 J x 18 Volkswagen R (4 light alloy wheels 7Jx18, in black, surface polished - AirStop tires 225/45 R 18 - wheel locks with extended theft protection)
- Seats: Front seats and outer rear seats of the 2nd row are heated.
- 230V power outlet in the luggage compartment on the left (additional luggage compartment lighting, removable and usable as a flashlight)
- Traffic sign recognition in conjunction with the "IQ.DRIVE" assistance package including IQ.LIGHT

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid glazed - dent(s) - Smart repair
2	Door - front left side	Door - dent(s) - Smart repair
3	Vehicle glazing	Triangular window - right side (Dichtung) - Broken / torn - Replace
4	Wheel / tyres	Alloy rim - front left side - Scratched - Loss in value
5	Mudguard - right side	Mudguard - right side - dent(s) - Repair and paint
6	Side panel - rear right side	Side panel - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Boot lid / rear door, Side panel - rear right side, Door - rear right side, Professionally carried out

Paint coat thickness measurement

Boot lid / rear door	519 µm	Side panel - rear right side	191 µm
Door - rear right side	189 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents



Figure 19: Additional tyres



Figure 20: Navigation



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Damage 1: Boot lid / rear door: Boot lid glazed - dent(s) - Smart repair




Damage 1: Boot lid / rear door: Boot lid glazed - dent(s) - Smart repair




Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 2: Door - front left side: Door - dent(s) - Smart repair



Damage 3: Vehicle glazing: Triangular window - right side (Dichtung) - Broken / torn - Replace



Damage 3: Vehicle glazing: Triangular window - right side (Dichtung) - Broken / torn - Replace



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front left side - Scratched - Loss in value



Damage 5: Mudguard - right side: Mudguard - right side - dent(s) - Repair and paint




Damage 5: Mudguard - right side: Mudguard - right side - dent(s) - Repair and paint




Damage 6: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Damage 6: Side panel - rear right side: Side panel - dent(s) - Repair and paint



Boot lid / rear door: 519 µm



Side panel - rear right side: 191 µm



Door - rear right side: 189 µm