TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48500400
Order No. / Reference: 27162038
Inspection date: 20 Oct 2026

Manufacturer: Ford	Model: Kuga 1.5 EcoBlue Aut. TITANIUM X
VIN: WF0FXXWPMFNM05304	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 1.5 EcoBlue Aut. TITANIUM X	
Vehicle Identification number	WF0FXXWPMFNM05304
Mileage (Read)	170,114 km
First registration	8 Feb 2023
Number of holders	2
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	88 kW
fine dust sticker	grün
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Magnetic-Grau (Metallic)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	12 %
Last service on / at	03/2026 at 143,678 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT624742
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	Conditional: Light/moisture/dirt	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BTJ 00306		
Emission standard	EURO6	**fine dust sticker**	green
Permitted total weight	2,110 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/60 R18 100H	Summer tyres on Light alloy	Firestone	4mm / 4mm
2)	225/60 R18 100H	Summer tyres on Light alloy	Firestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R17 106H	Winter tyres on Light alloy	Fulda	4mm / 4mm
2)	225/55 R17 106H	Winter tyres on Light alloy	Fulda	6mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Ambient lighting
- Electrically adjustable, heated and folding exterior mirrors
- Tires: 7 J x 17 alloy wheels (4) in 5x2-spoke design
- third brake light
- Roof rails, silver-colored
- Diesel particulate filter
- Dual exhaust system
- Electronic Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric parking brake with auto hold function
- Ford EcoCoach
- FordPass Connect
- Luggage compartment lighting
- Transmission: 8-speed automatic
- Electric tailgate, sensor-controlled (opens and closes via foot movement)
- Interior mirror, automatically dimming
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Paint finish: Solid
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3
- Front and rear parking pilot system
- Post-Collision Assist
- Pre-Collision Assist
- Tire Pressure Monitoring System (TPMS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Power steering
- Seats: Passenger seat, 8-way manually adjustable
- Seats: Map pockets on the driver's and front passenger's seat backrests
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Static LED headlights
- Carpet floor mats front and rear, velour
- Immobiliser
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: Tire repair kit
- Fabric headliner
- Roof spoiler
- 12.3-inch digital instrument panel
- Tachometer
- Driving mode switch selective
- Electric windows front and rear
- Ford Easy Fuel
- Ford Power Start Function & Ford Key Free System
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- Heated rear window
- rear window wiper
- Intelligent Protection System (IPS)
- Air conditioning with automatic temperature control
- Front and rear headrests (5) height adjustable
- LED taillights
- Steering column, adjustable in height and reach
- Rear center armrest with cup holder
- MyKey key system
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Upholstery: Premium Sensico upholstery in leather look/fabric
- Radio accessories: B&O Sound System
- Rear view camera
- Headlights with delayed shut-off
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Driver's seat electrically adjustable, 10-way including electrically adjustable lumbar support
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Start-stop system
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Inductive charging station for mobile devices (The inductive charging station allows you to charge your compatible smartphone while driving without the hassle of connecting it to a cable. The charging station is located in the vehicle's center console and is only activated when it comes into contact with a compatible device. If you place a wallet or other items on the charging station, it remains inactive.)
- Package: Winter (heated windscreen - heated leather steering wheel)
- Paint finish: Agate Black Metallic
- Tires: 4 all-season tires 225/65 R 17 102V
- Winter complete wheels
- Package: Driver Assistance Package (Automatic Transmission) (Intelligent Adaptive Cruise Control with Traffic Sign Recognition System - Traffic Jam Assist with Stop&Go Function and Lane Keeping Assist - Wrong-Way Driver Warning System - Evasive Steering Assist - Driver Drowsiness Detection - Pre-Collision Assist including Forward Collision Warning System with Cross Traffic Alert - Blind Spot Assist with Emergency Braking Function and Trailer Detection - Active Park Assist with Parking Assist and Semi-Autonomous Vehicle Steering - Front Camera with Split View - Door Edge Protectors - Intelligent Speed Limiter with Speed Limit Display)
- Tires: 7.5 J x 18 light alloy wheels (4) in 10-spoke Y-design in Magnetic, diamond-turned finish (with tires 225/60 R 18)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Engine	Engine cover - top / cover - Missing - Replace
2	Engine	Engine (Marderschreck) - Differs from the original configuration - No deduction
3	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
4	Equipment	Tirefit filler - Expired - Replace
5	Engine	Engine (Mehrkosten können entstehen) - Leaking - Perform diagnosis
6	Cab	Insulation lining - Damage caused by marten / rodent - Replace
7	Side panel - rear left side	Sill - Dent / paintcoat damage - Smart repair
8	Side panel - rear right side	Sill - dent(s) - Smart repair
9	Door - front right side	Door - dent(s) - Smooth repair work

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 25 Feb 2026	2.898,90 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.





Figure 24: Misc.



Figure 25: Misc.



Damage 1: Engine: Engine cover - top / cover - Missing - Replace



Damage 2: Engine: Engine (Marderschreck) - Differs from the original configuration - No deduction



Damage 3: Equipment: Vehicle key with remote control (Batterie) - Empty - Replace



Damage 4: Equipment: Tirefit filler - Expired - Replace




Damage 5: Engine: Engine (Mehrkosten können entstehen) - Leaking - Perform diagnosis




Damage 6: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 6: Cab: Insulation lining - Damage caused by marten / rodent - Replace



Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair




Damage 7: Side panel - rear left side: Sill - Dent / paintcoat damage - Smart repair



Damage 8: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 8: Side panel - rear right side: Sill - dent(s) - Smart repair



Damage 9: Door - front right side: Door - dent(s) - Smooth repair work



Damage 9: Door - front right side: Door - dent(s) - Smooth repair work



Damage 9: Door - front right side: Door - dent(s) - Smooth repair work



Damage 9: Door - front right side: Door - dent(s) - Smooth repair work



Previous damage 1: Side - left




Previous damage 1: Side - left



Previous damage 1: Side - left




Previous damage 1: Side - left




Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left



Previous damage 1: Side - left