APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	NISSAN
Model / version:	JUKE
Vin:	SJNF16FA0U2143258
Plate:	2HXP324
Mileage:	29855
First registration:	16/12/2025
Color:	Carbon Black

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES




















































VIN INFORMATION

EQUIPMENT

Board computer:	?	Central locking:	?
Compressor:	✓	Cruise control:	?
Gps:	?	Power steering:	?
Rear parking sensor:	?	Repair kit:	✓
Front seats heated:	?	Steering wheel:	?
Electric windows:	?	Climate control type:	
Headlighting type:		Tow bar type:	
Charging cables:	0	Fast charging cables:	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	4 mm			Summer		?
Front right	4 mm			Summer		?
Rear left	4 mm			Summer		?
Rear right	4 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
2	Roof	Dent(s)
3	Door RR	Dent(s)
4	Door RR	Scratch(es)
5	Door FR	Scratch(es)

Total: 4

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
1	Bodywork	Dent(s) and scratch(es)	✓	✗	✗

Total: 1

DAMAGES DETAILS

2 - Roof - Dent(s)







3 - Door RR - Dent(s)






4 - Door RR - Scratch(es)






5 - Door FR - Scratch(es)




1 - Bodywork - Dent(s) and scratch(es) - Renta®









SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

23/09/2026 14:21

