ARVAL
BNP PARIBAS GROUP

2CES721

INSPECTION REPORT

End of contract

GENERAL INFO

File	324823
License plate	2CES721
Vehicle identification number	TMBJJ9NS9N8055670
Dossier	2021 358 041
Make	Skoda Kod.2.0CRTDI 110kW L K D
Mileage	173050
First registration	27/06/2022
client availability date	09/10/2026
inspectionDate	21/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	


10:05
14.5°C
430 km
P
0


B
2-CES-721

DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
282	Bumper Rear / Trim Center / Replace	N
283	Bumper Rear / Trim Right / Replace	N
18	Bumper Front / Spoiler / Replace	N
32	Front Bonnet // Painting	N
84	Door Front Left // Repair & Painting	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
116	Wing Rear Left // Polish	Y
154	Rear Bonnet // Repair & Painting	N
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	Y
210	Door Front Right // Smart Repair Small	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	N
233	Wing Front right // Painting	Y
336	Tyre Rear Right // Replace	N
554	Central Console // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures










Tyre Rear Right // Replace-tear




Door Front Right // Smart Repair Small-scratch










Door Front Right // Painting-scratch




Door Rear Right // Painting-scratch



Wing Rear Left // Polish-scratch





Door Rear Left // Painting-scratch






Door Front Left / Trim / Replace-scratch










Front Bonnet // Painting-scratch




Wing Front right // Painting-scratch

Side View Mirror Right // Painting-scratch

Central Console // Replace Completely-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Bumper Front / Spoiler / Replace-scratch





Rocker Panel Left // Smart Repair Medium-dent








Door Front Left // Repair & Painting-dent



Roof // Smart Repair Medium-dent







Wing Rear Right // Smart Repair Small-dent









Rear Bonnet // Repair & Painting-scratch + dent




Bumper Rear / Trim Right / Replace-scratch + dent




Bumper Rear / Spoiler / Replace-scratch + dent




Bumper Rear / Trim Center / Replace-scratch + dent







Bumper Rear // Repair & Painting-scratch + dent