TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48505759
Order No. / Reference: 27135676
Inspection date: 3 Nov 2026

Manufacturer: Opel	Model: Corsa-e Edition
VIN: VXKUHZKXZM4301522	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Corsa-e Edition	
Vehicle Identification number	VXKUHZKXZM4301522
Mileage (Read)	50,120 km
First registration	26 Oct 2021
Number of holders	1
Fuel type	Electric
Power	57 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Jade Weiß Uni
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Grey-Black

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	13,800 km
Last service on / at	07/2025 at 39,890 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC786089
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ABX 00010		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	1,920 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91H	All-season tyres on Steel rim with wheel cover	Goodyear	6mm / 6mm
2)	195/55 R16 91H	All-season tyres on Steel rim with wheel cover	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (storage compartment in the center console, front and rear - cup holder in the center console - glove compartment - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Hill Start Assist
- On-board computer
- Braking system: Regenerative
- Electronic brake force distribution (EBD)
- Driver information display 7", color (fully digital)
- Front collision warning with automatic emergency braking and pedestrian detection (Active between 5 and 85 km/h. Monitors the distance to the vehicle ahead; if the vehicle approaches a vehicle or pedestrian too quickly, the driver is alerted by a warning tone and a display in the driver information screen. In case of a collision risk, the braking system is prepared and, if necessary, emergency braking is initiated to minimize the consequences of a potential collision.)
- Headrests (5) (Height adjustable)
- Charging cable: Mode 2 charging cable (Type 2, up to 1.8 kW - for household sockets - 6 meters length)
- Steering column, height and reach adjustable
- Lithium-ion battery (50 kWh storage capacity)
- Driver fatigue detection (Based on steering behavior and driving duration, it detects signs of possible driver fatigue and issues a visual and audible warning (3-stage warning).)
- Electric parking brake
- Pollen filter
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, smartphone integration via Apple CarPlay, Android Auto, voice control (e.g., navigation (Google Maps, Apple Maps), music, phone, reading and dictating text messages), 1 USB port in the center console, front, DAB+ digital radio reception, steering wheel controls, 6 speakers)
- Seats: Comfort seats (comfort driver's seat, 6-way manually adjustable (length, height, backrest angle) - comfort passenger seat, 4-way manually adjustable (length, backrest angle))
- Start/Stop system (reinforced starter motor - high-performance battery - switch to deactivate the start/stop function)
- 12V power outlet in the center console, front
- Daytime running light
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Pre-wiring for child seat mounting system "ISOFIX" (rear outer)
- Heat-insulating glazing, tinted
- Central locking with remote control
- Adaptive brake light
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Airbag: Front and rear head airbags
- Airbag: Side airbag for driver and front passenger side (side airbag, front passenger, deactivatable)
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable - exterior mirror housing in black)
- third brake light
- Headliner, Grey
- Electronic Stability Program Plus (ESP Plus)
- Electric front windows (one-touch function - anti-pinch protection)
- Pedestrian protection
- Intelligent speed control and limiter
- Transmission: Automatic electric drive with fixed gear ratio
- Back window, heater
- Rear window wiper (with intermittent function)
- Child safety lock in the rear doors, manual
- Automatic climate control (recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - rear footwell heating)
- Steering wheel: Comfort steering wheel (flattened at the bottom)
- Headlight range adjustment, manual
- Make-up mirrors (driver and passenger side)
- Onboard charger (vehicle-integrated charging unit, single-phase (7.4 kW))
- Opel Connect with telematics services (emergency call/breakdown call - vehicle status and information - route and journey information)
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Wheels: Steel 6.5 J x 16 with tires 195/55 R16 (low rolling resistance tires)
- Keyless Start system
- Power steering (speed-dependent)
- Seat belts: Three-point seat belts in all seats (belt force limiter, front and rear outer seats - Double belt tensioners, front seats - Belt tensioners, rear outer seats - Warning tone and light for unfastened seat belts, front and rear seats)
- Visibility equipment (rain sensor, front - automatic dimming headlights with tunnel detection - interior rearview mirror, automatically dimming)
- Seats: Rear seat backrest split 60:40, foldable
- Lane Keeping Assist (warning in case of unintentional lane departure (between 65 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- Ambient lighting
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))

Extra equipment

- Navigation system: Multimedia navigation system with 7" color touchscreen display (Multimedia radio, automatic music recognition, Bluetooth hands-free system, Apple CarPlay, Android Auto, voice control, 1 USB port, DAB+, steering wheel remote control, navigation system, road map of Europe (including Russia and Turkey), 3D map display, dynamic route guidance, display of points of interest, tour planning, GPS module, charging station display, OpelConnect, including live navigation services, real-time traffic information, online POI search, map updates (via USB))
- Mode 3 charging cable
- Onboard charger (vehicle-integrated charging unit, 3-phase (11 kW))
- Paint finish: Solid special color Jade White
- Reversing camera: 180-degree panoramic reversing camera including parking pilot, rear parking aid (display of the area behind the vehicle, including steering guidelines, when reverse gear is engaged in the color display of the infotainment system)
- Wheels: Steel 6.5 J x 16 with all-weather tires 195/55 R16

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Broken / torn - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Wing mirror - right side	Cap - Scratch(es) - Smart repair
4	Instrument panel	Instrument panel (Links, Klebereste) - Glued / labelled - De-glue / neutralise
5	Rear bumper	Rear bumper - Scratch(es) - Smart repair
6	Indicator - front	Mirror - right side - Scratch(es) - Replace
7	Roof	Roof - dent(s) - Smooth repair work
8	Door - rear left side	Door - Scratch(es) - Paint
9	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - charging cable (Mode 2)

Repainting

No.	Repainting
1	Bonnet, Professionally carried out, Invoice of repair done Non-existent
2	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Bonnet	265 µm	Door - front right side	163 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace




Damage 1: Wheel / tyres: Wheel cover - front right side - Broken / torn - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 4: Instrument panel: Instrument panel (Links, Klebereste) - Glued / labelled - De-glue / neutralise



Damage 4: Instrument panel: Instrument panel (Links, Klebereste) - Glued / labelled - De-glue / neutralise




Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 6: Indicator - front: Mirror - right side - Scratch(es) - Replace




Damage 6: Indicator - front: Mirror - right side - Scratch(es) - Replace




Damage 6: Indicator - front: Mirror - right side - Scratch(es) - Replace



Damage 7: Roof: Roof - dent(s) - Smooth repair work



Damage 7: Roof: Roof - dent(s) - Smooth repair work




Damage 7: Roof: Roof - dent(s) - Smooth repair work




Damage 7: Roof: Roof - dent(s) - Smooth repair work



Damage 7: Roof: Roof - dent(s) - Smooth repair work




Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Door - rear left side: Door - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper - Scratch(es) - Paint



Repainting 1: Bonnet



Repainting 1: Bonnet



Repainting 2: Door - front right side



Repainting 2: Door - front right side