TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48111592
Order No. / Reference: 26951964
Inspection date: 14 Oct 2026

Manufacturer: Peugeot	Model: 308 SW BlueHDi 130 EAT8 Allure
VIN: VR3FCYHZTPY558654	





Vehicle details

Manufacturer / Type / Model / Equipment	
Peugeot 308 SW BlueHDi 130 EAT8 Allure	
Vehicle Identification number	VR3FCYHZTPY558654
Mileage (Read)	92,532 km
First registration	5 Jul 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Schneeweiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	-1,400 km
Last service on / at	03/2026 at 78,112 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG065147
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AEI 00048		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,950 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment: Illuminated glove compartment
- Active Safety Brake Plus (Active day and night between 5 and 140 km/h, depending on the detected obstacle (moving obstacle: 5-140 km/h; stationary obstacle/cyclist: 5-80 km/h; pedestrian: 5-60 km/h). At speeds below 30 km/h, the vehicle is braked to a complete stop; between 30 and 140 km/h, the system reduces the impact speed by a maximum of 50 km/h. Above this threshold, the driver must brake manually.)
- Electrically adjustable, heated and folding exterior mirrors (with LED approach lighting - integrated LED turn signals)
- Turn signals with lane change indicator function
- third brake light
- Digital instrument cluster with high-resolution 10" screen, adjustable and customizable
- Eco-LED headlights
- Front parking aid, acoustic and visual
- Driving mode selector (Sport - Normal - Eco)
- Electric windows, front and rear (with comfort operation and anti-pinch protection)
- Follow-me-home function (automatic)
- Laminated glass windshield, noise-reducing
- Transmission: 8-speed automatic transmission EAT8
- Heated rear window
- Rear apron in black
- Map pockets on the front seatbacks
- Child safety lock at the rear
- Paint finish: Metallic Avatar Blue
- LED lighting in the front footwell
- LED taillights
- LED daytime running lights
- Steering wheel: Leather steering wheel with paddle shifters
- Mirror Screen (Wireless transmission of multimedia content and apps from a compatible smartphone to the vehicle's touchscreen, allowing direct control of compatible functions and apps - CarPlay (for compatible Apple iPhone models) - Android Auto (for compatible smartphone models with Android operating system))
- Fatigue warning system with fatigue detection
- Emergency brake assist with automatic activation of the hazard warning lights
- Particulate filter: FAP diesel particulate filter
- Break warning
- Peugeot i-Toggles (screen with configurable virtual buttons for the most important functions such as radio, air conditioning, navigation system, vehicle settings, telephone and connectivity)
- Upholstery: Fabric/faux leather
- Rain sensor
- Wheels: Halong 17" alloy wheels, two-tone (tires 225/45 R17 94V)
- Side windows in the second row and rear window are more heavily tinted.
- Seats: Driver's seat height adjustable
- ABS (Anti-lock Braking System) with electronic brake force distribution
- Airbags (6) (Driver and front passenger airbag - front passenger airbag deactivatable - front side airbags - front and rear curtain airbags)
- Rear Cross Traffic Alert (Rear Cross Traffic Alert)
- Adaptive Cruise Control (ACC) with Stop & Go function (EAT8) (detection of stop signs, one-way street signs and start/end of no-overtaking zones)
- Exterior mirror caps in Perla Nera Black
- Hill start assist
- On-board computer
- Decorative fabric inserts "Texa" for door panels and dashboard
- Tachometer
- Rear parking aid, acoustic and visual
- Electronic Stability Program (ESP) (with ASR (traction control))
- High beam assist
- electric parking brake
- Front collision warning
- luggage compartment roller blind
- Cup holder in the center console
- rear window wiper
- Interior mirror automatically dimming
- Keyless System Plus (keyless access and start system)
- Automatic climate control (2-zone), with activated carbon filter (separately adjustable for driver and front passenger)
- LED ceiling lighting at the front (2 reading lights at the front and rear)
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- light sensor
- Rear center armrest (with pass-through flap)
- front center armrest
- Multifunctional touchscreen with 10" HD color display (capacitive screen - multi-window capable with widgets or shortcuts)
- Multi-collision brake
- Navigation system: PEUGEOT i-Connect Advanced (up to 8 profiles and 2 smartphones simultaneously via Bluetooth - Bi-tuner - 6 speakers - DAB+ - MP3-compatible - Bluetooth hands-free calling with audio streaming via Bluetooth - 2 front USB ports (Type C) - Steering wheel and touchscreen controls. Navigation: - Real-time navigation by TomTom Services - Over-the-air map updates - Map display on the digital instrument cluster - OK PEUGEOT voice control for navigation, telephone, climate control and media - 2 rear USB-C ports)
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Passenger seat height adjustable
- Seats: Manual lumbar support for driver

- Seats: Rear bench seat and backrest split 40/20/40, foldable (Magic Flat system with control element in the boot)
- Seats: Front seats (three-point seat belts with belt locking devices - pyrotechnic belt tensioners and electronically controlled belt force limiters - warning light and warning signal when the seat belt is not fastened or is released for driver and front passenger - safety-optimized headrests)
- Doors lock automatically when driving off
- Traffic sign recognition (with display of the speed recommendation in the instrument cluster)
- Decorative trim in high-gloss black on the side windows
- Adjustable intermediate loading shelf
- Seats: Rear seats (3 three-point safety belts - belt force limiters on the side seats - warning light and warning signal when the safety belt is released - Isofix child seat anchors on the outer seats)
- Lane keeping assist with steering intervention
- 12-volt socket
- Stop&Start automatic
- Blind spot assist
- Chrome-plated decorative exhaust tailpipes
- Immobiliser
- Central locking system, activatable from inside via remote control

Extra equipment

- Detachable towbar (with removable ball head without tools)
- Seats: Heated front seats
- luggage compartment partition net
- Paint finish: Snow white

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
3	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
4	Door - front right side	Door - Dent / paintcoat damage - Smart repair
5	Rear bumper	Rear bumper (+ Blende) - Scratched - Smart repair
6	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
7	Misc.	Inspection / maintenance - Due - Replace
8	Front bumper	Front bumper (+ viele steinschläge) - Scratched - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Body	Body - Scratch(es) - No deduction
4	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
5	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
6	Door - front left side	Door edge - Scratch(es) - Cover / polish

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair




Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 4: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 5: Rear bumper: Rear bumper (+ Blende) - Scratched - Smart repair



Damage 5: Rear bumper: Rear bumper (+ Blende) - Scratched - Smart repair




Damage 5: Rear bumper: Rear bumper (+ Blende) - Scratched - Smart repair



Damage 5: Rear bumper: Rear bumper (+ Blende) - Scratched - Smart repair



Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace




Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 7: Misc.: Inspection / maintenance - Due - Replace



Damage 7: Misc.: Inspection / maintenance - Due - Replace




Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint




Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Damage 8: Front bumper: Front bumper (+ viele steinschläge) - Scratched - Repair and paint



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Wear and tear 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Wear and tear 5: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Wear and tear 5: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Wear and tear 6: Door - front left side: Door edge - Scratch(es) - Cover / polish



Wear and tear 6: Door - front left side: Door edge - Scratch(es) - Cover / polish