APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	HM Tongeren
Make:	BMW
Model / version:	X3
Vin:	WBATS110209H72815
Plate:	2BAW832
Mileage:	69344
SOH:	
First registration:	14/09/2021
Color:	Black Sapphi

ADDITIONAL INFORMATION

Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	?
Maintenance book:	
Number of keys:	2
Original key:	?


PICTURES


















































VIN INFORMATION

10 Haut-parleurs	Transmission automatique	8 rapports
Equipement Advantage	Matière : alliage	Lettre repère (J)
Diamètre avant 18	Diamètre arrière 18	Largeur avant 7,0
Largeur arrière 7,0	Diamètre avant 18	Diamètre arrière 18
Hauteur avant 60	Hauteur arrière 60	Indice de vitesse avant W
Indice de vitesse arrière W	Largeur avant 225	Largeur arrière 225
Climatisation automatique 2 zones	Climatisation réfrigérant 1234YF	Hybride essence
1998 cm3	2.00 litres	215 kw
292 ch	Euro 6	Métallisée vernissée
Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique	Rétroviseurs rabattables électriques
Rétroviseur intérieur jour/nuit automatique	Garnitures simili-cuir	Aide au stationnement avant

Aide au stationnement arrière	Assistance au parking	Caméra avant
Caméra arrière de recul	Alarme	Appel de secours
Lunette arrière teintée foncée	Vitres portes arrière teintées foncées	Vitres de custode teintées foncées
Fixotoit Individual Shadow Line	Protection piéton	Freinage d'urgence assistée autonome (urbain)
Avertisseur de collision avant	Contrôle pression des pneus	depuis 04.21
pack de rangement	mesures CO2 étendues	tuner DAB
filet de séparation coffre	BMW Live Cockpit Pro	protection acoustique des piétons
boulons antivol de roue	spécifique Europe	

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	6 mm		225/60R18 104V	Summer	Aluminium	×
Front right	6 mm		225/60R18 104V	Summer	Aluminium	×
Rear left	6 mm		225/60R18 104V	Summer	Aluminium	×
Rear right	6 mm		225/60R18 104V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Contact key - Bestuurdersprofiel verwijderen	Not original part
2	Bumper F	Grooved
3	Wing trim FL	Grooved
5	Bumper R	Grooved
6	Spoier bumper R	Grooved
7	Door RR	Dent(s) and scratch(es)
8	Wing trim RR	Grooved
9	Door trim RR	Grooved
10	Door FR	Dent(s) and scratch(es)

Total: 9

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Contact key - Bestuurdersprofiel verwijderen - Not original part



2 - Bumper F - Grooved










3 - Wing trim FL - Grooved







5 - Bumper R - Grooved







6 - Spoier bumper R - Grooved







7 - Door RR - Dent(s) and scratch(es)








8 - Wing trim RR - Grooved






9 - Door trim RR - Grooved





10 - Door FR - Dent(s) and scratch(es)







4 - Bodywork - Scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

12/10/2026 13:17

