TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48102687
Order No. / Reference: 27025046
Inspection date: 14 Oct 2026

Manufacturer: Ford	Model: S-Max 2.5 Duratec FHEV TREND
VIN: WF0JXXWPCHNJ56565	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford S-Max 2.5 Duratec FHEV TREND	
Vehicle Identification number	WF0JXXWPCHNJ56565
Mileage (Read)	55,155 km
First registration	5 Sept 2022
Number of holders	1
Next periodical technical inspection	09/2027
(Report on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	2,488 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	5 / 7
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	90 %
Last service on / at	08/2026 at 53,601 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP431213
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BVI 00101		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,350 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R17 103V	Winter tyres on Light alloy	Sonstige	2mm / 2mm
2)	235/55 R17 103V	Winter tyres on Light alloy	Sonstige	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Anti-lock braking system (ABS)
- Attachment points for safety partition grilles
- Tires: 7.5 J x 17 alloy wheels (4) with 235/55 R 17 tires (in 10-spoke design)
- Overhead console with glasses storage compartment and child observation mirror
- High Beam Assist
- Ford Easy Fuel
- Ford Power Start function
- FordPass Connect including eCall and Wi-Fi hotspot
- Luggage compartment lighting
- Transmission: CVT automatic
- rear window wiper
- Interior mirror, automatically dimming
- Isofix mount
- Air conditioning with automatic temperature control
- Front headrests, 4-way height and tilt adjustable
- Steering wheel: Multifunction leather steering wheel
- Reading lights front and rear
- MyKey key system (individually programmable second key)
- Emergency brake light
- Upholstery: Cloth
- Tire Pressure Monitoring System (TMPS)
- Windscreen wipers with rain sensor
- Headlight assistant with day/night sensor
- Electromechanical power steering
- Seats: Driver and passenger seats, 4-way manually adjustable
- Power outlet: 12-volt connection in the luggage compartment and in the center console
- Traffic sign recognition system
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats
- Exterior mirrors in body color, driver and passenger side, electrically adjustable and heated
- Hill start assist
- third brake light
- Tachometer
- Electric windows front and rear
- Electronic parking brake
- Ford EasyFold: 2nd row seat backrests fold down electrically at the touch of a button.
- luggage compartment cover
- Cruise control system with intelligent speed limiter
- Back window, heater
- Interior lighting with delay circuit
- Intelligent Protection System (IPS)
- Electric child safety lock
- Rear headrests (3)
- Steering wheel: Steering column, adjustable in height and reach
- Front center console with padded armrest
- Fog light
- Front and rear parking pilot system
- Tire repair kit (for use at a maximum speed of 80 km/h)
- LED taillights
- Headlight dipped beam with switch-off delay including "greeting function"
- Seats: 2nd row of seats with 3 individual seats (FoldFlat System)
- Seats: Front sports seats
- Daytime running light
- Premium carpet floor mats, front and rear
- Lashing eyes in the luggage compartment
- Immobiliser
- Central locking with remote control

Extra equipment

- Tires: 4 all-season tires (in combination with 7.5 J x 17 wheels with 235/55 R 17 tires)
- Package: Business Package I (Ford navigation system including Ford SYNC 3 with AppLink, touchscreen, DAB/DAB+, audible and visual route guidance, live traffic in conjunction with FordPass, enhanced voice control and voice output, Michelin travel guide, quick destination search for addresses and points of interest in a single input field - LED daytime running lights integrated into the headlights - Park Assist with automatic parking sensors - Pre-Collision Assist (distance display and distance warning, collision warning system and active emergency braking assist) - Rearview camera)
- Roof rails "aluminum look"
- Paint finish: Frozen White
- Package: Winter (Heated windscreen - Heated leather steering wheel - Individually and variably heated front seats)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: 3rd row of seats with 2 individual seats (FoldFlatSystem) (seat backrests individually foldable - headrests retractable - reading lights in 3rd row, LED)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Roof	Roof rail - right side - dent(s) - Smart repair
3	Wheel / tyres	Tyre - front - Does not meet the leasing specifications - Replace

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace




Damage 2: Roof: Roof rail - right side - dent(s) - Smart repair



Damage 2: Roof: Roof rail - right side - dent(s) - Smart repair



Damage 3: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 3: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace



Damage 3: Wheel / tyres: Tyre - front - Does not meet the leasing specifications - Replace