Ford

2.0TDCI 96KW TREND RWD 350E HD

VIN: WF0AXXTTRARY04334



Description

Registration number 2GWL272	**First registration date** 22/04/2025	**Odometer** 22490 km
Color Blanc Glacier	**Model year** 2025	**Upholstery** -
Number of doors 2	**Number of seats** -	**Generation** -
Engine displacement 1995	**Gearbox type** Manual	**Engine type** Combustion
Number of gears 6	**Drivetrain** Rear Wheel Drive (RWD)	**Max power** 96 KW

Vehicle Equipments

Rear-view camera	Automatic headlights	Climate control
Rain-sensitive wipers	Front sensors	

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 26/10/2026	**Inspection approval date** 27/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Spare Key / -	Missing	Replace

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



002	Emergency wheel / -	Missing	Replace



003	Wing / Front Left	Dent	Replace Part number : 2203290







004	Wing extension moulding / Front Left Painted : No	Scuff	Replace






005	Door / Front Left	Dent	Repair






006	Rear-view mirror / Left	Broken	Replace Part number : 2863968





All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

007	Mirror glass / Front Left Rear-view mirror glass type : Rear-view mirror glass	Broken	Replace





008	Turning signal light / Left	Broken	Replace




009	Wheel trim / Front Left Rim/Tyre diameter : 16 "	Missing	Replace




010	Bumper moulding / Back [1] Painted : No / Chromed : No	Non Compliant	Cleaning

011	Rear (wing) lamp glass / Back Right	Broken	Replace






012	Wheel trim / Front Right Rim/Tyre diameter : 16 "	Missing	Replace



013	Wheel trim / Back Right Rim/Tyre diameter : 16 "	Missing	Replace

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



014	Turning signal light / Right	Broken	Replace




015	Mirror glass / Front Right Rear-view mirror glass type : Rear-view mirror glass	Broken	Replace




016	Bumper / Front Painted : No	Scuff	Replace







017	laadklep / Back	Dent	Acceptable




[1] Verf

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Triangle
- [x] Jack
- [ ] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [ ] Spare wheel tyre
- [x] Registration certificate owner
- [x] Registration certificate

Main set of tyres

Front Left	CONTINENTAL	235/65/16 Summer	5 mm
Front Right	CONTINENTAL	235/65/16 Summer	5 mm
Back Left	CONTINENTAL	235/65/16 Summer	8 mm
Back Right	CONTINENTAL	235/65/16 Summer	8 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Dashboard from rear seat



Front passenger compartment


Front right


Odometer



Navigation



Spare Tyre




Vin


Other


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




Other



Other



Spare Key / - / Missing



Emergency wheel / - / Missing



Wing / Front Left / Dent



Wing / Front Left / Dent




Wing / Front Left / Dent



Wing / Front Left / Dent



Wing / Front Left / Dent



Wing extension moulding / Front Left / Scuff



Wing extension moulding / Front Left / Scuff



Wing extension moulding / Front Left / Scuff



Door / Front Left / Dent



Door / Front Left / Dent




Door / Front Left / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Door / Front Left / Dent



Rear-view mirror / Left / Broken




Rear-view mirror / Left / Broken



Rear-view mirror / Left / Broken



Mirror glass / Front Left / Broken



Mirror glass / Front Left / Broken



Turning signal light / Left / Broken



Turning signal light / Left / Broken




Wheel trim / Front Left / Missing



Wheel trim / Front Left / Missing



Bumper moulding / Back / Non Compliant



Bumper moulding / Back / Non Compliant



Rear (wing) lamp glass / Back Right / Broken



Rear (wing) lamp glass / Back Right / Broken



Rear (wing) lamp glass / Back Right / Broken

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Wheel trim / Front Right / Missing



Wheel trim / Back Right / Missing




Turning signal light / Right / Broken



Turning signal light / Right / Broken



Mirror glass / Front Right / Broken



Mirror glass / Front Right / Broken



Bumper / Front / Scuff



Bumper / Front / Scuff



Bumper / Front / Scuff




Bumper / Front / Scuff



Bumper / Front / Scuff



laadklep / Back / Dent



laadklep / Back / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.