ARVAL
BNP PARIBAS GROUP

2CLW156

INSPECTION REPORT

End of contract

GENERAL INFO

File	318881
License plate	2CLW156
Vehicle identification number	WAUZZZGE4PB002770
Dossier	2022011008
Make	Audi E-tron 55 300kW Quat.S-Li
Mileage	112125
First registration	09/09/2022
client availability date	20/08/2026
inspectionDate	27/08/2026












CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	


Verbruik
Bijrijdersairbag: in paraatheid gebracht
112125km
9:39
+19,5°c


2-CLW-156
KEURING

DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
139	Bumper Rear / Spoiler / Replace	N
40	Windshield // Repair	Y
184	Wing Rear Right // Repair & Painting	N
222	Side View Mirror Right // Painting	Y
236	Wing Front right // Polish	Y
237	Wing Front right / Trim / Replace	Y
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y

Damage Pictures




Wing Rear Right // Repair & Painting-scratch + dent



Windshield // Repair-stone chipping




Wheel Two Tone Rear Left // Repair-scratch




Wheel Two Tone Rear Right // Repair-scratch






Side View Mirror Right // Painting-scratch




Wing Front right / Trim / Replace-scratch






Wing Front right // Polish-scratch





Bumper Rear // Repair & Painting-scratch + dent






Bumper Rear / Spoiler / Replace-scratch + dent