TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48485954
Order No. / Reference: 27176895
Inspection date: 4 Nov 2026

Manufacturer: Audi	Model: A5 Sportback 40 TDI S tronic S line
VIN: WAUZZZF57PA040744	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A5 Sportback 40 TDI S tronic S line	
Vehicle Identification number	WAUZZZF57PA040744
Mileage (Read)	109,630 km
First registration	1 Mar 2023
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Mythosschwarz
Doors / Seats	5 / 4
Upholstery type	Cloth / leather combination
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	4,700 km
Last service on / at	11/2025 at 84,232 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS427223
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BWN 00469		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,125 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 96H	Winter tyres on Light alloy	Continental	7mm / 7mm
2)	225/50 R17 96H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R19 96Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	255/35 R19 96Y	Summer tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service including vehicle control
- Electrically adjustable/heated exterior mirrors
- Outdoor temperature display
- Fabric headliner
- Diesel particulate filter (DPF) with DeNox catalyst and AdBlue tank
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Driver information system
- Electric front windows
- front and rear floor mats
- Cruise control system with adjustable speed limiter
- Interior lighting
- Manual child lock
- Automatic air conditioning
- boot floor mat
- Fuel tank (40 liters)
- LED headlights
- Mild hybrid
- front center armrest
- Package Gloss
- Wheel: Alloy wheels "5-twin-spoke design" (S-design)
- Wheel: Tire repair kit
- Radio: MMI Radio Plus
- Radio accessories: Data module Europe
- Electromechanical power steering
- Front seats (standard seats)
- Phone: Bluetooth interface
- Glazing: Windscreen in heat-insulating and acoustic glazing
- Airbag for driver and front passenger
- Accent areas matte black
- Drive slip control
- Audi drive select
- Audi pre sense city
- Exterior mirror housings in body color
- third brake light
- Decorative inlays diamond lacquer silver grey
- Tachometer
- Rear parking sensors
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Suspension (sports suspension)
- Remote key, without safe lock
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic (7-speed)
- Interior mirror dimming
- ISOFIX and Top Tether child seat anchors for the outer rear seats
- Headrests (4)
- LED taillights
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Non-smoking version
- Upholstery: Fabric finish Index
- Wheel: Tire pressure monitoring system
- Wheel: Tires optimized for rolling resistance, speed-limited
- Radio accessories: 8 speakers
- Rear seat backrest foldable
- Seat belts: Three-point automatic seat belts for all seats
- Start-stop system
- First aid kit with warning triangle
- Electronic immobilizer
- Green thermal insulation glazing

Extra equipment

- Audi virtual cockpit with 12.3" color display (Innovative, fully digital instrument cluster for flexible and needs-based display of relevant information according to driver requirements: speed/RPM, map display, Audi connect services, radio/media information, etc.; the VIEW button on the multifunction steering wheel allows switching between two different-sized displays of the round instruments. The display with smaller instruments enables large, clear graphics of the on-board computer and MMI content)
- Auxiliary heater/ventilation (The auxiliary heater warms the interior and defrosts the windows without starting the engine. The auxiliary ventilation system supplies fresh air and lowers the interior temperature. Both functions can be activated via a timer and separate remote control. An intelligent control system with timer and departure time programming calculates the heating duration efficiently in terms of time and energy. Two heating modes are selectable: - defrost (defrost mode for the windows only) - warm (warm mode for preheating the interior)
- Decorative inlays in matt brushed aluminum (for dashboard, door panels and center console)
- Deletion of performance/technology lettering
- Driving Assistance Package (Audi active lane assist - Audi adaptive cruise control - Audi pre sense rear and basic - Traffic jam assist - Predictive efficiency assist - Evasive steering assist - Left turn assist - High beam assist - Driver information system with color display - Camera-based traffic sign recognition - Lane change warning)
- Fuel tank (54 liters)
- Head-up display (projects driver-relevant information from assistance systems, navigation or warning messages onto the windshield in the driver's direct field of vision. The height-adjustable head-up display enables a high-contrast, multi-colored display within the driver's field of vision.)
- Matrix LED headlights with Audi laser light (Matrix LED headlights with Audi laser light, dynamic light styling and dynamic turn signals - LED taillights with dynamic light styling and dynamic turn signals - headlight cleaning system)
- Package: Ambient Lighting Package (in addition to the interior lighting: - approach lighting in the exterior door handles - entry lights on the underside of the front doors - illuminated front cupholders - front footwell lighting - illuminated interior door handles - ambient door lighting - ambient lighting in the front center console)
- Paint finish: Metallic
- S line interior package (sports seats in front - S line seat covers in black fabric/leather combination with S embossing on the backrests of the front seats - 3-spoke leather steering wheel with multifunction plus including steering wheel grips in perforated leather and S emblem; steering wheel and gearshift boot with contrast stitching, color-coordinated - headliner in black fabric - decorative inlays in matt brushed aluminum with accent surfaces in gloss black - pedals and footrest in stainless steel - floor mats front and rear with contrast stitching)
- AdBlue tank (24 liters)
- Black glass-look accent surfaces (for dashboard, door trim panels and center console insert; in conjunction with automatic transmission including cover for storage compartment in the center console)
- Business package (front seat heating - comfort package mirrors - infotainment package smartphone - navigation package - leather steering wheel in 3-spoke design with multifunction plus)
- Comfort automatic climate control 3-zone (in addition to the automatic climate control: - climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear passenger compartment temperature in the rear center console - automatic recirculation control via air quality sensor, with dust and odor-removing allergen filter - ventilated glove compartment - dust and odor-removing cabin air filter - residual heat utilization)
- Comfort package seats (variable headrests for the front seats - 4-way lumbar support for the front seats, electrically adjustable horizontally and vertically - comfort center armrest in the front, longitudinally adjustable and tiltable; additional storage option in the integrated storage compartment)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides with memory function (with integrated LED turn signals and curb view function for the passenger-side exterior mirror; aspherical mirror glass, including heated windshield washer nozzles. The passenger-side exterior mirror tilts downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Parking Assistance Package (Parking Aid Plus - Parking Assist - Rearview Camera)
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)
- Seats: Electrically adjustable front seats with memory function for the driver's seat (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt; with memory function for the driver's side: 2 memory locations for the electrically adjustable front seats and the exterior mirrors, storable and recallable via the memory buttons in the door trim)
- Suspension with damper control (The suspension adapts very well to different driving situations and road conditions: - electronically controlled adaptation to different driving situations - dynamic or comfort-oriented damper tuning - adjustable via Audi drive select)
- Telephone: Audi Phone Box (Up to two smartphones can be paired with the vehicle simultaneously via Bluetooth, allowing you to either play music through the vehicle or make phone calls from one of the two smartphones. It connects to the vehicle's antenna, improving both reception and call quality. Additionally, the smartphone can be charged wirelessly using the Qi standard or via USB if it is still in the storage compartment.)

- Seat covers in microfiber Dinamica Frequency/leather with S embossing (seat center panel in microfiber Frequency - seat side bolsters, headrest center panel and center armrest in leather black or rotor grey with contrasting stitching - S embossing in the backrests of the front seats)
- Variable folding luggage compartment mat (foldable and collapsible in several segments; usable in full length to cover the luggage compartment floor even with the rear seat backrest folded down and for variable division of the load space; protective length sufficient also for the loading edge and the bumper)
- Wheel: Alloy wheels "5-parallel spoke design" (8.5 J x 19 with tires 255/35 R 19)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Winter package (windscreen with climate comfort and acoustic glazing, wirelessly heated - leather steering wheel in 3-spoke design with multifunction plus and steering wheel heating - seat heating front and rear)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front right side	Door - Scratch(es) - Paint
2	Front bumper	Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint
3	Bonnet	Bonnet (Mehrere) - Stone chips - Paint
4	Vehicle glazing	Windscreen with lane departure assistant - Damaged - Replace

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 11 Jun 2026	1.040,51 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

-Der montierte Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Damage 1: Door - front right side: Door - Scratch(es) - Paint



Damage 1: Door - front right side: Door - Scratch(es) - Paint



Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint




Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint




Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint




Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint




Damage 2: Front bumper: Front bumper (Viele Steinschläge) - Dent / paintcoat damage - Repair and paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 3: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 4: Vehicle glazing: Windscreen with lane departure assistant - Damaged - Replace



Damage 4: Vehicle glazing: Windscreen with lane departure assistant - Damaged - Replace



Damage 4: Vehicle glazing: Windscreen with lane departure assistant - Damaged - Replace