TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48418916
Order No. / Reference: 27202366
Inspection date: 29 Oct 2026

Manufacturer: Mercedes-Benz	Model: CLE 300 4Matic Cabrio 9G-TRONIC
VIN: W1KMK4HB7RF041234	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz CLE 300 4Matic Cabrio 9G-TRONIC	
Vehicle Identification number	W1KMK4HB7RF041234
Mileage (Read)	37,142 km
First registration	4 Oct 2024
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,999 ccm / 4
Power	190 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Convertible / Roadster
Colour / colour code	Graphitgrau Metallic
Doors / Seats	2 / 4
Upholstery type	Leather
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	153 Tag(e)
Last service on / at	01/2026 at 28,354 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HD776509
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BQS 00053		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,420 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95Y	Summer tyres on Light alloy	Continental	6mm / 6mm
2)	275/30 R20 97Y	Summer tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- 4MATIC all-wheel drive
- Ambient lighting with 64 light colors
- Tachometer
- Driver display
- Fingerprint scanner
- Transmission: 9-speed automatic, 9G-TRONIC
- THERMATIC automatic climate control (2-zone automatic climate control: allows individually adjustable temperature for driver and front passenger - climate settings can be controlled via the multimedia system or the climate control unit in the center console - automatic recirculation (only in conjunction with navigation) - fine dust activated carbon filter for filtering dust, soot and pollen as well as reducing pollutants and odors - dew point sensor, continuous defrost nozzle under the windshield and central defrost outlet)
- Otto particulate filter
- Package: AMG Line Exterior for CLE 300 and 450 4Matic (AMG Styling - A-frame radiator grille with Mercedes-Benz pattern and integrated Mercedes star - Sport suspension with sport direct steering - Exhaust system with two visible tailpipe trims integrated into the bumper - Brake system with larger brake discs on the front axle)
- Package: Convertible Comfort (AIRCAP - AIRSCARF - Fully electric trunk partition)
- Package: Interior lighting package (Illuminated glove compartment - Lighting for wireless mobile interface or mobile phone storage - Lighting for the storage compartment in the center console or the double cupholder - Lighting for the storage compartment under the armrest of the center console - Two makeup lights in front - Two reading lights in the overhead control unit - Two reading lights and interior light function in the grab handles in the rear - Lighting for the trunk or cargo area)
- Package: Parking package with reversing camera (including Active Parking Assist with PARKTRONIC - reversing camera)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding with parking position on the right and ambient lighting in the exterior mirrors with projection of the AMG logo)
- PRE-SAFE System
- Radio: Extended MBUX functions (personalization (profiles) and prediction functions - MBUX voice assistant* with natural language understanding - activation via Hey Mercedes - learning function of the MBUX voice assistant by connecting to a cloud-based online dictionary - Wi-Fi hotspot - internet radio)
- Tire pressure monitoring system
- Seats: Heated seats for driver and front passenger
- Phone accessory: Android Auto
- Phone accessories: Wireless charging system for mobile devices
- Convertible top: Fabric acoustic convertible top in black
- Airbag: Center airbag
- Airbag: Windowbag for driver, front passenger and rear passengers
- Anti-lock braking system (ABS)
- Third brake light
- Electric window regulator, 2-way
- Floor mats, velour
- KEYLESS-GO
- Rear headrests (2)
- LED High Performance headlights (low beam with LED projection technology - high beam with LED reflection technology - daytime running lights, position lights and direction indicators in LED technology - adaptive full-LED taillights with automatic adjustment of light intensity to the surroundings)
- Steering: Direct steering
- Mercedes-Benz emergency call system
- Center console in high-gloss black
- Package: AMG Line Advanced (00U Remote Services 382 Communication module (5G) for the use of Mercedes me connect services 70B Warning vest for driver P29 AMG Line interior P31 AMG Line exterior PBG MBUX Navigation Premium P65 Seat comfort package U02 Seat belt presenter PDA Advanced package)
- Package: AMG Line Interior (seats with exclusive sports seat design and integrated headrest - multifunction sports steering wheel in Nappa leather - AMG sports pedal assembly in brushed stainless steel with black rubber studs - instrument panel upper section and belt edges in ARTICO man-made leather in Nappa look black - trim element metal structure - AMG floor mats - interior headliner fabric black - ARTICO man-made leather/MICROCUT microfiber black)
- Package: Memory (driver and front passenger seat, steering column and exterior mirrors electrically adjustable and storable - seat longitudinal position and headrest height additionally electrically adjustable - 3 memory options for settings for driver and front passenger - 4-way lumbar support for driver and front passenger - seat cushion depth adjustment with gapless cushion - PRE-SAFE positioning function for the front passenger seat)
- Package: USB (USB-C port in the center console's storage compartment, suitable for data transfer - 2 USB-C ports under the front center armrest, suitable for data transfer)
- Radio: MBUX multimedia system
- Radio accessories: Digital radio (DAB)
- Radio accessories: Central display with 30.2 cm (11.9") screen diagonal (touch display with LCD technology - 30.2 cm (11.9") screen diagonal - resolution of 1,624 x 1,728 pixels (width x height) - angled 6° towards the driver)
- Windscreen wipers with rain sensor
- Seats: Rear seat backrests foldable
- Phone accessories: Apple CarPlay
- Phone accessories: Smartphone integration
- TIREFIT
- Pre-installation for digital key handover

- Immobiliser
- Central locking with remote control

Extra equipment

- Airbag: Automatic passenger airbag deactivation
- Active Distance Assist DISTRONIC
- Package: AMG Line Advanced Plus (AMG Line Advanced - Traffic Sign Assist - Blind Spot Assist - Ambient Lighting Plus - Illuminated Door Sills with "Mercedes-Benz" Lettering)
- Upholstery: Black leather
- Radio accessories: Burmester 3D surround sound system (15 powerful speakers, with dedicated amplifier channel; DSP amplifier with a total output of 710 W (2 x 120 watts, 7 x 50 watts, 6 x 20 watts); 2 broadband speakers in the front for 3D sound; Frontbass technology with woofers integrated into the body shell; sound optimization for the front, rear, or all seats; 2 sound presets: Pure and 3D Sound; equalizer function; noise compensation; pre-installation for MBUX entertainment)
- Sporty engine sound
- Windstop
- Decorative elements, wood, linden, line structure, anthracite, open-pore
- Airbag: Side airbags in the rear
- GUARD 360° Vehicle Protection Plus (Anti-theft alarm system - Tow-away protection with visual and audible warning in case of detected change in position - Audible alarm - Interior monitoring (triggers upon movement inside the vehicle) - Collision detection, free for 3 years from activation - GUARD 360° label on the front side windows)
- Wheels: 50.8 cm (20") AMG multi-spoke light-alloy wheels (aerodynamically optimized, painted black and high-sheen finish, front axle 245/35 R20 on 8.0 J x 20 ET 45.1, rear axle 275/30 R20 on 9.0 J x 20 ET 60.5)
- Seats: Seat climate control for driver and front passenger (3-stage seat ventilation - 3-stage seat heating)
- Extendable sun visors (The extendable and laterally swiveling sun visors for driver and front passenger can be easily adjusted – depending on whether irritating light is coming from the front or the side. A cosmetic mirror with LED lighting is integrated into the inside of each visor.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Mirror housing - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Convertible with open roof



Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Instrument cluster



Figure 9: Instrument panel

Figure 10: Interior 360° view (Online Link)



Figure 11: Cargo area




Figure 12: VIN



Figure 13: Mounted tyres



Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Damage 1: Wing mirror - right side: Mirror housing - Scratch(es) - Loss in value

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Damage 1: Wing mirror - right side: Mirror housing - Scratch(es) - Loss in value