DEKRA

DEKRA Automotive Solutions


# Appraisal Report

## Vehicle details

| | | | | | |
|---|---|---|---|---|---|
| VIN | W0V7H9ENX P4349501 | Registration date | 20/06/2024 | Exterior Color | Unknown |
| Brand | OPEL | Licence Plate | KO-VK 819 | Odometer | 20 215 km |
| Model | CROSSLAND 1.5 Diesel 81kW Elegance | | | | |

## Inspection Details

| | | | | | |
|---|---|---|---|---|---|
| Arrival Date | 20/08/2026 | Inspection ID | 7131267 | Inspection date | 26/08/2026 |
| Assign Date | 20/08/2026 | Fleet owner | Leasys Privat Leasing | Inspection loc. | Leasys AKB Kitzingen |



## Generic equipment


## Removable element

| | |
|---|---|
| Spare wheel kit | ✔ |
| Rear parcel shelf | ✔ |
| Aerial cable | ✔ |

## Technical Document

| | |
|---|---|
| User manual | ✔ |
| Warranty booklet | ✔ |
| Log books | ✔ |
| Spare key | ✔ |
| Key | ✔ |
| Remote key | ✔ |
| Service | ✔ |

## Tyres



Bridgestone 195/60/16 H Summer 6.0 mm


Bridgestone 195/60/16 H Summer 6.0 mm

Bridgestone 195/60/16 H Summer 6.0 mm

Bridgestone 195/60/16 H Summer 6.0 mm



## Winter kit



Falken 195/60/16 H Winter 7.0 mm

Falken 195/60/16 H Winter 7.0 mm

Falken 195/60/16 H Winter 7.0 mm

Falken 195/60/16 H Winter 7.0 mm



## Exception / Damage

**1**

| | | | | | |
|---|---|---|---|---|---|
| Part | Bumper | Repair Time | - | Part Cost | - |
| Position | Front | Repair Cost | - | Gross Cost | - |
| Damages | Worn out | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | **-** |

**2**

| | | | | | |
|---|---|---|---|---|---|
| Part | Bonnet | Repair Time | - | Part Cost | - |
| Position | - | Repair Cost | - | Gross Cost | - |
| Damages | Worn out | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | For info | Flat Rate | - | **Net Cost** | **-** |

**3**



| | | | | | |
|---|---|---|---|---|---|
| Part | Windscreen | Repair Time | 1.70 | Part Cost | 458.03€ |
| Position | Front | Repair Cost | 238.00€ | Gross Cost | 696.03€ |
| Damages | Stone impact | Paint Time | - | Depreciation % | - |
| Severity | - | Paint cost | - | Depreciation | - |
| Repair mode | Replace | Flat Rate | - | **Net Cost** | **696.03€** |

**4**

| | | | | | |
|---|---|---|---|---|---|
| Part | Fixing glue kit | Repair Time | - | Part Cost | 98.05€ |
| Position | Front | Repair Cost | - | Gross Cost | 98.05€ |
| Damages | Broken | Paint Time | - | Depreciation % | 15.00% |
| Severity | - | Paint cost | - | Depreciation | - 14.71 |
| Repair mode | Replace | Flat Rate | - | **Net Cost** | **83.34€** |

**5**



| | | | | | |
|---|---|---|---|---|---|
| Part | Wing | Repair Time | 0.60 | Part Cost | - |
| Position | Front right | Repair Cost | 84.00€ | Gross Cost | 129.00€ |
| Damages | Scratched | Paint Time | 0.30 | Depreciation % | 15.00% |
| Severity | - | Paint cost | 45.00€ | Depreciation | - 19.35 |
| Repair mode | Repair | Flat Rate | - | **Net Cost** | **109.65€** |

DEKRA Automotive Solutions

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| 6 |  | Part | Paint preparation | Repair Time | - | Part Cost | - |
| | | Position | - | Repair Cost | - | Gross Cost | 195.00€ |
| | | Damages | - | Paint Time | 1.30 | Depreciation % | 15.00% |
| | | Severity | - | Paint cost | 195.00€ | Depreciation | - 29.25 |
| | | Repair mode | Paintworks | Flat Rate | - | **Net Cost** | **165.75€** |

## Summary Inspection

| | | | | | |
|---|---|---|---|---|---|
| Gross Price | 1,118.08€ | Depreciation | -63.31€ | Net Price | 1,054.77€ |

## Labor cost summary

| | Hourly Rate | Time | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|---|---|
| Bodywork | 140.00€ | 2.30 | 322.00€ | 3.91 % | -12.60€ | 309.40€ |
| Paintwork | 150.00€ | 0.30 | 45.00€ | 15.00 % | -6.75€ | 38.25€ |
| Paint preparation | 150.00€ | 1.30 | 195.00€ | 15.00 % | -29.25€ | 165.75€ |

## Miscellaneous

| | Gross Price | Depreciation % | Depreciation | Net Price |
|---|---|---|---|---|
| Small parts / disposal charge | 0.00€ | - | - | 0.00€ |
| Part Cost | 556.08€ | 2.64 % | -14.71€ | 541.37€ |
| Flat Rate | 0.00€ | - | - | 0.00€ |