TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48398974
Order No. / Reference: 27204066
Inspection date: 29 Oct 2026

Manufacturer: Ford	Model: Focus Turnier 1.0 EcoBoost Hybrid Aut. ST-LINE X
VIN: WF0PXXGCHPSC43715	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.0 EcoBoost Hybrid Aut. ST-LINE X	
Vehicle Identification number	WF0PXXGCHPSC43715
Mileage (Read)	20,224 km
First registration	27 Oct 2025
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	114 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Fantastic-Rot Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Red
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Vehicle details

Maintenance booklet / proof	Available / incomplete	**Next maintenance in**	34 %
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HN229966
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BUE 00176		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,005 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/50 R17 95V	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	205/50 R17 95V	All-season tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
N	125/70 R16 96M	Summer tyres on Steel	Sonstige	3 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Tires: 7 J x 17 alloy wheels (4) with 215/50 R 17 tires (in 5-spoke Y-design, in Rock Metallic)
- Black woven fabric headliner
- Roof spoiler painted in car color
- Dual exhaust system
- Third brake light
- Electronic Stability Program (ESP) (with Emergency Brake Assist (EBA) and Traction Control System (TCS))
- Electric front and rear windows (with all-around closing function)
- Ford ECO-Coach (signals environmentally friendly driving style)
- FordPass Connect including live traffic information (Additionally for PowerShift automatic transmission: Ford Mobile Remote remote start function)
- Cruise control
- Transmission: 7-speed PowerShift automatic transmission
- Back window, heater
- Interior lighting with LED technology (front and rear and map reading lights at the front)
- Isofix mounting (including top tether anchor points on the outer seats of the 2nd row)
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Knee pads on the center console
- Paint finish: Solid
- LED headlights (LED low beam - LED high beam - LED daytime running lights incl. integrated LED turn signals at the front - LED cornering lights, static, incl. integrated LED fog light function and maneuvering light)
- Make-up mirrors in driver and passenger sun visors
- Rear center armrest (with 2 cup holders)
- MyKey key system (individually programmable second key)
- Fatigue warning
- Navigation: Ford SYNC 4 including Ford navigation system with AppLink, 13.2" touchscreen and DAB/DAB+ (6 speakers - Amazon Alexa built-in voice assistant - Android Auto and Apple CarPlay - Steering wheel controls - Digital user manual - Bluetooth hands-free calling and audio streaming - USB ports - Voice control for audio and phone - Ford Power-Up software updates - Intelligent route suggestions - Customizable user profiles - Radio player - Audible and visual route guidance, dynamic and cloud-based navigation with advanced traffic information system, lane guidance and road map for Europe)
- Pre-Collision Assist (Forward Alert system with pedestrian and bicycle detection)
- Rear view camera
- Ambient lighting, front
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable (with integrated turn signals - ambient lighting)
- Hill start assist
- Roof rails, black
- Digital instrument panel 12.3" (31.2 cm screen diagonal)
- Tachometer
- Electronic Shifter
- Lane keeping assist including lane keeping assist
- Chassis: Sport-tuned
- Electric parking brake with auto-hold function
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Ford Key Free system including Ford Power Start function (keyless unlocking/locking - keyless starting)
- luggage compartment cover
- Speed limiter (Intelligent speed limiter with speed limit display)
- Rubber mats (wet area with standard rubber mat)
- Illuminated glove compartment
- rear window wiper
- Interior mirror, automatically dimming
- Intelligent safety system (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts on all seats, height-adjustable in the front - safety pedal assembly)
- Headrests: 2 front and 3 rear, height adjustable
- LED taillights
- ST-Line design steering wheel (flattened at the bottom and with red decorative stitching - Sensico leather-look leather)
- Steering column, adjustable (adjustable in height and reach)
- Front center console "Premium" (sliding armrest - cup holder incl. cover - storage compartments - 12-volt and USB connection)
- Emergency call assistant
- Otto particulate filter
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist (In the event of a severe collision, which would also deploy the airbag and in which the driver might be incapacitated, this system initiates the braking process. This reduces the risk of colliding with further obstacles and road users after the initial collision. The driver can intervene and operate the accelerator or brake pedal manually throughout the entire process.)
- Tire repair kit (for use at a maximum speed of 80 km/h)
- Tire Pressure Monitoring System (TMPS)
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Electro-mechanical speed-dependent power steering (EPAS - Electric Power Assisted Steering)

- Headlight assistant with day/night sensor
- Selective driving mode switch (including 3 selectable driving modes: Normal, Sport and Eco)
- Seats: Passenger seat, 2-way adjustable
- Seats: Driver's seat height adjustable (with manually adjustable lumbar support)
- Seats: Front sports seats with enhanced lateral support
- Start-stop system
- 12-volt socket
- Phone accessories: Inductive charging station for mobile devices (according to Qi standard, compatibility depends on the device)
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release
- Seats: Rear seat backrest (foldable, 60:40 split with ski pass-through)
- Sport body kit (ST-Line design grille - front and rear bumpers, ST-Line design side skirts, painted in body color)
- Carpet floor mats front and rear, velour
- Black trim around the side windows
- 2 USB ports in the center console, rear
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

Extra equipment

- Detachable towbar (including ESP trailer stabilization)
- Head-up display
- Paint finish: Fantastic Red Metallic
- Package: Easy Parking (Active Parking Assist with parking and exiting function (in conjunction with 8-speed automatic transmission including semi-automated vehicle guidance) - Door edge protection - Rearview camera with "Split View" technology)
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Wheels: Emergency spare wheel (permitted for use up to max. 80 km/h - steel wheel 3.5 J x 16 with 125/70 R16 tire)
- Tires: 4 all-season tires
- Tailgate, electric and sensor-controlled (opening and closing via foot movement)
- Package: Driver Assistance Package (for automatic transmission) (Drive Assist, Intelligent Adaptive Cruise Control, Lane Keeping Assist, Traffic Jam Assist with Stop&Go function, Traffic Sign Recognition System, Wrong-Way Driver Warning, Evasive Steering Assist, Distance Display and Distance Warning, High Beam Assist (in conjunction with adaptive LED matrix headlights with glare-free high beam assist), Blind Spot Assist with Cross Traffic Alert including emergency braking function (when reversing out of parking spaces) and trailer detection, Rearview camera with split view)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Door - front right side	Door (Polieren) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Das Fahrzeug weißt eine erhöhte Lackdichte auf

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Damage 1: Front bumper: Front bumper - Scratched - Paint



Damage 1: Front bumper: Front bumper - Scratched - Paint




Damage 1: Front bumper: Front bumper - Scratched - Paint



Damage 1: Front bumper: Front bumper - Scratched - Paint



Wear and tear 1: Door - front right side: Door (Polieren) - Scratch(es) - No deduction



Wear and tear 1: Door - front right side: Door (Polieren) - Scratch(es) - No deduction