TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48467942
Order No. / Reference: 27165474
Inspection date: 3 Nov 2026

Manufacturer: Mercedes-Benz	Model: E 220 d Cabrio 9G-TRONIC AMG Line
VIN: W1K1K1EB1PF209257	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 220 d Cabrio 9G-TRONIC AMG Line	
Vehicle Identification number	W1K1K1EB1PF209257
Mileage (Read)	44,773 km
First registration	9 Oct 2023
Number of holders	1
Next periodical technical inspection	10/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	143 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Convertible / Roadster
Colour / colour code	Polarweiß
Doors / Seats	2 / 4
Upholstery type	Leather
Colour of upholstery	Brown
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11 Tag(e)
Last service on / at	10/2025 at 35,996 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY501280
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / AFO 00178		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,380 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95Y	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	275/30 R20 97Y	Summer tyres on Light alloy	Goodyear	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R19 98V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/40 R19 98V	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- AMG floor mats in black with AMG lettering
- Anti-lock braking system (ABS)
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Diesel particulate filter
- Third brake light
- Electronic Stability Program (ESP)
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Black fabric headliner
- KEYLESS-GO start function
- Communication module (LTE) for the use of Mercedes me connect services
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: AMG Line Exterior
- Upholstery: ARTICO leatherette/DINAMICA microfiber
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Windscreen wipers with rain sensor
- Service interval indicator ASSYST
- Seats: i-Size child restraint system
- Cruise control
- High-visibility vest for drivers
- Electronic immobilizer
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Ambient lighting with 64 colors and 3 light zones
- AMG sports pedal assembly made of brushed stainless steel with black rubber studs
- ATTENTION ASSIST
- Exterior mirror housings with integrated ambient lighting
- Basic services
- Brake system with larger brake discs on the front axle
- Tachometer
- DYNAMIC SELECT
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Transmission: 9-speed automatic, 9G-TRONIC
- Interior lighting
- THERMATIC automatic climate control
- Headrests (4)
- Paint finish: Solid
- Steering wheel: Multifunction sports steering wheel in Nappa leather
- Steering: Direct steering
- Center console piano black finish
- Navigation: Hard disk navigation
- Package: Storage
- Package: Seating comfort
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Touchpad with controller
- Trip computer and on-board computer
- Wheels: 48.3 cm (19") AMG light-alloy wheels in a 5-twin-spoke design, painted tantalum grey
- Seats: Rear seat backrests foldable, 50/50 split
- Power outlets: 2 USB ports in the rear
- Convertible top: black fabric convertible top
- Maintenance interval indicator "ASSYST"
- Decorative elements: aluminum with longitudinal brushing, light finish

Extra equipment

- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - 66-Liter Fuel Tank)
- Package: Parking package with reversing camera (The parking package with reversing camera makes finding and selecting parking spaces, as well as parking in and out of parallel and perpendicular parking spaces or garages, easier. The active parking assistant steers the vehicle into parking spaces - in conjunction with automatic transmission including cruise control and automatic gear shifting.)
- Upholstery: Two-tone, sun-reflecting leather (instrument panel top and trim in ARTICO imitation leather with decorative stitching)
- Seats: Seat heating for driver and front passenger (3 different heating levels can be individually selected for each seat at the touch of a button)
- Decorative elements in open-pore black ash wood (including center console in open-pore black ash wood)
- Package: Convertible Comfort (AIRCAP - AIRSCARF - Fully electric trunk partition)
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC incl. Active Speed Limit Assist, Extended Automatic Restart on Highways, Route-Based Speed Adaptation with Traffic Jam Function (only when selecting Parking Packages), Active Steering Assist incl. Active Emergency Stop Assist with SOS Function, Emergency Lane Radio, Active Brake Assist incl. Turning and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist incl. Exit Warning, Pedestrian Warning Radio, PRE-SAFE PLUS)
- Package: Mirror package (interior and exterior mirrors on the driver's side automatically dimming - exterior mirrors left and right electrically folding - ambient lighting in the exterior mirrors)
- Wheels: 50.8 cm (20") AMG multi-spoke light-alloy wheels, painted in Himalayan grey (gloss-turned front axle: 8 J x 20 ET 43, tire size 245/35 R 20 rear axle: 9 J x 20 ET 49, tire size 275/30 R 20 - including run-flat tires)
- Wind deflector (foldable, including protective cover for mounting behind the front seats)
- Winter complete wheels M+S 4-way

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
2	Sill - left side	Trim - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - rear left side - Paint defect - Loss in value
4	Misc.	Main inspection - Due - Perform
5	Seat - rear	Upholstery (Abdrücke) - Deformed - Loss in value
6	Seat - rear	Armrest - centre (Vorne Preis nicht gefunden) - Deformed - Replace
7	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint
8	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
9	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Body	Body - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
2nd wheel set - Wheel cover set - complete (Nabenkappen)

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 7 Mar 2025	3.142,86 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

2. Radsatz lag im Fhzg., dadurch die Beschädigung an der Armlehne.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Convertible with open roof



Figure 6: Interior - front



Figure 7: Interior - rear



Figure 8: Instrument cluster



Figure 9: Instrument panel



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Sill - left side: Trim - Scratch(es) - Smart repair



Damage 2: Sill - left side: Trim - Scratch(es) - Smart repair



Damage 2: Sill - left side: Trim - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - rear left side - Paint defect - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear left side - Paint defect - Loss in value



Damage 5: Seat - rear: Upholstery (Abdrücke) - Deformed - Loss in value



Damage 5: Seat - rear: Upholstery (Abdrücke) - Deformed - Loss in value



Damage 6: Seat - rear: Armrest - centre (Vorne Preis nicht gefunden) - Deformed - Replace



Damage 6: Seat - rear: Armrest - centre (Vorne Preis nicht gefunden) - Deformed - Replace



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 7: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Repair and paint



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace




Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Previous damage 1: Rear

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Previous damage 1: Rear