SCHIPPER VAASEN
AUTOMOTIVE SERVICES

Technician
Bas Vaasen

2-FXL-854

2-FXL-854 · Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT / · 4 November 2026 · Zaventem Brussel

Specifications

License Plate Number	2-FXL-854
Manufacturer	TOYOTA
Model	Corolla Cross
Model Versions	Cross 1.8 Hybrid Safety Pack DYNAMIC 1.8 140PS AT /
Body Type	5 door hatchback
Color	Silver
Paint Type	Metallic
Production Year	2024
KW	103
Fuel Type	Hybrid Gasoline

VIN	JTNADADB90J022126
Cylinder Capacity	2 cm3
Transmission Type	Automatisch geschakelde Transmissie
First Admission	26-09-2024
First Registration	26-09-2024
Odometer	94.701 Km
Numer Of Keys	2
Interior	Black – Cloth
Number Headrests	5

Images































UNIROYAL

UNIROYAL

UNIROYAL


Accessories

ABS	Cruise control
Airbags	Electric rear windows
Alloy wheels	Electric windows front
ASR	Electrically adjustable exterior mirrors
Audio System	Leather steering wheel
Automatic air conditioning	Parking sensors
Bluetooth car kit	Rear view camera
Central door locking	Steering wheel multifunction
Centre armrest	

Condition

Condition exterior	Adequate	Last Maintenance	Unknown
Condition interior	Adequate	Previous Repairs	Unknown

Tire Specifications

Tire	Profile	Brand	Width	Aspect Ratio	Radial	Type
Front Left	2 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Left	4 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Front Right	2 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Rear Right	4 mm	UniRoyal	215 mm	60 mm	17 inch	All Season
Spare Tire Type	Homecomer					

Notes

Rolhoes manco

Damages




Damage Part	Damage Type	Repair Type	Acceptable
Trunkshelf	Missing	Replace	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Touch-up / Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Right	Scratch(es)	Panelbeating & Spotrepair	No







Damage Part	Damage Type	Repair Type	Acceptable
Reardoor – Right	Dent(s) & Scratch(es)	Panelbeating & Spray	No




Damage Part	Damage Type	Repair Type	Acceptable
Mirror - Rightside	Small scratch(es)	Acceptable	Yes




Damage Part	Damage Type	Repair Type	Acceptable
Bumper – Front	Small scratch(es)	Touch-up / Polish	No




Damage Part	Damage Type	Repair Type	Acceptable
Frontdoor – Left	Small scratch(es)	Acceptable	Yes



Damage Part	Damage Type	Repair Type	Acceptable
Rear seat	Stains & dirt	Cleaning	No




Damage Part	Damage Type	Repair Type	Acceptable
Fender – Rear Left	Small dent(s)	Restyle	No








Damage Part	Damage Type	Repair Type	Acceptable
Hood	small dents / small scratches	Panelbeating & Spray	No



Damage Part	Damage Type	Notes	Repair Type	Acceptable
Roof	Small dent(s)	circa 5 deukjes	Restyle	No