TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48476010
Order No. / Reference: 27228731
Inspection date: 2 Nov 2026

Manufacturer: Renault	Model: Master dCi 135 L2H2 VA Basis Kasten
VIN: VF1MA000967896490	





Vehicle details

Manufacturer / Type / Model / Equipment	
Renault Master dCi 135 L2H2 VA Basis Kasten	
Vehicle Identification number	VF1MA000967896490
Mileage (Read)	62,380 km
First registration	13 Oct 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	2,299 ccm / 4
Power	100 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Mineral-Weiß
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	19,800 km
Last service on / at	08/2025 at 43,539 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC990560
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	3333 / BCZ 02024		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R16 112R	All-season tyres on Steel rim with wheel cover	Pirelli	5mm / 4mm
2)	225/65 R16 112T	All-season tyres on Steel rim with wheel cover	Continental	3mm / 2mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS with EBV and brake assist (with automatic activation of the hazard warning lights during emergency braking)
- Exterior mirrors, electrically adjustable and heated
- third brake light
- Easy-Life work surface - elimination
- electric front windows
- Chrome-plated front grille surround
- Glove compartment, closed
- Headrests (3) (height adjustable)
- Paint finish: Solid
- Height-adjustable steering wheel
- Alternator 230 A
- Upholstery: Fabric "Kaleido"
- Tire repair kit (incl. 12V compressor & tire sealant)
- Wheels: Steel rim 16"
- Key: 3-button key with radio remote control
- Power steering
- Seats: Driver's seat height adjustable (with center armrest)
- Seats: Driver's seat, height-adjustable (with integrated armrest)
- Electronic immobilizer
- Airbag: Driver's side
- Automatic door locking after starting to drive
- On-board computer
- Tachometer
- ESP with load detection (traction control (ASR) - hill start assist - trailer stabilization)
- Transmission: 6-speed manual transmission
- Rear door, opening angle 180°, without window
- Fuel tank 105 liters
- LED daytime running lights
- Light and rain sensor
- Pollen filter
- Wheel cover (Mini)
- Self-cleaning diesel particulate filter
- Sliding door on the right, closed
- Crosswind assist
- Seats: Double passenger seat (multifunctional) (with fold-down backrest in the middle of the work surface)
- 12V power outlet on the dashboard
- Lashing eyes in the cargo area floor
- Central locking (including automatic door locking after driving off)

Extra equipment

- Easy-Life drawer
- Wooden floor in the cargo area
- Air conditioning
- Retrofitting radio + hands-free system
- Package: Comfort Package with rear and front parking aid (cruise pilot with speed limiter - rear and front parking aid - one-touch function for electric windows on driver's side - blind spot warning - height-adjustable driver's seat with integrated center armrest and lumbar support)
- Package: Mobile Office Package (Easy-Life drawer - storage compartment under the passenger double seat - Deluxe Package - closed storage compartment centrally on the dashboard - Easy-Life work surface)
- Seats: sprung driver's seat (with lumbar support and center armrest - 4-way adjustable)
- Cruise control including speed limiter
- Lashing eyes, located on the side of the cargo area
- Rear and front parking assist
- Wooden cladding of the side walls (complete)
- LED lighting in the cargo area
- Package: Deluxe package (chrome elements on the air vents and gearshift knob)
- Package: Cargo area protection package (wooden paneling of the side walls up to the roof - wooden floor in the cargo area - lashing eyes in the cargo area walls - LED lighting in the cargo area)
- Radio pre-wiring including 2 speakers
- Tires: All-season tires
- Seat: Lumbar support for driver's seat
- Seats: Double passenger seat (multifunctional) (with fold-down backrest in the middle of the work surface - additionally with storage compartment)
- Blind spot warning system

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Door - front left side	Door - dent(s) - Smooth repair work
3	Trim / covers	Trim / covers - Missing - Replace
4	Sill - right side	Sill - dent(s) - Smart repair
5	Sill - left side	Sill - dent(s) - Smart repair
6	Seat - front	Seat cover - left side - Broken / torn - Smart repair
7	Tail light	Auxiliary brake light - Broken / torn - Replace
8	Wheel / tyres	Tyre - rear left side - Broken / torn - Replace
9	Wheel / tyres	Tyre - rear right side - Broken / torn - Replace
10	Boot lid / rear door	Rear door - right side - Dent / paintcoat damage - Loss in value
11	Engine	Engine cover - Damage caused by marten / rodent - Replace
12	Bonnet	Bonnet - Dent / paintcoat damage - Smart repair
13	Interior	Interior - Soiled - Loss in value
14	Front bumper	Front bumper - Scratched - Replace
15	Vehicle glazing	Windscreen - Scratch(es) - Replace
16	Roof	Roof - Corrosion - Repair and paint
17	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint

Wear and tear

No.	Component group	Description
1	Interior	Interior - Dent / paintcoat damage - No deduction
2	Boot lid / rear door	Rear door - left side - dent(s) - No deduction
3	Rear bumper	Rear bumper (unpainted) - Scratch(es) - No deduction
4	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	183 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.



Damage 2: Door - front left side: Door - dent(s) - Smooth repair work



Damage 2: Door - front left side: Door - dent(s) - Smooth repair work



Damage 2: Door - front left side: Door - dent(s) - Smooth repair work



Damage 3: Trim / covers: Trim / covers - Missing - Replace



Damage 4: Sill - right side: Sill - dent(s) - Smart repair




Damage 4: Sill - right side: Sill - dent(s) - Smart repair



Damage 5: Sill - left side: Sill - dent(s) - Smart repair



Damage 5: Sill - left side: Sill - dent(s) - Smart repair



Damage 6: Seat - front: Seat cover - left side - Broken / torn - Smart repair



Damage 6: Seat - front: Seat cover - left side - Broken / torn - Smart repair



Damage 7: Tail light: Auxiliary brake light - Broken / torn - Replace



Damage 7: Tail light: Auxiliary brake light - Broken / torn - Replace



Damage 8: Wheel / tyres: Tyre - rear left side - Broken / torn - Replace



Damage 8: Wheel / tyres: Tyre - rear left side - Broken / torn - Replace



Damage 9: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace




Damage 9: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 9: Wheel / tyres: Tyre - rear right side - Broken / torn - Replace



Damage 10: Boot lid / rear door: Rear door - right side - Dent / paintcoat damage - Loss in value



Damage 11: Engine: Engine cover - Damage caused by marten / rodent - Replace



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 12: Bonnet: Bonnet - Dent / paintcoat damage - Smart repair



Damage 13: Interior: Interior - Soiled - Loss in value



Damage 14: Front bumper: Front bumper - Scratched - Replace



Damage 14: Front bumper: Front bumper - Scratched - Replace



Damage 14: Front bumper: Front bumper - Scratched - Replace



Damage 14: Front bumper: Front bumper - Scratched - Replace



Damage 14: Front bumper: Front bumper - Scratched - Replace



Damage 15: Vehicle glazing: Windscreen - Scratch(es) - Replace



Damage 15: Vehicle glazing: Windscreen - Scratch(es) - Replace




Damage 15: Vehicle glazing: Windscreen - Scratch(es) - Replace



Damage 16: Roof: Roof - Corrosion - Repair and paint



Damage 16: Roof: Roof - Corrosion - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 17: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Wear and tear 1: Interior: Interior - Dent / paintcoat damage - No deduction



Wear and tear 1: Interior: Interior - Dent / paintcoat damage - No deduction



Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side