BMW

VIN: WBA81CY05RFT47014

Estimated repair cost

568.50 EUR
TOTAL



Description

Registration number 2HRF069	**First registration date** -	**Odometer** 26512 km
Color -	**Model year** -	**Upholstery** -
Number of doors -	**Number of seats** -	**Generation** -

Statement details

Inspection loc
PARC LIZY

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction	net cost
001	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 18 " / Surface : Diamond cut	Scratched	Smart repair	225.00 EUR



Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	225.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
002	Bumper / Front Painted : Yes	Scratched	Painting	303.50 EUR



Bodywork time	Paint time	Part Price	Lumpsum
2.80 h	1.10 h	-	-
Bodywork cost	**Paint cost**	**MaterialCost**	
210.00 EUR	93.50 EUR	-	

#	Element	Defect	Correction	net cost
003	Document holder / -	Missing	Replace	20.00 EUR

Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	20.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

#	Element	Defect	Correction	net cost
004	User manual / -	Missing	Replace	20.00 EUR

Bodywork time	Paint time	Part Price	Lumpsum
-	-	-	20.00 EUR
Bodywork cost	**Paint cost**	**MaterialCost**	
-	-	-	

Loose Items

- [x] Quick charging cable (Type 2, Mode 3)
- [x] First aid kit
- [x] Rear parcel shelf
- [ ] Document holder
- [x] Registration certificate owner
- [x] Registration certificate
- [x] Triangle
- [ ] User manual
- [x] Spare Key

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Main set of tyres

Front Left	HANKOOK	225/45/18 95 Y All-season	6 mm
Front Right	HANKOOK	225/45/18 95 Y All-season	6 mm
Back Left	HANKOOK	225/45/18 95 Y All-season	6 mm
Back Right	HANKOOK	225/45/18 95 Y All-season	6 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures



Front left



Rear left



Boot opened



Rear right



Rear passenger compartment



Dashboard from rear seat



Front passenger compartment



Front right




Odometer



Cable



Vin



Other

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched



Bumper / Front / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.