ARVAL
BNP PARIBAS GROUP

2CVQ934

INSPECTION REPORT

End of contract

GENERAL INFO

File	323166
License plate	2CVQ934
Vehicle identification number	WBY41DU080S581086
Dossier	2022 020 043
Make	BMW iX3
Mileage	99323
First registration	13/12/2022
client availability date	29/09/2026
inspectionDate	29/09/2026
File	323166
License plate	2CVQ934
Vehicle identification number	WBY41DU080S581086
Dossier	2022 020 043
Make	BMW iX3
Mileage	99323
First registration	13/12/2022
client availability date	29/09/2026
inspectionDate	29/09/2026









CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	








BELCAR

DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
258	Towing Cover Rear // Replace	N
283	Bumper Rear / Trim Right / Replace	N
31	Front Bonnet // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
202	Rocker Panel Right // Painting	Y
314	Wheel Front Left / Wheel Cover / Replace	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures




Wheel Two Tone Rear Left // Repair-scratch




Rocker Panel Right // Painting-scratch





Wheel Two Tone Rear Right // Repair-scratch




Wheel Front Left / Wheel Cover / Replace-scratch




Rear Left Door Interior Coating // Replace Completely-scratch





Front Bonnet // Smart Repair Small-dent




Door Rear Left // Smart Repair Small-dent



Towing Cover Rear // Replace-scratch





Bumper Rear // Painting-scratch





Bumper Rear / Trim Right / Replace-cracked