TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48163979
Order No. / Reference: 27162824
Inspection date: 15 Oct 2026

Manufacturer: Volkswagen	Model: Transporter T6.1 DSG Kurz
VIN: WV1ZZZ7HZMX011860	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Transporter T6.1 DSG Kurz	
Vehicle Identification number	WV1ZZZ7HZMX011860
Mileage (Read)	42,921 km
First registration	28 Apr 2021
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	14,100 km
Last service on / at	03/2025 at 32,444 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA692829
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / BXU 57204		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,800 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	Hankook	5mm / 5mm
2)	205/65 R16 107T	Summer tyres on Steel rim with wheel cover	unterschiedliche Hersteller	5mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/65 R16 107T	Winter tyres on Light alloy	Bridgestone	5mm / 5mm
2)	205/65 R16 107T	Winter tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	205/65 R16 107T	Summer tyres on Steel	Hankook	6 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments and boxes (glove compartment with lockable flap)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors, left and right convex
- Floor coverings: Rubber floor covering in the driver's cab
- Tachometer
- Chassis: 16" chassis with 16" brake system
- Electric windows, front
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Heating system with electronic control
- Headrests (2)
- Headlight range control
- Non-smoking version (12V socket and cup holder in the dashboard)
- Upholstery: Seat covers in fabric, "Double Grid" design
- Radio: Digital radio reception (DAB+)
- Radio accessories: 2 speakers (wideband)
- Wheels/Tires: Steel wheels 6.5 J x 16 in 20-hole design
- Wheels/Tire Accessories: Wheel covers for 16" wheels
- Keys for locking system: 2 remote control flip keys
- Crosswind assist
- Seat belts: Three-point automatic seat belts (height-adjustable on the outer seats in the driver's cab)
- Daytime running lights (continuously switched on while driving)
- Lashing eyes for securing cargo
- Green thermal insulation glazing
- Additional heater
- Airbag for driver and front passenger (with front passenger airbag deactivation - seat belt tensioners for the outer seats)
- Hill Start Assist
- third brake light
- Electronic Stability Program (including ABS, ASR, EDS, Hill Start Assist, Brake Assist)
- Fresh air system with multi-stage fresh air blower (recirculation flap, center vents and defroster nozzles)
- Tailgate without window
- Child safety lock, electrically operated
- Paint finish: Solid
- Multi-collision brake
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- "Composition Audio" radio with TFT display (monochrome) (USB interface, Bluetooth interface)
- Wheels/Tires: 205/65 R 16 C 107/105 T, optimized for low rolling resistance
- Sliding door in the passenger/cargo compartment: sliding door on the right
- Electromechanical power steering (speed-dependent control, steering column height and length adjustable)
- Start-stop system (with brake energy recuperation)
- Telephone: Mobile phone interface
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Registration as a truck

Extra equipment

- Airbag: Side and head airbags for driver and front passenger
- Ventilation
- Driver assistance systems: Rearview camera "Rear View" ((static lines))
- Fire extinguisher
- Glove compartment with light
- Luggage ramp
- Fuel tank with 80 l tank capacity
- Multifunction display: Digital cockpit and fatigue detection
- Fog lights including cornering lights
- Package: Comfort Package Plus (2 12-volt sockets, air conditioning in the driver's cab with electronic control, fabric seat covers, "Bricks" design, 1 waste bin for the door pockets in the driver's cab, additional soundproofing measures in the driver's cab, height adjustment for the left single seat in the driver's cab, glove compartment lid with light, foldable grab handle on the roof frame on the passenger side, storage compartments on the driver's cab seats, reading light, sun visors with mirrors (front/rear), grab handle (front/rear), manual lumbar support for the left single seat in the 1st row of seats)
- Package: Winter package (laminated glass windshield, heated - heated windshield washer nozzles at the front and washer fluid level indicator)
- ParkPilot in the front and rear areas
- Radio navigation system "Discover Media" including "Streaming & Internet" (voice control - 2 USB interfaces (Type C) in the dashboard - "Discover Media" radio navigation system with 20.3 cm (8 inch) touchscreen including "Streaming and Internet" - navigation function/ preparation - 4 speakers: 2 tweeters, 2 woofers - Wired & Wireless App-Connect)
- Seat configuration - 4. Lumbar support: Lumbar support, left and right, manually adjustable for individual use.
- Power outlets: 2 12-volt sockets in the dashboard
- Exterior mirrors, electrically adjustable, heated and folding (including folding function via vehicle key)
- Floor coverings: Universal floor in the passenger/cargo area (Universal floor in the cargo area with loading edge protection, rear - step lighting in the passenger/cargo area)
- Total weight: Permissible total weight 3.2 t with reinforced 16" steel wheels (4 steel wheels 6.5 J x 16 - Permissible total weight 3,200 kg - Suspension and damping, for vehicles with 3.2 t permissible total weight - On-board tools and jack, reinforced, for vehicles with 3.2 t GVW)
- Package: Driver Assistance Package Plus DSG (Traffic sign recognition, multifunction leather steering wheel, safety interior mirror with integrated display, "Front Assist" area monitoring system with City Emergency Braking function, electrically adjustable, heated, and folding exterior mirrors including folding function via vehicle key, "Lane Assist" lane keeping assistant, "Side Assist" lane change assistant, "Parking Assist", "Light Assist" high beam control, daytime running lights with automatic headlight control, windscreen wipers with automatic distance control (ACC) with "follow to stop", speed limiter).
- Package: Transport package (Preparation for trailer hitch (incl. trailer stabilization) - Partition wall, high - Without child safety lock in the passenger compartment - Side interior paneling in the load compartment (up to the roof frame) made of plywood - Lashing eyes for load securing, reinforced (ISO 27956) - C-rails on side wall)
- Tire pressure monitoring system
- Wheels/Tires: Spare wheel (steel rim) with driving tires
- Heated seats for the driver's cab, left and right, separately adjustable
- Seat configuration - 3. Seat settings: Height adjustment for left and right single seat in the driver's cab
- Seat configuration - 5. Armrests: Armrests for both seats in the driver's cab
- Lashing rails on the side walls and partition

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover - front right side - Missing - Replace
2	Door - front left side	Door - Scratch(es) - Smart repair
3	Body	A-pillar - left side - Scratch(es) - Smart repair
4	Wing mirror - left side	Cap - Scratch(es) - Replace
5	Wing mirror - right side	Cap - Broken / torn - Replace
6	Trim / covers	Trim / covers - Broken / torn - Replace
7	Tail light	Tail lamp - left side - Scratch(es) - Replace
8	Interior	Interior - Dent / paintcoat damage - Loss in value
9	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Replace
10	Boot lid / rear door	Boot lid - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Roof	Roof - Dent / paintcoat damage - No deduction
3	Door - front right side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Damage 1: Wheel / tyres: Wheel cover - front right side - Missing - Replace



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door - Scratch(es) - Smart repair



Damage 3: Body: A-pillar - left side - Scratch(es) - Smart repair



Damage 3: Body: A-pillar - left side - Scratch(es) - Smart repair



Damage 4: Wing mirror - left side: Cap - Scratch(es) - Replace




Damage 4: Wing mirror - left side: Cap - Scratch(es) - Replace



Damage 5: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 5: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 5: Wing mirror - right side: Cap - Broken / torn - Replace



Damage 6: Trim / covers: Trim / covers - Broken / torn - Replace



Damage 7: Tail light: Tail lamp - left side - Scratch(es) - Replace



Damage 7: Tail light: Tail lamp - left side - Scratch(es) - Replace



Damage 8: Interior: Interior - Dent / paintcoat damage - Loss in value



Damage 8: Interior: Interior - Dent / paintcoat damage - Loss in value



Damage 9: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 9: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Replace



Damage 10: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 10: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 10: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Damage 10: Boot lid / rear door: Boot lid - Dent / paintcoat damage - Paint



Accident 1: Side right



Accident 1: Side right




Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Accident 1: Side right



Accident 1: Side right