BMW X2

Vehicle information

Brand:	**BMW**	License plate:	**2BUQ121**
Gearbox:		Body color:	
Model:	**X2**	LEVEL:	**WBAYK510705V08457**
Fuel type:		Power:	**100 kW**
Version:	**2.0 SDRIVE18D AUTO 100KW**	First registration	**29/03/2022**
Mileage:	**112427 km**	Number of doors:	

Summary of damages

RIGHT	2
LEFT	1
Interior	2
Roof & other	1

Commercial photos

























Options according to the inspector

GPS	**Yes**


Damages

Bodywork


Damaged -




Acceptable.

Roof & other


















Damaged **Interior**
- Acceptable
Interior








Polished front left alloy wheel
with scratches
on the left - Repair and paint (complete
)







Right **rear door**
- Dent(s) and scratch(es)
- Repair and paint (complete)









Front Right **Door Dent**
(s)
- Repair and Paint (Complete)





ARG seat upholstery, Smart repair
tear , interior





Tires

Front Left
Summer
Aluminum
225/50/18/99/W
Pirelli
5.0 mm
Front Right
Summer
Aluminum
225/50/18/99/W
Pirelli
3.0 mm
Left Back
Summer
Aluminum
225/50/18/99/W
Continental
5.0 mm
Rear Right
Summer
Aluminum
225/50/18/99/W
Continental
5.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Vehicle inspection	**OK**
Vehicle inspection	**20/01/2028**	Jack	**Yes**
Interview	**OK**	Interview	**Engine oil 2500 km, Brake fluid 01/2027**
Galette	**Yes**	Repair kit	**P/A**
Number of charging cables (220V)	**0**	Number of charging cables (fast charging)	**0**
Total number of keys	**2**	Charge level	**20**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Type of maintenance log	**Digital interview**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.