TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48573431
Order No. / Reference: 27259080
Inspection date: 9 Nov 2026

Manufacturer: Opel	Model: Astra Sports Tourer 1.5 D Business Edition
VIN: VXKFCYHZLP1052750	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Astra Sports Tourer 1.5 D Business Edition	
Vehicle Identification number	VXKFCYHZLP1052750
Mileage (Read)	74,863 km
First registration	25 Oct 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Arktisweiß
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	24,200 km
Last service on / at	08/2026 at 69,138 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS873269
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AEY 00084		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,960 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Continental	6mm / 6mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 94V	Summer tyres on Light alloy	Michelin	6mm / 6mm
2)	205/55 R16 94V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 180-degree reversing camera
- Airbag: Chest-pelvis-side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and manually folding
- On-board computer
- Roof design line, in black
- Tachometer
- Electronic brake force distribution (EBD)
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Back window, heater
- Cable set for trailer hitch
- Front headrests and 3 rear headrests, height adjustable
- LED interior lighting
- Steering wheel: Leather steering wheel, flat-bottomed, with steering wheel remote control
- Multimedia infotainment system
- Opel Vizor with chrome frame
- Parkpilot, front and rear parking aid
- Tire pressure monitoring system
- Rear seat backrest folds forward in a 40:20:40 split
- Seat belts: Three-point seat belts in all seats
- Solar Protect thermal insulation glazing
- 12V power outlet in the center console
- Electronic immobilizer
- Storage compartments
- Airbag: Front airbags, driver and front passenger
- Airbag: Front and rear outer head airbags
- Automatic activation of the hazard warning lights
- Exterior mirror housings in black
- Hill Start Assist
- third brake light
- Diesel particulate filter (DPF) maintenance-free
- Eco Coaching: Upshift recommendation via display in the driver information display
- Electric windows front and rear
- Transmission: 6-speed manual transmission
- rear window wiper
- automatic climate control
- Paintwork: Roof in car color
- LED headlights
- Illuminated makeup mirrors in both sun visors
- Center armrest, front and rear
- Fog light
- Electric parking brake
- Tire repair kit
- Wheels: Alloy wheels 7 J x 16 (5 double spokes) in silver
- Keyless Start system
- Seats: Ergonomic active driver's seat, Modene fabric
- Start/Stop System
- Pre-wiring for ISOFIX child seat mounting system
- Central locking with remote control

Extra equipment

- Front Collision Warning (with automatic emergency braking, pedestrian detection, lane keeping assist, traffic sign recognition and driver drowsiness detection as well as automatic speed assist)
- Paint finish: Solid
- safety net
- Wheels: Winter tires 205/55R16 on LMF
- Navigation system (Multimedia infotainment system with 10" color touchscreen display and 10" driver information display; navigation system with integrated memory; 3D map display for Europe and Russia; dynamic route guidance via map and/or arrow display and voice prompts; TomTom Online Traffic; online POI search and route guidance; parking information; fuel price information; live weather; over-the-air map updates; intelligent voice control; "Hey Opel" shortcut button; 6 functions; active route suggestions)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Boot lid / rear door	Boot lid - Glued / labelled - De-glue / neutralise
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Door - front left side	Window guide - Scratch(es) - Loss in value
5	Rear bumper	Rear bumper - Scratch(es) - Smart repair
6	Engine	Engine cover - Damage caused by marten / rodent - Replace
7	Vehicle glazing	Windscreen (Zierleiste links) - Scratch(es) - Replace
8	Door - front left side	Door seal - Broken / torn - Replace
9	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Scratched - Replace
10	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
11	Sill - right side	Sill - Deformed - Repair and paint
12	Bonnet	Bonnet - Scratch(es) - Paint
13	Front bumper	Front bumper - Stone chips - Paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Winterradsatz abweichend Auslieferung-ist höherwertig.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Damage 1: Boot lid / rear door: Boot lid - Glued / labelled - De-glue / neutralise



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Door - front left side: Window guide - Scratch(es) - Loss in value



Damage 4: Door - front left side: Window guide - Scratch(es) - Loss in value



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 6: Engine: Engine cover - Damage caused by marten / rodent - Replace




Damage 7: Vehicle glazing: Windscreen (Zierleiste links) - Scratch(es) - Replace



Damage 7: Vehicle glazing: Windscreen (Zierleiste links) - Scratch(es) - Replace



Damage 8: Door - front left side: Door seal - Broken / torn - Replace



Damage 8: Door - front left side: Door seal - Broken / torn - Replace



Damage 9: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 9: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 10: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 11: Sill - right side: Sill - Deformed - Repair and paint




Damage 11: Sill - right side: Sill - Deformed - Repair and paint




Damage 11: Sill - right side: Sill - Deformed - Repair and paint



Damage 12: Bonnet: Bonnet - Scratch(es) - Paint



Damage 12: Bonnet: Bonnet - Scratch(es) - Paint



Damage 13: Front bumper: Front bumper - Stone chips - Paint



Damage 13: Front bumper: Front bumper - Stone chips - Paint



Damage 13: Front bumper: Front bumper - Stone chips - Paint