TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48228774
Order No. / Reference: 27118562
Inspection date: 20 Oct 2026

Manufacturer: Audi	Model: A5 Sportback 40 TFSI quattro S tronic advanced
VIN: WAUZZZF56PA003104	





Vehicle details

Manufacturer / Type / Model / Equipment

Audi A5 Sportback 40 TFSI quattro S tronic advanced

Vehicle Identification number	WAUZZZF56PA003104
Mileage (Read)	115,111 km
First registration	21 Jul 2022
Number of holders	1
Next periodical technical inspection	07/2027
(Report on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,984 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Car hatchback
Colour / colour code	Manhattangrau Metallic
Doors / Seats	5 / 4
Upholstery type	Artificial leather
Colour of upholstery	Black-Brown
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,200 km
Last service on / at	08/2026 at 110,663 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM607419
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BUT 00386		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,160 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R19 96Y	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	255/35 R19 96Y	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/40 R18 97V	Winter tyres on Light alloy	Pirelli	4mm / 4mm
2)	245/40 R18 97V	Winter tyres on Light alloy	Pirelli	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Accent areas matte black
- Anti-lock braking system (ABS)
- Audi connect emergency call & service including vehicle control
- Electrically adjustable/heated exterior mirrors
- Outdoor temperature display
- Fabric headliner
- Tachometer
- Door sill trims with aluminum inlay
- Electronic Stability Control (ESC)
- Chassis: Standard chassis
- Remote key, without safe lock
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic (7-speed)
- Interior mirror dimming
- ISOFIX and Top Tether child seat anchors for the outer rear seats
- Headrests (4)
- LED taillights
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Non-smoking version
- Package Gloss
- Wheel: Alloy wheels "5-V-spoke Y-design"
- Wheel: Tire repair kit
- Radio: MMI Radio Plus
- Radio accessories: Data module Europe
- Electromechanical power steering
- Front seats (standard seats)
- Phone: Bluetooth interface
- Glazing: Windscreen in heat-insulating and acoustic glazing
- Airbag: Front side airbags and head airbag system
- "quattro" all-wheel drive with ultra technology
- Drive slip control
- Audi drive select
- Audi pre sense city
- Exterior mirror housings in body color
- third brake light
- Decorative inlays diamond lacquer silver grey
- Rear parking sensors
- Electromechanical parking brake
- Driver information system
- Electric front windows
- front and rear floor mats
- Cruise control system with adjustable speed limiter
- Interior lighting
- Manual child lock
- Automatic air conditioning
- boot floor mat
- Fuel tank (58 liters)
- LED headlights
- Mild hybrid
- front center armrest
- Otto particulate filter
- Upholstery: Fabric finish Index
- Wheel: Tire pressure monitoring system
- Wheel: Tires optimized for rolling resistance, speed-limited
- Radio accessories: 8 speakers
- Rear seat backrest foldable
- Seat belts: Three-point automatic seat belts for all seats
- Start-stop system
- First aid kit with warning triangle
- Electronic immobilizer
- Green thermal insulation glazing

Extra equipment

- Black fabric headliner
- Comfort key with sensor-controlled luggage compartment unlocking (wireless communication between the key and the vehicle allows opening the doors and luggage compartment lid, and locking via the sensors on the door handles. The comfort key simply needs to be carried with the vehicle. The engine is started and stopped using the engine start/stop button. The luggage compartment lid can also be conveniently unlocked with a foot gesture by kicking the rear of the vehicle if your hands are full.)
- Comfort package seats (variable headrests for the front seats - 4-way lumbar support for the front seats, electrically adjustable horizontally and vertically - comfort center armrest in the front, longitudinally adjustable and tiltable; additional storage option in the integrated storage compartment)
- Driving Assistance Package (Audi active lane assist - Audi adaptive cruise control - Audi pre sense rear and basic - Traffic jam assist - Predictive efficiency assist - Evasive steering assist - Left turn assist - High beam assist - Driver information system with color display - Camera-based traffic sign recognition - Lane change warning)
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides with memory function (with integrated LED turn signals and curb view function for the passenger-side exterior mirror; aspherical mirror glass, including heated windshield washer nozzles. The passenger-side exterior mirror tilts downwards when reverse gear is engaged, providing the driver with a better view of the curb).
- Front sports seats (with manual adjustment of seat height, seat longitudinal position, seat tilt, backrest tilt, headrest and belt height; with pronounced seat side bolsters for better lateral support in curves, extendable thigh support)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Headlight cleaning system (provides more light on the road, especially in adverse weather conditions. Cleaning with water and high pressure creates better luminosity and good visibility due to reduced scattering.)
- Interior elements in synthetic leather (lower center console and armrest in the doors in synthetic leather, color-matched to the interior color).
- Matrix LED headlights with Audi laser light (Matrix LED headlights with Audi laser light, dynamic light styling and dynamic turn signals - LED taillights with dynamic light styling and dynamic turn signals - headlight cleaning system)
- Mechanically swiveling towbar (The mechanically swiveling towbar can be conveniently locked and unlocked via a release mechanism. - Ball head mechanically swiveling with electric release - Ball rod and head made of forged steel, operated via a button in the luggage compartment - Trailer stabilization via the electronic stability control (ESC))
- Paint finish: Metallic
- Audi virtual cockpit with 12.3" color display (Innovative, fully digital instrument cluster for flexible and needs-based display of relevant information according to driver requirements: speed/RPM, map display, Audi connect services, radio/media information, etc.; the VIEW button on the multifunction steering wheel allows switching between two different-sized displays of the round instruments. The display with smaller instruments enables large, clear graphics of the on-board computer and MMI content)
- Auxiliary heater/ventilation (The auxiliary heater warms the interior and defrosts the windows without starting the engine. The auxiliary ventilation system supplies fresh air and lowers the interior temperature. Both functions can be activated via a timer and separate remote control. An intelligent control system with timer and departure time programming calculates the heating duration efficiently in terms of time and energy. Two heating modes are selectable: - defrost (defrost mode for the windows only) - warm (warm mode for preheating the interior)
- Business package (front seat heating - comfort package mirrors - infotainment package smartphone - navigation package - leather steering wheel in 3-spoke design with multifunction plus)
- Comfort automatic climate control 3-zone (in addition to the automatic climate control: - climate control unit with large TFT display and capacitive rocker switches - electronically regulates the air temperature and distribution individually for driver and front passenger - additional climate control unit for setting the rear passenger compartment temperature in the rear center console - automatic recirculation control via air quality sensor, with dust and odor-removing allergen filter - ventilated glove compartment - dust and odor-removing cabin air filter - residual heat utilization)
- Head-up display (projects driver-relevant information from assistance systems, navigation or warning messages onto the windshield in the driver's direct field of vision. The height-adjustable head-up display enables a high-contrast, multi-colored display within the driver's field of vision.)
- LED matrix headlights with dynamic turn signals front and rear (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, static curve lighting (supplementing lateral illumination in tight curves and when turning), all-weather light (to reduce glare in poor visibility conditions), maneuvering light (illuminating the swivel area when reversing), motorway light (extended beam range from a speed of 110 km/h), automatic dynamic headlight range control)
- Package: Ambient Lighting Package (in addition to the interior lighting: - approach lighting in the exterior door handles - entry lights on the underside of the front doors - illuminated front cupholders - front footwell lighting - illuminated interior door handles - ambient door lighting - ambient lighting in the front center console)
- Parking Assistance Package (Parking Aid Plus - Parking Assist - Rearview Camera)

- Panoramic glass roof (electric operation for tilting and opening the glass element, automatic opening and closing, tinted glass insert with continuously adjustable electric sunshade. Comfort opening and closing from the outside via the remote key; the extra-large glass surface provides a pleasant, light-flooded interior ambience, good acoustics when the roof is tilted or fully open. Integrated wind deflector reduces wind noise when the roof is open.)
- Seats: Pneumatically adjustable lumbar support with massage function (pneumatic lumbar support using 3 lordosis bubbles that provide optimal support in the lumbar region through targeted inflation and deflation - with massage function: This is controlled via the multifunction switch and via MMI - a massage lasts approximately 10 minutes)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus (height and reach of the leather steering wheel are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with 12 multifunction buttons. Includes a leather gearshift/ selector lever knob and a leatherette handbrake grip.)
- Telephone: Smartphone interface with USB at the rear in V with navigation package (Audi Smartphone Interface - Bluetooth interface)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Light alloy wheels in multi-spoke design, graphite grey, polished (8.5 J x 19 with tires 255/35 R 19)
- Radio accessories: Bang & Olufsen sound system with 3D sound (20 speakers (including center speaker/2 subwoofers and additional 3D sound tweeters and midrange drivers) - 755-watt 16-channel amplifier - illuminated front speaker grilles - speed-dependent volume adjustment - spatial sound reproduction thanks to the new 3D sound feature. This is created by additional speakers in the A-pillar, the midrange drivers, and Fraunhofer Symphoria technology.)
- Seats: Electrically adjustable front seats with memory function for the driver's seat (with electric adjustment of seat height, seat longitudinal position, seat and backrest tilt; with memory function for the driver's side: 2 memory locations for the electrically adjustable front seats and the exterior mirrors, storable and recallable via the memory buttons in the door trim)
- Storage and luggage compartment package (Sportback) (flexible transport of items and comfort on journeys; consisting of: - storage net on the back of the front seat backrests - cupholder in the rear center armrest - storage compartment on the driver's side - lockable glove compartment in the luggage compartment: - luggage compartment net - net in recesses on the left and right - tension strap on the right)
- Upholstery: Leather/synthetic leather combination (for standard and sport seats: - center section of the front seats and the two outer rear seats, as well as the driver's side side bolster in the entry area in leather; for sport seats with seat ventilation: - center section of the front seats, non-ventilated center section of the two outer rear seats in perforated leather, as well as the driver's side entry bolster in leather in atlas beige, rock grey, okapi brown or black)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
4	Door - rear left side	Door - Scratch(es) - Paint
5	Bonnet	Bonnet - Stone chips - Paint
6	Front bumper	Front bumper (+ Steinschläge) - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Mudguard - right side	Mudguard - right side - Stone chips - No deduction
2	2nd wheel set	Tyres - complete set - Does not meet the leasing specifications - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book (Digitaler Ausdruck)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.




Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.





Figure 42: Misc.



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 1: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 4: Door - rear left side: Door - Scratch(es) - Paint



Damage 4: Door - rear left side: Door - Scratch(es) - Paint




Damage 4: Door - rear left side: Door - Scratch(es) - Paint




Damage 4: Door - rear left side: Door - Scratch(es) - Paint



Damage 4: Door - rear left side: Door - Scratch(es) - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint




Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 5: Bonnet: Bonnet - Stone chips - Paint



Damage 6: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 6: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint




Damage 6: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 6: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Wear and tear 1: Mudguard - right side: Mudguard - right side - Stone chips - No deduction



Wear and tear 1: Mudguard - right side: Mudguard - right side - Stone chips - No deduction