TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 47006530
Order No. / Reference: 26817911
Inspection date: 11 Aug 2026

Manufacturer: Peugeot	Model: 308 SW Hybrid 180 e-EAT8 Allure
VIN: VR3F4DGXTPY503752	





Vehicle details

Manufacturer / Type / Model / Equipment	
Peugeot 308 SW Hybrid 180 e-EAT8 Allure	
Vehicle Identification number	VR3F4DGXTPY503752
Mileage (Read)	127,364 km
First registration	9 May 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	05/2028
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,598 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Avatar Blau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	9,400 km
Last service on / at	03/2026 at 106,766 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GG056747
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AEK 00008		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,170 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 91Y	Summer tyres on Light alloy	Bridgestone	5mm / 5mm
2)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment: Illuminated glove compartment
- Active Safety Brake Plus (for nighttime use and cyclists)
- Airbags (6) (Driver and front passenger airbag - front passenger airbag deactivatable - front side airbags - front and rear curtain airbags)
- Exterior mirror caps in Perla Nera Black
- Trim panel between the taillights in high-gloss black
- On-board computer
- Decorative fabric inserts "Texa" for door panels and dashboard
- Tachometer
- Eco-LED headlights
- Front and rear parking assistance, acoustic and visual
- Driving modes (driving profile selection Electric, Hybrid, Sport)
- High beam assist
- electric parking brake
- Front collision warning
- Functions Brake and e-Save (for energy recovery when releasing the accelerator pedal and for preserving purely electric range (10 km, 20 km or the full charging capacity))
- Cup holder in the center console
- rear window wiper
- Infotainment system: PEUGEOT i-Connect (Infotainment system: up to 8 profiles and 2 smartphones simultaneously via Bluetooth, - Bi-tuner, 6 speakers (midrange and tweeters) - Digital radio reception DAB+ - MP3-compatible - Bluetooth hands-free system with audio streaming via Bluetooth - 2 USB-C ports at the front - Operation via steering wheel and touchscreen)
- Paint finish: Metallic Avatar Blue
- Charging cable: Mode 2 charging cable (Type 2, up to 2.3 kW), 6 meters long
- LED lighting in the front footwell
- LED taillights
- LED daytime running lights
- Steering wheel: Leather steering wheel with paddle shifters
- Makeup mirror (illuminated for driver and front passenger)
- front center armrest
- Multi-collision brake
- Multimedia: Mirror Screen (Transfer of multimedia content and apps from a compatible smartphone to the vehicle's touchscreen, allowing direct control of compatible functions and apps - CarPlay (for compatible Apple iPhone models) - Android Auto and Mirror Link (for compatible smartphone models with Android operating system))
- Emergency brake assist with automatic activation of the hazard warning lights
- On-board charger 3.7 kW, 1-phase
- Particle filter: OPF (Otto particulate filter)
- Break warning
- ABS (Anti-lock Braking System) with electronic brake force distribution
- Acoustic pedestrian warning system (AVAS)
- Electrically adjustable, heated and folding exterior mirrors (with LED approach lighting - integrated LED turn signals)
- Hill start assist
- Turn signals with lane change indicator function
- third brake light
- Digital instrument cluster with high-resolution 10" screen, adjustable and customizable
- Pressure tank system (including switch for opening the fuel filler flap on the dashboard)
- Electronic Stability Program (ESP) (with ASR (traction control))
- Electric windows, front and rear (with comfort operation and anti-pinch protection)
- Follow-me-home function (automatic)
- Laminated glass windshield, noise-reducing
- luggage compartment roller blind
- Cruise control system with speed limiter
- Transmission: 8-speed automatic transmission EAT8
- Heated rear window
- Rear apron in black
- Interior mirror automatically dimming
- Frameless interior mirror (with cyan LED lighting in Electric mode)
- Map pockets on the front seatbacks
- Keyless system (keyless start system)
- Child safety lock at the rear
- Automatic climate control (2-zone), with activated carbon filter (separately adjustable for driver and front passenger)
- LED ambient lighting on the dashboard and door panels (adjustable in 8 colors)
- LED ceiling lighting at the front (2 reading lights at the front and rear)
- Steering wheel: Small multifunction leather steering wheel, flattened at the top and bottom.
- light sensor
- Rear center armrest (with pass-through flap)
- Multifunctional touchscreen with 10" HD color display (capacitive screen - multi-window capable with widgets or shortcuts)
- Fatigue warning
- Navigation system: PEUGEOT i-Connect Advanced (PEUGEOT i-Connect Advanced 3D navigation system, map display on the digital instrument cluster, natural voice control "OK PEUGEOT" for navigation, telephone, air conditioning and media, real-time navigation by (TomTom Services, traffic information, petrol stations, parking lots, weather, local search), hazard zone warning (6-month trial period included, then paid subscription), PEUGEOT Connect Box, telematics services)
- Peugeot i-Toggles (screen with configurable virtual buttons for the most important functions such as radio, air conditioning, navigation system, vehicle settings, telephone and connectivity)

- Peugeot Connect Box (with the free telematics services Peugeot Connect SOS and Peugeot Connect Assistance - GPS module - Integrated European SIM card - Speaker and microphone - Emergency battery)
- Upholstery: Fabric/faux leather
- Tire pressure monitoring system
- Wheels: Tire repair kit (compressor + tire sealant spray)
- Reversing camera with 180° surround view
- Electric power steering
- Seats: Passenger seat height adjustable
- Seats: Manual lumbar support for driver
- Seats: Rear seats (3 three-point seat belts - belt force limiters on the side seats - warning light and warning signal when the seat belt is released - 3 fully retractable headrests - Isofix child seat anchors on the outer seats)
- Lane keeping assist with steering intervention
- 12-volt socket
- Doors lock automatically when driving off
- Chrome-plated decorative exhaust tailpipes
- Preconditioning function
- Immobiliser
- Decorative trim in high-gloss black on the side windows
- Rain sensor
- Wheels: Calgary 17" alloy wheels, two-tone (tires 225/45 R17 94V)
- Side windows in the second row and rear window are more heavily tinted.
- Seats: Driver's seat height adjustable
- Seats: Rear bench seat and backrest split 40/20/40, foldable (Magic Flat system with control element in the boot)
- Seats: Front seats (three-point seat belts with belt locking devices - pyrotechnic belt tensioners and electronically controlled belt force limiters - warning light and warning signal when the seat belt is not fastened or is released for driver and front passenger - safety-optimized headrests)
- Traffic sign recognition (with display of the speed recommendation in the instrument cluster)
- Central locking system, activatable from inside via remote control

Extra equipment

- Charging cable: Green-up charging cable (Type 2, up to 3.6 kW), 6 meters long
- Seats: Heated front seats

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Replace
4	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
5	Trim / covers	Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value
6	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - Replace
7	Bonnet	Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents



Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.




Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace




Damage 3: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace




Damage 4: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 4: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value



Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value



Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value




Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value



Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value




Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value




Damage 5: Trim / covers: Trim / covers (Laderaum / + verschmutzt) - Scratched - Loss in value




Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace



Damage 6: Vehicle glazing: Windscreen with lane departure assistant - Stone chips - Replace




Damage 7: Bonnet: Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 7: Bonnet: Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 7: Bonnet: Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 7: Bonnet: Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint



Damage 7: Bonnet: Bonnet (Steinschläge) - Dent / paintcoat damage - Repair and paint