TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48567819
Order No. / Reference: 27196601
Inspection date: 9 Nov 2026

Manufacturer: Seat	Model: Born 150kW/58kWh
VIN: VSSZZZK1ZNP017594	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Born 150kW/58kWh	
Vehicle Identification number	VSSZZZK1ZNP017594
Mileage (Read)	31,585 km
First registration	14 Oct 2022
Number of holders	1
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car station wagon
Colour / colour code	Pebble Grey (A7C)
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	681 Tag(e)
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ890494
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ASO 00001		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,280 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 99V	Winter tyres on Light alloy	Yokohama	6mm / 6mm
2)	215/55 R18 99V	Winter tyres on Light alloy	Yokohama	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger (center airbag - side airbags for driver and front passenger)
- Ambient lighting in the front door trim (including footwell lighting)
- Electrically adjustable, folding and heated exterior mirrors (including passenger-side mirror lowering function)
- third brake light
- CCS charging socket
- CUPRA e-Sound (AVAS Acoustic Vehicle Alert System, acoustic vehicle warning system) from 0-50 km/h
- CUPRA side skirts in Liquid Grey
- Decorative elements (decorative element on instrument panel Black, decorative stitching in Copper - decorative inlay in front doors, Dinamica Granite Grey, made from recycled materials - decorative elements in Copper)
- Luggage compartment lighting
- Speed limiter
- Heat pump (heat pump for efficient air conditioning and range optimization)
- Rear bumper and diffuser in body color (with Liquid Grey accents)
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control (separate for driver and front passenger, with stationary air conditioning)
- Paint finish: Solid
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather (heated)
- Front center armrest (in Dinamica Granite Grey, front, made from recycled materials)
- Center console with integrated storage compartment and cup holder (including roller shutter, in black)
- Fatigue detection
- Emergency call service (no registration required - service is activated upon delivery)
- Rain sensor
- Tire pressure monitoring system
- Wheels: CYCLONE 7.5J x 18" alloy wheels (tires 215/55 R 18 with Tyre Fit)
- Seat belts - front and rear (warning buzzer and warning light for unfastened seat belts)
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Seats: Driver's seat with height adjustment
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color (with air intakes in Liquid Grey and trim in Copper)
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Passenger airbag deactivation
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Exterior mirror housing in Liquid Grey
- Battery warranty 8 years, maximum 160,000 km
- C-pillar with CUPRA design element
- CUPRA Drive Profile (driving profiles can be individually selected - Range, Comfort, Performance, Individual)
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electronic Stability Control (ESC) (Anti-lock Braking System (ABS) - Traction Control System (ASR))
- Electric window regulator with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- rear window wiper
- Rear spoiler in car color
- Interior mirror automatically dimming
- ISOFIX child seat restraint system, in the 2nd row left and right as well as on the front passenger seat (i-Size compatible - incl. top tether anchor points at the rear)
- Headrests, 2 front
- Headrests, 3 rear
- Mode 3 Type 2 charging cable, 16 A
- Lights: Full headlights (full LED headlights with light sensor and automatic headlight control, cornering light function and bad weather light - full LED taillights with Infinite Light; dynamic LED light strip at the rear - turn signals with LED technology integrated into exterior mirrors including welcome light projection under the exterior mirrors - Ceremony Light)
- Progressive steering
- Radio: Radio, navigation and multimedia systems (2 USB-C charging ports for the 2nd row of seats - 5 speakers - Virtual Cockpit-5, 3" fully digital instrument cluster - antenna for FM reception - Bluetooth interface with integrated hands-free system and audio streaming - Android Auto, Apple CarPlay incl. Full Link Wireless - 2 USB-C ports in the front - DAB+ - infotainment system with 12" color touchscreen - voice control - CUPRA CONNECT)
- Seats: CUPRA front sport bucket seats (made of SEAQUAL Yarn fabric, Black)
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Front Assist area monitoring system with City Emergency Braking function

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Front bumper	Front bumper - Scratch(es) - Smart repair
3	Front bumper	Front strip - Scratched - Smart repair
4	Sill - right side	Sill - dent(s) - Smart repair
5	Rear bumper	Rear bumper - Scratch(es) - Smart repair
6	Body	Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument cluster



Figure 9: Instrument panel

Figure 10: Interior 360° view (Online Link)



Figure 11: Cargo area



Figure 12: VIN



Figure 13: Mounted tyres




Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 2: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 3: Front bumper: Front strip - Scratched - Smart repair



Damage 3: Front bumper: Front strip - Scratched - Smart repair



Damage 4: Sill - right side: Sill - dent(s) - Smart repair



Damage 4: Sill - right side: Sill - dent(s) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 5: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise




Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 6: Body: Body (Kleberückstände / Mehrkosten können entstehen) - Glued / labelled - De-glue / neutralise