TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48487861
Order No. / Reference: 27204583
Inspection date: 4 Nov 2026

Manufacturer: Opel	Model: Crossland 1.5 Diesel Elegance
VIN: W0V7H9EN0P4240268	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Crossland 1.5 Diesel Elegance	
Vehicle Identification number	W0V7H9EN0P4240268
Mileage (Read)	66,084 km
First registration	13 Nov 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	81 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Silber/Dach Karbon Schwarz Meta
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	27,300 km
Last service on / at	09/2026 at 63,390 km		
Key is / should be	2 / 2	**FZG documents**	ZB#1 (S) was available (copy), ZB#2 (B) was not available.
		Letter No.	GY737530
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AMH 00132		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,835 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/60 R16 89H	Winter tyres on Light alloy	Dunlop	5mm / 5mm
2)	195/60 R16 89H	Winter tyres on Light alloy	Dunlop	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R17 95W	Summer tyres on Light alloy	Dunlop	5mm / 5mm
2)	215/50 R17 95H	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front and rear outer head airbags
- Anti-lock braking system (ABS)
- Hill Start Assist
- On-board computer
- Roof design line, above in chrome
- Diesel particulate filter (DPF) maintenance-free
- Electronic brake force distribution (EBD)
- Driver information display, 3.5"
- Electric front windows
- Transmission: 6-speed manual transmission
- rear window wiper
- Instrument inserts, black with chrome rings
- Automatic climate control, two zones
- Front headrests
- LED ambient lighting
- Steering wheel: Leather steering wheel with chrome elements and steering wheel remote control
- Proactive driver assistance system
- Radio: Digital radio reception DAB/DAB+/DMB-R
- Tire repair kit
- Power steering
- Visibility equipment
- Seats: Seat backrest split 60:40, foldable
- Lane Assist
- 12V power outlet in the center console, front
- Underride protection look, front and rear, in silver
- Pre-installation for child seat mounting system "ISOFIX"
- Central locking with remote control
- Airbag for driver and passenger side
- Airbag: Side airbag for driver and front passenger side
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- third brake light
- Roof spoiler in carbon black
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric rear windows
- Speed controller with limiter
- Back window, heater
- Interior lighting, front and rear, including reading lights, front
- Rear headrests (3)
- Paint finish: Roof in carbon black
- LED daytime running lights
- Makeup mirror, illuminated in sun visor
- Navigation system: Multimedia Navi Pro with 8" color touchscreen display, voice control for audio, telephone, navigation
- Tire pressure warning
- Seat belts: Three-point seat belts in all seats
- Seats: Comfort seats
- Solar Protect thermal insulation glazing
- Start/Stop System
- Traction control (TC Plus)
- Traffic sign assistant
- Immobiliser
- Ignition keys with remote control, two, both foldable

Extra equipment

- Silver roof rails
- LED headlights CWJ=PS03
- Multimedia Navi Pro with 8" touchscreen IO6=JY11
- Fog light
- Wheels: Alloy wheels 6.5 J x 17 with tires 215/50 R17, in black (5 double spokes)
- Keyless locking and starting system (for driver and passenger doors as well as the luggage compartment)
- Head-Up Display UV6=YB01
- Steering wheel heating and seat heating, company and B. CWG=NA01
- Package: Tech Package Elegance 1 (180-degree panoramic reversing camera - Park Pilot, front and rear parking aid)
- Heated windscreen, ThermaTec C50=LW02

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 1 (registration document) was available, but the vehicle registration certificate Part 2 (title) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Braking system	Brake fluid - No evidence - No deduction
3	Side panel - rear right side	Sill - dent(s) - Smooth repair work
4	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - front right side - Scratched - No deduction
2	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book

Repainting

No.	Repainting
1	Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Mudguard - right side	208 µm	Side panel - rear right side	259 µm
Door - rear right side	250 µm	Door - front right side	177 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Der montierte Radsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.




Figure 32: Misc.



Damage 3: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 3: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 4: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 4: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Repainting 1: Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side



Repainting 1: Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front right side