TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48181866
Order No. / Reference: 27107567
Inspection date: 12 Oct 2026

Manufacturer: Audi	Model: A3 30 TFSI Limousine S tronic S line
VIN: WAUZZZGY7PA105729	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 30 TFSI Limousine S tronic S line	
Vehicle Identification number	WAUZZZGY7PA105729
Mileage (Read)	95,772 km
First registration	5 Jul 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	09/2028
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	81 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Gletscherweiss Metallic
Doors / Seats	4 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	19,300 km
Last service on / at	04/2026 at 85,067 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS525516
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BXN 00302		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,840 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Bridgestone	6mm / 6mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Michelin	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 02/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Traction control ASR
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- third brake light
- Tachometer
- Rear parking sensors
- Electromechanical parking brake
- Electronic Differential Lock (EDS)
- Chassis: Sport chassis
- Remote key (without Safe-Lock)
- Speed limiter
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Light and rain sensor
- Non-smoking version
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seats: Rear seat backrest foldable
- Start-stop system
- 12V socket
- Glazing: Green tinted thermal insulation glazing
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Audi connect emergency call & service m.connect remote & control
- Exterior mirror housings in body color
- Digital instrument cluster - fully digital instrument cluster in 10.25 inches
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electronic Stability Control (ESC)
- Electric windows front and rear
- front and rear floor mats
- Transmission: S tronic 7-speed
- Electrically operated child safety lock
- Rear headrests (3)
- Front headrests
- Mild hybrid
- Otto particulate filter
- Tire pressure monitoring system
- Headlight
- 3-point automatic seat belts
- Lane Departure Warning
- 12-volt power outlet in the rear
- Daytime running light
- Electronic immobilizer

Extra equipment

- Adaptive cruise control (assists with acceleration, braking, and maintaining speed and distance. The adjustable speed limiter helps, for example, to prevent exceeding a preset maximum speed within built-up areas from approximately 30 km/h. Audi pre sense front uses a front radar to detect the area in front of the vehicle within the system's limits and warns of potential hazards with visual and audible signals.)
- Exterior mirror housings in black
- Deletion of model designation and performance/technology lettering
- High-beam assist (within the system's limitations, it automatically detects oncoming headlights, taillights of other road users, and light sources in built-up areas. Depending on the traffic situation, the high beams are automatically switched on or off. The system thus improves the driver's visibility and increases comfort.)
- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Paint finish: Metallic
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- Business package (USB ports with charging function in the rear - Audi connect Navigation & Infotainment plus - Audi phone box - Audi virtual cockpit plus - Smartphone interface (Android Auto and Apple CarPlay) - MMI Navigation plus with MMI touch - Cruise control)
- Black Optics Package (Includes: - black accents in the area of the Audi Singleframe grille - black accents in the area of the trim strips on the side windows - black accents in the area of the front and rear bumpers - black accents on the widened side sills (only with S line) - optional roof rails in black (only for Sportback))
- Parking assistant with parking aid plus (Using ultrasonic sensors, the system searches for suitable parallel or perpendicular parking spaces. For perpendicular spaces, the system calculates the parking path (forwards and backwards); for parallel spaces, it calculates the entry and exit paths. The driver must accelerate, shift gears, and brake, as well as monitor the parking process. The system handles the steering. Within the system's limits, the surround view displays warnings of obstacles around the vehicle, depending on the driving path. Multi-stage parking maneuvers are supported.)
- Aluminum look in the interior (frame of the control button strip of the center console, the door trim strips front and rear, the elements on the mirror adjustment switch, the window regulator switch and the control buttons of the parking brake in aluminum look)
- Ashtray at the front and cigarette lighter (cigarette lighter - removable ashtray with lid)
- Audi drive select (allows the desired vehicle characteristics to be set in various available modes via a separate control element in the switch panel of the center console and via the MMI operating system. This includes adjustments to the steering assistance, engine characteristics or shift points (in vehicles with S tronic), driving dynamics control, and other standard systems. If ordered, optional equipment is also adapted to the selected mode.)
- Camera-based traffic sign recognition (Supports the driver by displaying traffic signs detected within the system's limits, such as speed limits, no-overtaking zones, and temporary speed restrictions, which are within the detection range of the front camera. The traffic sign recognition is displayed automatically in the digital instrument cluster or in the optional Audi virtual cockpit.)
- Comfort key with sensor-controlled luggage compartment unlocking (The vehicle can be unlocked wirelessly at all doors and the luggage compartment lid. The comfort key simply needs to be carried and does not need to be actively used. The vehicle can be locked again using the sensors on the door handles. The engine is started and stopped using the engine start/stop button. The tailgate can be conveniently unlocked and closed with a foot gesture (kick movement) at the rear.)
- Steering wheel: Leather steering wheel in a 3-spoke design with multifunction plus and shift paddles (The steering wheel's height and reach are manually adjustable. For convenient operation of the extensive standard and optional infotainment features, the steering wheel is equipped with twelve multifunction buttons. Shift paddles allow manual gear changes.)
- S line interior package (S tronic) (front sport seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt and seat belt height, as well as headrests; fabric Puls/mono.pur 550-K synthetic leather; 3-spoke leather steering wheel with multifunction plus and shift paddles including leather steering wheel grips; front and rear door armrests in synthetic leather; aluminum spectrum dark decorative inlays; illuminated front door sill trims with aluminum inlays and S lettering; black fabric headliner; front center armrest; stainless steel floor mats, pedals and footrest)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Alloy wheels - 18 inch - 5-twin-spoke V (S-design), graphite grey (8.0 J × 18, tires 225/40 R 18)

- Seat covers in microfiber Dinamica/mono.pur 550 synthetic leather combination with S embossing (for front sport seats: - Seat center panels of the front seats and the two outer rear seats in microfiber Dinamica - Seat side bolsters, headrests, middle rear seat and front center armrest (if ordered) in mono.pur 550 synthetic leather - Contrast stitching and diamond quilting - S embossing in the backrests of the front seats)
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Phone: LTE support for Audi phone box
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Reversing camera (captures the area behind the vehicle within the system limits. The display is adjusted according to the steering angle using dynamic display elements in the MMI touch display. The user can choose between perpendicular parking and trailer modes. Depending on the selected mode, the calculated driving lane or a guide line for coupling a trailer is displayed, also dependent on the steering angle. The reversing camera is activated by engaging reverse gear or via a button in the center console.)
- Seats: Rear seat backrest foldable (three-part), with center armrest (split in a 40:20:40 ratio or fully foldable; with center armrest and cupholders)
- Telephone: Audi Phone Box (universal Bluetooth interface - convenient, integrated hands-free system - coupling antenna for connecting the mobile phone to the external antenna for improved reception quality - reduced radiation in the vehicle interior - LTE support - charging option via USB port or wireless charging (Qi standard) - forget-to-use warning - charging status indicator in the MMI touch display - connection of a second mobile phone)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Exhaust system	Tail pipe (Blende) - Scratched - Smart repair
2	Front bumper	Front bumper - Unprofessionally repaired - Smart repair
3	Rear bumper	Rear bumper (Schleifspuren) - Unprofessionally repaired - Repair and paint

Wear and tear

No.	Component group	Description
1	Seat - front	Seat cover - left side - Abrasion - No deduction
2	Seat - front	Backrest cover - left side - Abrasion - No deduction
3	Rear bumper	Spoiler - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Repainting

No.	Repainting
1	Side panel - rear right side, Door - rear right side, Professionally carried out
2	Bumper front, Unprofessionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	193 µm	Door - rear right side	174 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Wartungshistorie gemäß Auftraggeber Informationen.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum




Figure 25: Misc.



Figure 26: Misc.



Damage 1: Exhaust system: Tail pipe (Blende) - Scratched - Smart repair



Damage 1: Exhaust system: Tail pipe (Blende) - Scratched - Smart repair



Damage 2: Front bumper: Front bumper - Unprofessionally repaired - Smart repair



Damage 2: Front bumper: Front bumper - Unprofessionally repaired - Smart repair



Damage 3: Rear bumper: Rear bumper (Schleifspuren) - Unprofessionally repaired - Repair and paint



Damage 3: Rear bumper: Rear bumper (Schleifspuren) - Unprofessionally repaired - Repair and paint



Damage 3: Rear bumper: Rear bumper (Schleifspuren) - Unprofessionally repaired - Repair and paint



Repainting 1: Side panel - rear right side, Door - rear right side



Repainting 1: Side panel - rear right side, Door - rear right side