TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48221259
Order No. / Reference: 27041396
Inspection date: 12 Oct 2026

Manufacturer: Volkswagen	Model: Multivan T7 Kurz Life
VIN: WV2ZZZST1PH011921	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Multivan T7 Kurz Life	
Vehicle Identification number	WV2ZZZST1PH011921
Mileage (Read)	45,999 km
First registration	13 Apr 2023
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Starlight Blue Metallic
Doors / Seats	5 / 7
Upholstery type	Cloth
Colour of upholstery	Dark grey-Light grey
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8,000 km
Last service on / at	10/2025 at 30,769 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS525308
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CQJ 00226		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,850 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R18 101H	Summer tyres on Light alloy	Hankook	6mm / 6mm
2)	235/50 R18 101H	Summer tyres on Light alloy	Hankook	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R16 102H	Winter tyres on Light alloy	Goodyear	6mm / 6mm
2)	215/65 R16 102H	Winter tyres on Light alloy	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 01/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Various shelves and storage compartments
- Evasive steering assist and turn assist
- Exterior mirrors, electrically adjustable, heated and folding
- Exterior mirror housings in high-gloss black
- LED turn signals, integrated into the side of the exterior mirrors
- Roof rails/roof load carrier: Mounting points for roof rack system (6 pieces)
- Parking assistance in the front and rear areas
- Chassis: 16" chassis with 16" disc brakes at the front and 16" disc brakes at the rear
- Windows: Front pane made of laminated safety glass, heat and sound insulating
- Cruise control system with speed limiter
- Glove compartment with light
- Tailgate: Power closing tailgate
- Instrument usage (km/h)
- Fuel-powered auxiliary heater
- LED headlights with LED daytime running lights
- LED taillights
- Steering wheel: Multifunction leather steering wheel with paddle shifters
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Without Mode 3 charging cable
- Radio: "Ready 2 Discover" with 25.4 cm (10 inch) color touchscreen including "Streaming & Internet"
- Radio accessories: 8 speakers (passive)
- Radio accessories: USB interface
- Wheels/Tires: 215/65 R 16 102 H XL, optimized for low rolling resistance
- Windscreen wiper intermittent control with rain sensor for the front windscreen wipers
- Drawers under the outer seats in the passenger compartment and 2 waste bins
- Automatically dimming interior safety mirror
- Seats in the passenger compartment: 2 individual seats facing forward in the 2nd row.
- Seats: Armrest(s) inside the seats (removable and repositionable)
- Seats: Seat left and right, in the 1st row
- Lane keeping assistant “Lane Assist”
- Daytime running light activation with cornering lights
- First aid kit, warning triangle and high-visibility vest
- Lashing eyes (4 pieces)
- Central locking with keyless start system "Keyless Start" without safe locking
- Airbag for driver and front passenger
- Airbag: Side and head airbags for driver and front passenger
- Exterior mirrors, left and right convex
- Reinforced battery (68 Ah/ 380 A)
- On-board tools and tire mobility set
- third brake light
- Decorative inlays: Decorative inlays "Dark Silver Brushed"
- Three-phase generator 160-250 A
- Electronic Stability Program, ABS, ASR (with deactivation button), EDS
- Chassis: Suspension and damping, standard
- Electric windows, front
- Floor mats: Textile floor mats in the driver's cab
- Transmission: DSG (dual-clutch transmission), 7-speed automatic
- Rear window with wiper/washer system, heated
- Child seat anchorage ISOFIX and Top Tether
- Cargo space divider (load capacity 20 kg) with bag hooks and luggage net
- Strip between the headlights painted in glossy black
- Headlight range control
- Multi-collision brake
- Non-smoking version
- eCall emergency call system
- Particulate filter: Soot particle filter for diesel engines
- Radio: App-Connect incl. App-Connect Wireless
- Radio: Digital radio reception (DAB+)
- Radio accessories: Voice control
- Wheels, tires: Covers for alloy wheels
- Wheels/Tires: Tire pressure monitoring system
- Wheels/Tire Accessories: Lockable wheel bolts
- Sliding door: Closing aid on both sides for sliding doors
- Keys for locking system: 2 vehicle keys
- Power steering
- Seatbelt check
- Seat covers: Bi-color seat covers in fabric, design "Ribella"
- Seats in the passenger compartment: 3 individual seats in the 3rd row.
- Seats: Armrests for driver and front passenger seats, on both sides
- Sun visors with mirrors, illuminated, ticket holder on the driver's side
- Telephone: Mobile phone interface
- Traffic sign recognition
- Electronic immobilizer

Extra equipment

- Bulli badge and lettering 0NP
- Windows (glass type in the cargo/passenger compartment) - rear windows tinted
- Paint finish: Metallic
- Multifunctional display: Digital Cockpit Pro
- Navigation system "Discover Media" (25.4 cm (10 inch) color touchscreen - streaming & internet)
- Package: Easy Open Package (Environmental lighting on the tailgate and 30-color ambient lighting - Tailgate with electric opening and closing - Central locking with keyless locking and starting system "Keyless Advanced" without safe locking - Electric tailgate (opening and closing) with "Easy Open" and "Easy Close" function - Sliding door left, electric with "easy open" function - Sliding door right, electric with "easy open" function)
- Rear View reversing camera
- Heated seats for the driver's cab, left and right, separately adjustable
- Display: Head-Up Display
- Air conditioning: 3-zone "Air Care Climatronic" with additional control unit in the passenger compartment
- Light and visibility: IQ.Light - LED matrix headlights (Dynamic Light Assist high beam control for LED matrix headlights - IQ.Light LED matrix headlights with LED daytime running lights - Dynamic headlight range control with dynamic cornering lights - Bad weather lights including turning lights)
- Radio: "Harman Kardon" sound system (13 speakers - 840 watts total power - digital 16-channel amplifier - subwoofer)
- Wheels/Tires: "Toshima" 7.5 J x 18 alloy wheels in anthracite (4 "Toshima" 7.5 J x 18 alloy wheels in anthracite - tires 235/50 R 18 101 H xl, optimized for rolling resistance - wheel center cover for alloy wheels - lockable wheel bolts)
- Lane change assistant "Side Assist" including "Blind Spot Detection" (parking assistant and exit warning)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Boot lid / rear door	Boot lid - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Mudguard - left side	Mudguard - left side - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Mounted tyres




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.





Figure 33: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair



Damage 2: Boot lid / rear door: Boot lid - Scratch(es) - Smart repair