DS

1.5 BLUEHDI 130 BASTILLE + AUTO

VIN: VR1JCYHZUMY534635



Description

Registration number 2BGB986	**Registration date** 10/11/2021	**Odometer** 77513 km
Color cristal pearl	**Year** 2019	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1499 cc	**Gearbox type** Automatic	**Engine type** Combustion
Fuel Type Diesel	**Number of gears** 8	**Drivetrain** Front Wheel Drive (FWD)
Max power 96 KW		

Vehicle Equipments

Standard

Parkpilot system front and rear	interior mirror with automatic dimming	airbag driver side/passenger side
sidebag front	headlight assist with day/night sensor	roof rails (aluminium)
body: 5-door	steering column (steering wheel) mech. height/longitudinal adjustment	Electronic Stability Control (ESP)
traction control system (ASR)	tire puncture indicator	Peugeot Connect Box / emergency button (emergency call for localization vehicle) Version 3R
wheelbase 2738 mm	maintenance: Normal operating conditions	windshield wiper with rain sensor
parking brake electromechanical	Light-alloy rims	tire repair kit
rear window heated	window lifter electr., front with comfort feature and pinch protection	window lifter electric rear
Type of drive: front-wheel drive	trip computer	Equipment package: DS Inspiration Bastille
seat covers/upholstery: cloth	Equipment package: DS Sensorial Drive	Advanced safety package
exterior mirror electrically adjustable, heated + folding	exterior mirror fold-up	front fog lights LED with cornering lights
driver assistance system: traffic sign detection	driver assistance system: blind-spot assistant	driver assistance system: lane assist
driver assistance system: alertness assistant	Comfort package	seat front right height-adjustable
lumbar support front, electrically adjustable	long-cargo channel (center armrest rear)	modular package
power outlet (12V outlet) in trunk/load space	Pneus 235/55 R18 ..V	xenon headlights
pedals aluminium	headlight leveling control	headlight leveling control electric
cruise control (cruise control) incl. vehicle speed limiter	seat front left height-adjustable	Isofix mounts for child seat at rear seat
active suspension / damping system (DS Active Scan Suspension)	Audio navigation system: Connect Nav with digital radio reception DAB / DAB+	driver assistance system: safety system SYNC with automatic emergency call
head airbag system (Sideguard)	head airbag system rear	antilock braking system (ABS)
driver assistance system: hill-start assist (Hill-Holder)	driver assistance system: brake assistant (Audi pre sense front)	side window rear and rear window darkened
ambient lighting LED		

Optional

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Optional

center armrest rear	multifunction display with colour touchscreen 12 inch	parking aid rear incl. reversing camera
parking aid front and rear, acoustic and optical with selective display (APS Plus)	Park-Distance-Control (PDC)	driver assistance system: parking aid front and rear with reversing camera
airbag passenger side deactivatable	side and pelvic airbag front, with head airbag unit	generator 180 A (class 18, HEA)
head rests front adjustable	front part synthetic design	side protection strips with chrome trim
Batterie 70 Ah (Type EFBC)	automatic transmission - (8-speed)	automatic transmission - type: 8F40 (8-speed)
Bras de suspension Aluminium, renforcé(e)	Caches de moyeux de roues noir(e)	steering angle sensor
catalyst (< 50 PPM)	shift control electric	standard suspension
automatic air-conditioning system	air conditioning with internal heat exchanger (IHX technology)	instrument cluster digital (virtual cockpit)
air-conditioning compressor with coupling	air-conditioning condenser, variant: 19,3 dm², thickness 12 mm	Connexion USB (x 3)
Contrôle dynamique de stabilité (ESP Bosch 9.3)	rear lid open+close automatic (Hands-Free-Access system)	power steering electric, dual sprocket
start/stop system	stop/start system (starter)	brake discs front 304 mm
starter STTD	footwell light driver, passenger	interior equipment decorative trim inserts Deep Iron Grey
interior equipment black	rear lights LED, 3D optic	fuel filter without water separator and coolant level sensor
diesel particulate filter	suspension without reinforcement	refrigerant R 1234 YF
fan system: 140 W, fan blade dynamic (2-stage)	Interrupteur mode de conduite (Mode double)	Montage Multiplex R3 ECO
engine (fuel type Diesel)	Moteur 1,5 litre(s) - 96 kW Blue-HDI FAP Catalyseur (YHZ / DV5RC)	low emissions according to emission standard Euro 6d
windshield heated	bumper front in gray with trim cover vehicle-coloured	Base engine DV5R
power outlets (12V outlet) in cab (2 pieces)	underride protection powertrain (engine and transmission) long	preparation trunk/cargo space floor dual
accelerator synthetic design	Radiateur de chauffage	radiator, variant: 28 dm², thickness 28 mm, aluminium soldered
repairability improved	fuel tank with misfueling protection	fuel tank with integrated fuel filter
Réservoir à carburant: 55 litre(s)	interior mirror frameless with automatic dimming	interior mirror without integrated display
seat heating front	Siège sans réglable Assise (coté passager)	Sièges sans fonction massage
Stabilisateur AV (Dureté 32500 Nm/rad)	front axle carrier steel reinforced, with longitudinal extensions	audio navigation system R-Link Evolution with touchscreen and Carminat TomTom
driver assistance system: active lane-keeping assistant	driver assistance system: collision warning system with brake function	driver assistance system: alertness assistant
driver assistance system: parking assistant incl. reversing camera	SCR system (AdBlue technology)	Train AR suspension indépendante multibras, Axe de roue bas
engine type DV	VarEq-méthode Codage B0E0N	VarEq-méthode Codage DVS05
Steering AV equipment TDI	central locking system incl. door locking automatic	side window tempered and sound-insulating
Volant de direction (cuir Nappa, 4 branches)	steering wheel with shift rockers/buttons	veh. with OBD
veh. without anti-theft alarm	Véhicule sans amplificateur	Véhicule sans Aptitude à la flottaison
Véhicule sans Chauffage additionnel	veh. without booster heater	veh. without vehicle lowering
Véhicule sans dossiers AR inclinaison réglable	Véhicule sans Fonction video	Véhicule sans horloge (analogique)
veh. without lashing eyes	veh. without driver assistance system: Night Vision	veh. without driver assistance system: blind-spot assistant
Véhicule sans toit panoramique	Climate zones: variant cold countries	

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	24/06/2026	25/06/2026


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Personal Data / -	Non Compliant	Cleaning
			
002	Rim / Back Left Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Brushed Aluminium	Rust	Warranty
	 		
003	Rim / Front Right Material : Aluminium alloy / Rim/Tyre diameter : 19 " / Surface : Brushed Aluminium	Scratched	Repair
	  		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [ ] Toolkit
- [ ] Load cover
- [ ] Conformity certificate
- [ ] Locking wheel nut
- [ ] Remote key
- [ ] Towing hook
- [ ] Cargo net
- [ ] Security Kit
- [ ] Satellite navigation
- [ ] Document holder
- [ ] Charging cable bag
- [ ] First aid kit
- [ ] Slow charging cable (Type 2, Mode 2)
- [ ] Service book
- [ ] Registration certificate
- [ ] Card key
- [ ] Compressor tyre repair kit
- [ ] Hook /Hicth ball
- [ ] Safety vest
- [ ] Jack handle crank
- [ ] In-car tools
- [ ] Refill tyre repair kit
- [ ] Remote control
- [ ] Quick charging cable (Type 2, Mode 3)
- [ ] Warranty booklet
- [ ] Registration certificate owner
- [ ] Locking wheel nuts key
- [ ] Jack
- [ ] Spare Key
- [ ] Tyre repair kit complete
- [ ] User manual
- [ ] Rear parcel shelf
- [ ] Spare wheel tyre
- [ ] Triangle

Main set of tyres

Front Left	MICHELIN	235 / 50 / 19 / Summer	5 mm
Front Right	MICHELIN	235 / 50 / 19 / Summer	5 mm
Back Left	MICHELIN	235 / 50 / 19 / Summer	5 mm
Back Right	MICHELIN	235 / 50 / 19 / Summer	5 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right


Odometer


Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Personal Data / - / Non Compliant



Rim / Back Left / Rust




Rim / Back Left / Rust



Rim / Front Right / Scratched



Rim / Front Right / Scratched



Rim / Front Right / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.