TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

Expertise

Protocol number: 48195457
Order No. / Reference: 27160973
Inspection date: 20 Oct 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV COOL&CONNECT
VIN: WF0FXXWPMHPY31090	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV COOL&CONNECT	
Vehicle Identification number	WF0FXXWPMHPY31090
Mileage (Read)	41,713 km
First registration	27 Sept 2023
Number of holders	1
Next periodical technical inspection (Report on hand)	10/2028
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	112 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Blazer Blau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	41 %
Last service on / at	11/2025 at 36,262 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GX170961
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106V	All-season tyres on Light alloy	Michelin	2mm / 2mm
2)	225/65 R17 106V	All-season tyres on Light alloy	Michelin	3mm / 3mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Electrically adjustable and heated exterior mirrors (painted in car color - with integrated turn signals)
- Tires: Tire repair kit
- third brake light
- Roof spoiler
- Tachometer
- Selective driving mode switch (5 driving modes to choose from: Normal, Sport, Eco, Slippery and Unpaved Roads)
- Electric parking brake with auto hold function
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Geofencing - Display of emission zones with Euro 6 and higher in the SYNC navigation device
- Luggage compartment cover, roller blind, removable
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- rear window wiper
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front and rear headrests (5) height adjustable
- Paint finish: Solid
- LED taillights
- Steering column, adjustable in height and reach
- Make-up mirrors in driver and passenger sun visors
- MyKey key system (individually programmable second key)
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist (including Forward Alert system with pedestrian and bicycle detection)
- Tire Pressure Monitoring System (TPMS)
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 4-way manually adjustable
- Seats: Backrest for front passenger, adjustable tilt
- Seats: Driver's backrest, adjustable tilt
- Seats: Front sports seats with integrated headrests
- Power outlet: 12-volt connection in the luggage compartment
- Immobiliser
- Anti-lock braking system
- Passenger airbag deactivation
- Tires: 7 J x 17 alloy wheels (4) in 5-spoke design (with 225/65 R 17 tires)
- Fabric headliner
- 12.3-inch digital instrument panel
- Electronic Safety and Stability Program (ESP)
- Lane keeping assist including lane keeping assist
- Electric front and rear windows with all-around closing function
- Ford EcoCoach (shows the efficiency of current driving behavior)
- FordPower start function (keyless start)
- FordPass Connect including eCall, Live Traffic information (information about the current status or location of the vehicle, as well as control of selected vehicle functions via a compatible smartphone with the FordPass app - Real-time traffic information)
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts on all seats, height-adjustable in the front - warning system for unfastened seat belts in the front and in the 2nd row)
- Charging cable for household socket
- Steering wheel: Steering wheel, 3-spoke design, Sensico in leather look
- Front center console with integrated armrest
- Navigation system: Ford navigation system including Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3 cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth hands-free system and audio streaming - USB port - Voice control for audio and telephone - Acoustic and visual route guidance - Dynamic navigation with enhanced traffic information system - Lane guidance - Road map for Europe)
- Projection lens headlights with LED daytime running lights
- Power steering
- Seats: Driver's seat, 8-way manually adjustable, including adjustable lumbar support
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front seats, individually and variably heated
- Carpet floor mats in the front
- Variable radiator air intake
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Tires: 4 all-season tires 225/65 R 17 102V
- Charging cable for the public charging station
- Roof rails, silver-colored
- Safety partition net for attachment behind the 2nd row of seats (including attachment points behind the first and second rows of seats)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wing mirror - left side	Cap - Scratched - Smart repair
2	Wing mirror - right side	Cap - Scratch(es) - Smart repair
3	Side panel - rear left side	Sill - Scratch(es) - Smart repair
4	Side panel - rear right side	Sill - Scratch(es) - Smart repair
5	Wheel / tyres	Tyres - complete set - Does not meet the leasing specifications - Replace
6	Door - rear right side	Door - Scratch(es) - Paint
7	Door - rear left side	Door - Scratch(es) - Paint
8	Bonnet	Bonnet - Scratch(es) - Paint
9	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
10	Boot lid / rear door	Boot lid glazed - dent(s) - Repair and paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
2	Side panel - rear left side	Side panel - Scratch(es) - No deduction
3	Rear bumper	Bumper with Parktronic (Ladekante) - Scratch(es) - No deduction
4	Sill - right side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Navigation




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 1: Wing mirror - left side: Cap - Scratched - Smart repair



Damage 1: Wing mirror - left side: Cap - Scratched - Smart repair




Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 4: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace




Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace




Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 5: Wheel / tyres: Tyres - complete set - Does not meet the leasing specifications - Replace



Damage 6: Door - rear right side: Door - Scratch(es) - Paint




Damage 6: Door - rear right side: Door - Scratch(es) - Paint




Damage 6: Door - rear right side: Door - Scratch(es) - Paint



Damage 7: Door - rear left side: Door - Scratch(es) - Paint



Damage 7: Door - rear left side: Door - Scratch(es) - Paint



Damage 7: Door - rear left side: Door - Scratch(es) - Paint




Damage 7: Door - rear left side: Door - Scratch(es) - Paint



Damage 8: Bonnet: Bonnet - Scratch(es) - Paint




Damage 8: Bonnet: Bonnet - Scratch(es) - Paint



Damage 9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 9: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 10: Boot lid / rear door: Boot lid glazed - dent(s) - Repair and paint



Damage 10: Boot lid / rear door: Boot lid glazed - dent(s) - Repair and paint



Damage 10: Boot lid / rear door: Boot lid glazed - dent(s) - Repair and paint



Damage 10: Boot lid / rear door: Boot lid glazed - dent(s) - Repair and paint



Wear and tear 3: Rear bumper: Bumper with Parktronic (Ladekante) - Scratch(es) - No deduction