Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 8 Sept 2026
Protocol number: **47871375**

WBA81FJ030CU28707

Vehicle details

Operator		**Inspection condition**	sufficient
License number		**Mileage (Read)**	54,182 km
Manufacturer	BMW	**Next maintenance in**	11,000 km
Type / Model	530e xDrive	**Main inspection (Report not on hand)**	11/2027
Vehicle Identification number	WBA81FJ030CU28707	**Power**	220 kW
Engine displacement	1,998 ccm	**Cylinder**	—
First registration	12 Dec 2024	**Upholstery/Colour**	Leather / Black
Last maintenance	08/2025, 32,486 km	**Paintwork**	White
Fuel type	Hybr.B/E ext.aufl	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Repair and paint
2	Front bumper	Front bumper - Scratch(es) - Repair and paint

Wear and tear

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction
2	Door - front left side	Door - Scratch(es) - No deduction
3	Rear bumper	Rear bumper (Ladekante) - Scratch(es) - No deduction

Missing parts

Missing part

Detected repainting

No.	Location

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	245/45 R19	Pirelli	Summer tyres	5mm - 5mm	o.k.	
2	245/45 R19	Pirelli	Summer tyres	4mm - 4mm	o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	2-year warranty
-	AC Charging Plus
-	Active Guard Basic
-	Airbags
-	Attention assistant
-	Automatic climate control with 2-zone regulation
-	BMW ID
-	BMW iDrive
-	BMW Interaction Bar
-	BMW Live Cockpit Plus
-	BMW xDrive
-	Braking system
-	Central locking system
-	Central locking with remote control
-	Condition Based Service
-	Cruise control with braking function
-	DAB tuner
-	Dark silver accent combined with Dark Graphite matt effect paint finish, 19" M light-alloy wheels Triplex-spoke 933
-	Driving experience switch
-	electric window regulator
-	Extended exterior mirror package
-	Exterior features
-	Fund seats
-	Heated seats for driver and front passenger
-	Interior features
-	Interior lighting
-	LED headlights
-	My Modes
-	Otto particulate filter (OPF)
-	Outdoor lighting
-	Parking Assistant
-	Power socket
-	Professional charging cable (Mode 3) for public charging
-	Security systems
-	Solid color paint
-	Speed Limiter
-	Sports seats for driver and front passenger
-	Standard steering wheel
-	Standard suspension
-	Steering

Code	Description
-	Stereo speaker system
-	Storage options
-	Through-loading system, 40-20-40 split backrest
-	Traction control
-	Transmission: Steptronic transmission with paddle shifters
-	Veganza perforated padding
-	Vehicle key
-	Velour floor mats
-	Warning triangle with first aid kit
-	Wireless Charging Tray

Extra equipment

Code	Description
04U9	Acoustic pedestrian protection
05AV	Active Guard
08TF	Active pedestrian protection
0552	Adaptive LED headlights
A070	AGM battery 70 Ah
0302	Alarm system
02TE	Automatic transmission with paddle shifters
03DK	BMW Digital Key
04V1	BMW ICONICSOUNDS ELECTRIC
06U3	BMW Live Cockpit Professional
03G0	BMW LM wheel Triplex spoke 933 STD
06U7	BMW Natural Interaction
01CB	CO2 scope
08R3	COC ADDITIONAL PACKAGES
06AK	Connected Drive Services
06C4	Connected Package Professional
08WN	Control E
0654	DAB tuner (DAB+ capable)
043G	Dark Graphite matt effect paint
05AU	Driving Assistant Professional
0230	EU-specific additional scopes
01DF	EU6 rde II emissions standard
04U8	Fast charging AC
0851	German language version
0494	Heated seats for driver and passenger
04NR	INTERIOR CAMERA
06AF	Legal emergency number
0548	odometer
08KA	Oil change interval: 24 months/30,000 km
0879	Onboard literature in German
05DN	Parking Assistance System Plus
06PA	Personal eSIM
04T2	PROFESSIONAL CHARGING CABLE (MODE 3)
07EW	Professional Equipment Package
08R9	Refrigerant R1234yf
06NX	Storage tray wireless charging
06AE	Teleservices
0420	tinted glazing
02VB	Tire pressure gauge
02VC	Tyre repair kit
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock

Comments

Fahrzeug hat dem Alter und Laufleistung entsprechende Gebrauchsspuren.
Verkehrssicherheit wurde nicht überprüft.

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Lagermax - AT - Straßwalchen
Lagermax Str. 1
5204 Straßwalchen

Inspection date: 8 Sept 2026
Protocol number: **47871375**

Vehicle details

Manufacturer	BMW	**Inspection condition**	sufficient
Type / Model	530e xDrive	**Mileage (Read)**	54,182 km
Vehicle Identification number	WBA81FJ030CU28707	**First registration**	12 Dec 2024

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
The inspection conditions were sufficient for the assessment of the vehicle.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior



Figure 6: Interior




Figure 7: Interior



Figure 8: Interior



Figure 9: Interior




Figure 10: Interior




Figure 11: Interior



Figure 12: Interior




Figure 13: Interior




Figure 14: Interior




Figure 15: Interior




Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.

Pictures of damage



Damage Wing mirror - right side: Wing mirror - right side: Cap - Scratch(es) - Repair and paint



Damage Wing mirror - right side: Wing mirror - right side: Cap - Scratch(es) - Repair and paint



Damage Front bumper: Front bumper: Front bumper - Scratch(es) - Repair and paint



Damage Front bumper: Front bumper: Front bumper - Scratch(es) - Repair and paint