TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48140605
Order No. / Reference: 26826340
Inspection date: 22 Sept 2026

Manufacturer: Audi	Model: A6 40 TDI S tronic sport
VIN: WAUZZZF25PN059338	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 40 TDI S tronic sport	
Vehicle Identification number	WAUZZZF25PN059338
Mileage (Read)	112,468 km
First registration	25 Apr 2023
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Manhattangrau Metallic
Doors / Seats	4 / 5
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	7,200 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS508190
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BTN 03284		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,250 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V	Winter tyres on Light alloy	Semperit	6mm / 6mm
2)	225/55 R18 102V	Winter tyres on Light alloy	Goodyear	6mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102Y	Summer tyres (Without wheel rim)	Continental	5mm / 4mm
2)	225/55 R18 102Y	Summer tyres (Without wheel rim)	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters) Tank for AdBlue solution for reducing nitrogen oxides in the exhaust gas using an SCR system
- Anti-lock braking system (ABS)
- Audi connect Navigation & Infotainment - Navigation with Google Satellite Map - Online search for navigation destinations - Online voice input - Online traffic information/Traffic Info Plus - Online points of interest - On-street parking - Hazard information - Online traffic sign information - myAudi Navigation - Highly detailed 3D city view - Amazon Alexa integration - Online media streaming (e.g., Amazon Music integration) - Online radio - Hybrid radio - Weather information - Online news - Wi-Fi hotspot - User profiles
- Audi drive select allows you to adjust the vehicle characteristics in the available modes: auto, comfort, dynamic, efficiency, allroad, offroad, and individual by adapting the steering assistance, engine characteristics or shift points, dynamic all-wheel steering, damper control, adaptive air suspension, sport differential, ultra technology, adaptive speed assistant, matrix LED headlights, and setting other optional equipment.
- Electrically adjustable and heated exterior mirrors with integrated LED turn signals, including heated windshield washer nozzles, aspherical mirror glass
- Fabric headliner
- Diesel particulate filter (DPF) with nitrogen oxide catalyst and AdBlue tank
- Tachometer
- Electronic Stability Control (ESC)
- The remote key locks and unlocks the doors, luggage compartment, and fuel filler flap. Drive authorization is granted without actively using the key (keyless go). The driver must be in the vehicle and have the key with them. The engine is started and stopped using the engine start/stop button on the center console.
- Automatic tailgate opening/manual tailgate: When the tailgate is unlocked via the remote control, the button in the driver's door, or the soft-touch button in the tailgate handle recess, it swings open automatically for easier access. Manual tailgate closing
- Transmission: S tronic 7-speed
- Interior lighting, front and rear roof module, including reading lights (capacitively switched); illuminated vanity mirrors for driver and front passenger; entry lights on the underside of the front doors; front/rear door handles; front storage compartment; glove compartment; front/rear footwell lighting; right/left trunk lighting
- ISOFIX and Top Tether child seat attachment for the outer rear seats: Mounting device for the practical attachment of ISOFIX child seats with an additional upper attachment point (Top Tether) on the outer rear seats.
- Headrests (4) - front, manually height adjustable
- Airbag for driver and front passenger, full-size airbag, with passenger airbag deactivation
- Airbag: Front side airbags and head airbag system - Front side airbags integrated into the seatbacks - with additional head airbag system: deploys in front of the side window area, thus protecting front and outer rear passengers in the event of a side impact
- Audi connect Emergency Call & Service m.connect Remote & Control The Audi connect Emergency Call & Service services ensure peace of mind on every journey. - Emergency call - Online breakdown call - Audi damage service - Audi service appointment online Audi connect Remote & Control: - Vehicle status - Remote locking/unlocking - Parking position - Remote control of auxiliary heating - Push notification Anti-theft alarm system
- Audi pre sense front can warn of impending collisions within its system limits, depending on the situation and speed, and initiate appropriate braking. The system is active from approximately 5 km/h. Pedestrians and cyclists can be detected at speeds up to approximately 85 km/h, and vehicles at speeds up to 250 km/h. If an impending frontal collision is detected, the system warns the driver visually, audibly, and haptically in a multi-stage process.
- Exterior mirror housings in body color
- third brake light
- Decorative aluminum fragment inserts for dashboard, door panels and center console; including aluminum-look trim.
- Door sills with aluminum inlay, front and rear, unlit
- Driver information system with 7-inch color display. Display content: Speed (digital speedometer), time, mileage, outside temperature, fuel warning with remaining range, shift indicator, current radio station or music track, radio and media lists, telephone menu, navigation information and driver assistance system alerts (if available), on-board computer. The integrated efficiency program supports the driver with consumption data overviews and fuel-saving tips for more economical driving. Break recommendation.
- Cruise control system including speed limiter: The cruise control system maintains the desired speed from 20 to 250 km/h by adjusting engine power or by actively applying the brakes, provided engine and braking performance allow. It is operated via a separate steering column stalk, which also displays the set speed in the driver information system. The speed limiter helps to prevent exceeding a preset maximum speed.
- Interior mirror dimming
- 2-zone automatic climate control with separate temperature distribution for driver and front passenger sides; rear passenger compartment air conditioning via air vents in the rear center console; defroster nozzles for windshield and side windows; combined pollutant and particulate filter
- Steering wheel: Leather steering wheel, 3-spoke with multifunction and paddle shifters. Paddle shifters allow manual changing of the driving modes.
- Steering column, manually adjustable in height and axis

- LED headlights: The headlights have the following functions: - Daytime running lights - Low beam - High beam - Position lights - Turn signals (incandescent bulb technology) - All-weather lights (to reduce glare in poor visibility conditions) LED taillights: - Turn signals, brake lights, tail lights, reversing lights and rear license plate lights (LED technology)
- MMI Navigation with MMI touch response, 10.1-inch color display (1,540 × 720), additional display of the navigation map or arrow display in the driver information system, map updates, 3D map display, efficiency assistant, online traffic information, MMI search, MMI touch response for quick, intuitive operation, easy operation of the infotainment system via natural language interaction, detailed route information, input of up to 10 waypoints, selected portfolio Audi connect Navigation & Infotainment
- Wheel: Light alloy wheels, 5-arm design, 8 J x 18 with tires 225/55 R 18
- Wheel: Tire pressure monitoring system - visual and audible warning in case of pressure loss in one or more wheels - display in the driver information system
- Radio: MMI Radio plus with MMI touch response - 10.1-inch color display - Driver information system with 7-inch TFT color display - Audi music interface; 2 USB-C ports with data and charging function - Bluetooth interface (hands-free calling and audio streaming) - Remote MMI touch control unit with 8.6-inch color display including MMI touch response with haptic feedback; for controlling the climate control function and input field for handwriting recognition - AM/FM phase diversity - Speed-dependent volume adjustment - DAB+
- Sun visor on driver and passenger side
- Start-stop system – helps reduce fuel consumption and CO2 emissions by switching off the engine when stationary, e.g., at traffic lights. The restart process is initiated as soon as the foot brake is released. Can be deactivated at any time via a button.
- Glazing: Windscreen in heat-insulating glazing
- Glazing: Rear window, rear door and side windows in clear glass
- Heat-insulating glazing, green tinted on the sides and rear; heated rear window with timer.
- Front center armrest adjustable in tilt, longitudinally adjustable
- Gloss Package - Window channel trim in anodized aluminum - Exterior B-pillar trim in high-gloss black - Rear light trim in chrome
- Non-smoking package: no ashtray in the front center console, one 12-volt socket each in the front and rear.
- Progressive steering enhances driving dynamics and comfort through more direct steering response (e.g., on winding country roads or when turning) and reduced steering effort (e.g., when parking and maneuvering); driving characteristics are improved by a steering ratio dependent on the steering angle and speed-dependent power steering assistance; various modes are adjustable via Audi drive select.
- Wheel: Tire repair kit
- Radio accessories: 8 speakers (passive) front and rear
- Seat covers in fabric
- Seats: 4-way electric lumbar support, adjustable horizontally and vertically
- Seats: Front sports seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt, headrest height and distance, and seatbelt height, with pronounced side bolsters for better lateral support in curves, extendable thigh support, and electric 4-way lumbar support.
- Lane Departure Warning helps prevent unintentional lane departures within the system's limits. If the system is activated and ready, and the driver has not used the turn signal, Lane Departure Warning assists by making corrective steering interventions to prevent crossing detected lane markings. Additional steering wheel vibration is available upon request. Operating range: approximately 60 to a maximum of 250 km/h.
- Electronic immobilizer
- Central locking

Extra equipment

- AdBlue tank with increased filling volume - AdBlue tank with 22 liter filling volume - for diesel vehicles with SCR technology, for reducing nitrogen oxides in the exhaust gas
- Deletion of model designation and performance/technology lettering
- Electrically opening and closing tailgate: The tailgate can be opened electrically by pressing the button on the vehicle key, in the driver's door, or the soft-touch button on the tailgate handle. Closing the tailgate: Simply press the button on the inside of the tailgate, the button in the driver's door, or the button on the vehicle key. A6 Avant: Opening the tailgate in low-ceiling areas is made easier by a programmable opening angle.
- Seats: Split-folding rear seat backrest - pronounced outer rear seats, visually matched to the front seats, and an additional center seat - 3 L-shaped rear headrests, manually height-adjustable for good rear visibility - three 3-point seat belts - rear seat backrest split 40:20:40 or fully foldable - one-piece, foldable rear center armrest with storage compartment
- Glazing: Sun protection glazing, tinted rear window, rear door and side windows
- Parking aid plus with surround view: Acoustic and visual parking aid front, side, and rear to assist with parking and maneuvering using 12 ultrasonic sensors. A selective visual display shows the distance to detected objects on the upper display, depending on the current steering angle and direction of travel. Optionally, activation occurs automatically as soon as the vehicle approaches a detected obstacle at a speed of less than 10 km/h.
- Fuel tank (73 liters) Fuel tank for 73 liters of gasoline/diesel fuel
- Paint finish: Metallic
- Ambient lighting package in addition to the standard interior lighting: - Ambient fabric lighting in the front/rear doors - Approach lighting from the exterior door handles, front/rear - Ambient lighting of the instrument panel
- Front seat heating - heats seat and backrest center sections; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Misc.	Inspection / maintenance - No evidence - No deduction
3	Front bumper	Front bumper - Scratch(es) - Smart repair

Wear and tear

No.	Component group	Description
1	Door - rear right side	Door - Scratch(es) - No deduction
2	Side panel - rear right side	Side panel - dent(s) - No deduction
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - No deduction
4	Rear bumper	Rear bumper - Scratch(es) - No deduction
5	Mudguard - left side	Mudguard - left side - Stone chips - No deduction
6	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction
7	Boot lid / rear door	Boot lid - Paint defect - Cover / polish
8	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - No deduction
9	Wheel / tyres	Tyres - complete set - Differs from the original configuration - Un- / install

The vehicle shows signs of wear and tear commensurate with its age and use.

Paint coat thickness measurement

Roof	126 µm	Roof rail - left side	136 µm
Roof rail - right side	114 µm	Boot lid / rear door	127 µm
Mudguard - left side	124 µm	Mudguard - right side	123 µm
Bonnet	133 µm	Side panel - rear left side	125 µm
Side panel - rear right side	119 µm	Door - rear left side	113 µm
Door - rear right side	116 µm	Door - front left side	110 µm
Door - front right side	118 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN




Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Additional tyres



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair




Wear and tear 1: Door - rear right side: Door - Scratch(es) - No deduction



Wear and tear 1: Door - rear right side: Door - Scratch(es) - No deduction




Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - No deduction



Wear and tear 7: Boot lid / rear door: Boot lid - Paint defect - Cover / polish



Wear and tear 7: Boot lid / rear door: Boot lid - Paint defect - Cover / polish



Wear and tear 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction



Wear and tear 8: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - No deduction



Wear and tear 9: Wheel / tyres: Tyres - complete set - Differs from the original configuration - Un- / install



Wear and tear 9: Wheel / tyres: Tyres - complete set - Differs from the original configuration - Un- / install