MACADAM

Polestar Polestar 2 '19 BEV

Vehicle information

Make:	**Polestar**	License:	**N731GP**
Gearbox:	**Automatic**	Body color:	
Model:	**Polestar 2 '19 BEV**	VIN:	**LPSVSECEKNL050406**
Fuel type:	**Electric**	Power:	**165 kW**
Version:	**Polestar 2 63kWh Sing.M.St.Ra.**	First registration	**28/10/2021**
Mileage:	**99460 km**	N° of doors:	

Damage summary

Interior	1
Rear	1
Right	3

Commercial pictures
















Trip
Trip handmatig (TM)
9 651.8 km
17.9 kWh/100km
72:02 h
59 km/h
Trip automatisch (TA)
0.1 km
461.0 kWh/100km
00:04 h
2 km/h
Klik om te bevestigen
ODO 99 460 km


Polestar 2
Supplement
Polestar 2
Status en Garantie


LPSVSECEKNL050406


BRIDGESTONE


BRIDGESTONE










09:24
360°
P
Parkeersensoren
Automatisch remmen achter


09:24
Zoeken
Inloggen
om Thuis in te stellen
Google Maps
20°
20°


Batterijcertificaat
Datum van diagnose: 28/10/2026
93,37%
Status van de gezondheid (SOH)*
Polestar 2 SR Single motor
VIN : LPSVSECEKNL050406
Kilometerstand : 99.460 km
* SOH berekend op basis van fabrieksgegevens, informatie om rekening mee te houden voor de fabrieksgarantie
Raadpleeg het Moba-certificaat door deze QR-code te scannen
Meer weten over:
www.get-moba.com
CARA





Options according to the inspector

Central consol F	**Yes**	GPS	**Yes**	Headlights Xenon/LED/Laser	**Yes**
Panoramic roof	**Yes**	Radio multimedia	**Yes**	Rear view camera	**Yes**
Telephone equipment	**Yes**				

Damages

Alloy rim FR
Scratch(es)
Repair and paint (complete)
Right




Alloy rim RR
Scratch(es)
Repair and paint (complete)
Right





Bumper R
Scratch(es)
Smart repair
Rear




Door FR
Scratch(es)
Repair and paint (complete)
Right





Ignition key
Missing
Replace
Interior

Tyres

Front Left
Summer
245/45/19/102/Y
Bridgestone
5.0 mm
Front Right
Summer
245/45/19/102/Y
Bridgestone
4.9 mm
Rear Left
Summer
245/45/19/102/Y
Michelin
6.0 mm
Rear Right
Summer
245/45/19/102/Y
Michelin
5.3 mm

Checks

CO2 Emission	**0**	Digital maintenance	**N/A**
GPS storage	**Yes**	Luggage cover	**Yes**
Number head rests	**5**	Number of charging cables (rapid charge)	**1**
Number of keys total	**1**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Service book	**Yes**	User's manual	**Yes**

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.