TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

# Expertise

Protocol number: 48376794
Order No. / Reference: 27175290
Inspection date: 28 Oct 2026

| Manufacturer: Ford | Model: Transit Connect 230 L2 S&S Trend |
|---|---|
| VIN: WF07XXWPG7NY75975 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Ford Transit Connect 230 L2 S&S Trend | |
| **Vehicle Identification number** | WF07XXWPG7NY75975 |
| **Mileage** (Read) | 194,740 km |
| **First registration** | 25 Jul 2022 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 06/2027 |
| (Report on hand) | |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,499 ccm / 4 |
| **Power** | 88 kW |
| **Gearbox / Number of gears** | Manual / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Station wagon |
| **Colour / colour code** | Polar-Silber Metallic |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black-Anthracite |
| **Vehicle with smoke odor** | no |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 65 % |
| **Last service on / at** | 06/2026 at 184,146 km | | |
| **Key is / should be** | 3 / 3 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GH428263 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8566 / BLK 00440 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 2,300 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/60 R16 96V | Summer tyres on Steel rim with wheel cover | Pirelli | 4mm / 4mm |
| 2) | 205/60 R16 96V | Summer tyres on Steel rim with wheel cover | Pirelli | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/60 R16 96H | Winter tyres on Steel | Pirelli | 5mm / 5mm |
| 2) | 205/60 R16 96H | Winter tyres on Steel | Pirelli | 5mm / 5mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 02/2026 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- ABS with EBD
- Airbag package (front airbag for passenger, including deactivation function and glove compartment with lid - head and shoulder airbags in front and for outer rear seats - side airbags for driver and passenger)
- Hill start assist
- On-board computer including outside temperature display
- Tachometer
- Third brake light
- Fixed rear windows, right and left (at the height of the 3rd row of seats)
- Rear electric windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- FordPass Connect (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - incl. live traffic information in real time (in conjunction with Ford navigation system incl. Ford SYNC 3) - incl. Wi-Fi hotspot)
- Cruise control system with intelligent speed limiter (camera-based) (with intelligent speed limiter (camera-based) including traffic sign recognition system - multifunction leather steering wheel with 4 spokes in aluminum decor)
- Isofix mounting (on the outer seats of the 2nd row)
- Paint finish: Solid
- Steering column, adjustable in height and reach
- Center console, front (open with storage area, 2 cup holders)
- Package: Passenger car version package with rear swing door (folding front passenger seat, lane keeping assist, lane departure warning, driver drowsiness detection, cruise control, integrated speed limiter (camera-based), traffic sign recognition system, IPS: front and side airbags, front/rear head/shoulder airbags, seat belt tensioners and force limiters, safety pedals and steering column, 3-point seat belts at all seats, height-adjustable front seats, pre-collision assist, pedestrian/cyclist detection, tire pressure monitoring system (TPMS). Without partition and safety net).
- Sliding door, right and left
- Side protection strips, plastic
- Emergency Brake Assist (EBA)
- Automatic security door lock (45 sec.) (Automatic relocking if no door is opened within 45 seconds of unlocking via remote control)
- Seats: Seat package 22 (fabric "Capitol/City" in Ebony (black) - driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - single passenger seat, 2-way manually adjustable (forward/backward, backrest), foldable - headrests, height-adjustable - lumbar support, manual (driver's seat) - map pockets for driver and passenger seats - airbag package for driver and passenger seats)
- Daytime running light
- Carpet floor mats, front (2-piece set)
- Door handles, black
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Exterior mirrors, narrow mirror format
- Exterior mirror housing black
- Battery (12 V / 71h) ((EFB, 12V 70 Ah, 700 CCA))
- Floor covering: Carpet (1st and 2nd row)
- Diesel particulate filter (DPF) (with SCR catalyst and AdBlue tank)
- Electronic Stability Program (ESP) (with Traction Control (TCS) including Torque Vectoring Control and Adaptive Load Control)
- Front electric windows (with one-touch down function for driver's side)
- Ford ECO-Coach (signals environmentally friendly driving style)
- Heated windscreen (including electrically adjustable and heated exterior mirrors)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Rubberized luggage compartment floor mat
- Transmission: 6-speed transmission
- Glove compartment with lid
- Heated rear windows
- Rear window wiper/washer system
- Front interior lighting with delay function
- Front air conditioning including semi-electronic recirculation system
- Alternator/Generator
- Fog light
- Emergency brake light (hazard warning flashing activated during heavy braking)
- Pre-Collision Assist, camera-based (with pedestrian and cyclist detection, including Automatic Emergency Braking (AEB), Dynamic Brake Support (DBS), Forward Collision Warning (FCW))
- Radio: Ford Audio System 2 (DAB/DAB+ radio - FM/AM radio - USB port - Bluetooth interface - Steering wheel audio remote control)
- Tire pressure monitoring system
- Wheels: Tire repair kit
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Passenger compartment seats: 2nd row (bench seat, 60:40 split, foldable, can be lowered into the footwell - ISOFIX mounting on the outer seats)
- Front spoiler lip
- Start-stop system
- Dust and pollen filter
- Concealed storage compartment (in the floor of the 2nd row of seats)
- Power outlet: 12-volt connection on the center console, front and rear
- Front bumper and rear bumper end caps painted in body color
- Child safety lock on sliding doors
- Lashing eyes
- Electronic immobilizer (EPATS)

- Seatbelt warning system (Seatbelt warning system in all other seats)
- Central locking with remote control (door lock only on driver's door - 2 keys, one of which is a remote control key)
- Heat-insulating glazing, lightly tinted
- Auxiliary electric heater (PTC), front

### Extra equipment

- Electrically adjustable and heated exterior mirrors with blind spot assist (blind spot assist including cross traffic alert)
- Paint finish: Metallic
- Front and rear parking pilot system
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, TMCpro live traffic, detailed 3D visualization, Michelin travel guide for Europe)
- Seats: Seat Package 6 (Fabric "Capitol/City" in Ebony (black) - Driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - Front passenger single seat, 2-way adjustable (forward/backward/backrest) and foldable - Headrests, height adjustable - Seat heating driver, front passenger - Lumbar support, manual (driver) - Map pocket for driver's seat - Airbag package for driver and front passenger)
- Anti-theft alarm system with interior monitoring (including double locking and 2 remote control keys)
- Adaptive cruise control (with intelligent speed limiter - including radar- and camera-based pre-collision assist with pedestrian and cyclist detection, lane keeping assist including lane keeping assist and driver drowsiness detection - including traffic sign recognition system - leather multifunction steering wheel with 4 spokes in aluminum trim)
- Headlight assistant with day/night sensor including automatically dimming interior mirror (including headlight dimming with delayed switch-off, windscreen wipers with rain sensor)
- Safety partition net for separating passenger and luggage compartments (including attachment points (retrofitting not possible later))
- Heat-insulating glazing, tinted (from the B-pillar) (side windows from the 2nd row of seats)
- Xenon: Bi-xenon headlights with LED daytime running lights (with automatic headlight range control)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Equipment | Tirefit filler - Expired - Replace |
| 2 | Interior | Cargo area floor - Broken / torn - Loss in value |
| 3 | Wheel / tyres | Tyre - front left side - Leaking - Replace |
| 4 | Body | Body - Glued / labelled - De-glue / neutralise |
| 5 | Front bumper | Front bumper - Scratch(es) - Paint |
| 6 | Sliding door - left side | Sliding door with glass panel - Scratch(es) - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Steering system | Steering wheel - Abrasion - No deduction |
| 2 | 2nd wheel set | 1 tyre - Leaking - No deduction |
| 3 | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 4 | Bonnet | Bonnet - Stone chips - No deduction |
| 5 | Roof | Roof rail - left side - dent(s) - Smart repair |
| 6 | Mudguard - left side | Mudguard - left side - dent(s) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Side right, Provided by user / customer, from 25 Feb 2023 | 1.385,66 € |
| 2 | Roof, Rear, Side - left, Provided by user / customer, from 22 Oct 2025 | 6.282,41 € |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Roof, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | |
|---|---|
| Roof | 299 µm |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

Das Fahrzeug weist der Laufzeit entsprechende Gebrauchsspuren auf.

Winter - Radsatz ist kein Bestandteil des Lieferumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres





**Figure 13:** Documents




**Figure 14:** Documents




**Figure 15:** Documents




**Figure 16:** Documents



**Figure 17:** Additional tyres




**Figure 18:** Navigation



**Figure 19:** Misc.



**Figure 20:** Misc.




**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.




**Damage 1:** Equipment: Tirefit filler - Expired - Replace



**Damage 2:** Interior: Cargo area floor - Broken / torn - Loss in value




**Damage 2:** Interior: Cargo area floor - Broken / torn - Loss in value



**Damage 2:** Interior: Cargo area floor - Broken / torn - Loss in value




**Damage 2:** Interior: Cargo area floor - Broken / torn - Loss in value




**Damage 3:** Wheel / tyres: Tyre - front left side - Leaking - Replace




**Damage 3:** Wheel / tyres: Tyre - front left side - Leaking - Replace




**Damage 3:** Wheel / tyres: Tyre - front left side - Leaking - Replace




**Damage 3:** Wheel / tyres: Tyre - front left side - Leaking - Replace



**Damage 4:** Body: Body - Glued / labelled - De-glue / neutralise



**Damage 4:** Body: Body - Glued / labelled - De-glue / neutralise



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 5:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 6:** Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint



**Damage 6:** Sliding door - left side: Sliding door with glass panel - Scratch(es) - Paint




**Wear and tear 6:** Mudguard - left side: Mudguard - left side - dent(s) - No deduction



**Wear and tear 6:** Mudguard - left side: Mudguard - left side - dent(s) - No deduction




**Repainting 1:** Roof

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck




**Repainting 1:** Roof