ARVAL
BNP PARIBAS GROUP


2CTV323

INSPECTION REPORT

End of contract

GENERAL INFO

File	324558
License plate	2CTV323
Vehicle identification number	VF1RJA00469796295
Dossier	2022 262 009
Make	Renault Clio TCe 90 Techno
Mileage	54931
First registration	25/11/2022
client availability date	14/10/2026
inspectionDate	16/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




2-CTV-323
KEURING
BELCAR


DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
60	Wing Front Left // Smart Repair Small	N
83	Door Front Left // Painting	N
180	Wing Rear Right // Smart Repair Small	Y
194	Door Rear Right // Repair & Painting	Y
222	Side View Mirror Right // Painting	Y
316	Tyre Front Left // Replace	Y
346	Tyre Front Right // Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures





Door Rear Right // Repair & Painting-scratch + dent




Door Front Left // Painting-bad repair




Trunk Lid Interior Coating / Complete Panel / Replace-cracked






Tyre Front Left // Replace-worn




Tyre Front Right // Replace-worn






Side View Mirror Right // Painting-scratch





Wing Rear Right // Smart Repair Small-dent




Wing Front Left // Smart Repair Small-dent

See External Expertise-dent