TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48511973
Order No. / Reference: 27208692
Inspection date: 4 Nov 2026

Manufacturer: Audi	Model: A5 Sportback 40 TDI S tronic S line business
VIN: WAUZZZF58RA031876	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A5 Sportback 40 TDI S tronic S line business	
Vehicle Identification number	WAUZZZF58RA031876
Mileage (Read)	139,234 km
First registration	16 Nov 2023
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,968 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Mythosschwarz Metallic
Doors / Seats	5 / 4
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	3,000 km
Last service on / at	05/2026 at 125,749 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY343502
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	0588 / BWN 00501		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,125 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	265/30 R20 94Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm
2)	265/30 R20 94Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/35 R19 96V	Winter tyres on Light alloy	Continental	3mm / 3mm
2)	255/35 R19 96V	Winter tyres on Light alloy	Continental	4mm / 4mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- AdBlue tank (12 liters)
- Airbag: Front side airbags and head airbag system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service including vehicle control
- Audi virtual cockpit with 12.3" color display
- Exterior mirror housings in body color
- third brake light
- Decorative inlays diamond lacquer silver grey
- Tachometer
- Parking assistance plus
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Electric front windows
- front and rear floor mats
- Cruise control system with adjustable speed limiter
- Hold assist
- Interior mirror dimming
- ISOFIX and Top Tether child seat anchors for the outer rear seats
- Headrests (4)
- LED taillights
- Mild hybrid
- Non-smoking version
- Business Package
- Infotainment package smartphone package
- Wheel: Alloy wheels "5-twin-spoke design" (S-design)
- Wheel: Tire repair kit
- Radio: MMI Radio Plus
- Radio accessories: Data module Europe
- Rear seat backrest foldable
- Seat belts: Three-point automatic seat belts for all seats
- Lane Departure Warning
- Phone: App Store and smartphone interface
- Phone: Bluetooth interface
- Glazing: Windscreen in heat-insulating and acoustic glazing
- Green thermal insulation glazing
- Airbag for driver and front passenger
- Accent areas matte black
- Drive slip control
- Audi drive select
- Audi pre sense city
- Electrically adjustable/heated exterior mirrors
- Outdoor temperature display
- Fabric headliner
- Diesel particulate filter (DPF) with DeNox catalyst and AdBlue tank
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Suspension (sports suspension)
- Remote key, without safe lock
- Luggage compartment lid, electrically opening and closing
- Transmission: S tronic (7-speed)
- Interior lighting
- Manual child lock
- Automatic air conditioning
- boot floor mat
- Fuel tank (40 liters)
- LED headlights
- front center armrest
- Driving Assistance Package
- Package Gloss
- Upholstery: Fabric finish Index
- Wheel: Tire pressure monitoring system
- Wheel: Tires optimized for rolling resistance, speed-limited
- Radio accessories: 8 speakers
- Rear view camera
- Electromechanical power steering
- Front seats (standard seats)
- Start-stop system
- Phone: Audi Phone Box
- First aid kit with warning triangle
- Camera-based traffic sign recognition
- Electronic immobilizer

Extra equipment

- AdBlue tank (24 liters)
- Paint finish: Metallic only in V with Competition Edition / Edition Plus
- S line interior package (sports seats in front - S line seat covers in black fabric/leather combination with S embossing on the backrests of the front seats - 3-spoke leather steering wheel with multifunction plus including steering wheel grips in perforated leather and S emblem; steering wheel and gearshift boot with contrast stitching, color-coordinated - headliner in black fabric - decorative inlays in matt brushed aluminum with accent surfaces in gloss black - pedals and footrest in stainless steel - floor mats front and rear with contrast stitching)
- Upholstery: Fabric Sequenz/leather with S line embossing in the backrests of the front seats (seat center section of the front seats and the two outer rear seats in fabric Sequenz black - seat side bolsters, headrest center sections and middle seat in leather black with contrasting stitching - with S embossing in the backrests of the front seats)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Comfort key with sensor-controlled luggage compartment unlocking (wireless communication between the key and the vehicle allows opening the doors and luggage compartment lid, and locking via the sensors on the door handles. The comfort key simply needs to be carried with the vehicle. The engine is started and stopped using the engine start/stop button. The luggage compartment lid can also be conveniently unlocked with a foot gesture by kicking the rear of the vehicle if your hands are full.)
- Package: Competition Edition Plus (Competition Edition - Audi Sport wheels, 5-twin-spoke polygon, anthracite black, gloss-printed, 9.0 J x 20, tires 265/30 R 20 - Exterior mirror housings in gloss black - Brake calipers front and rear painted red - Matrix LED headlights with Audi laser light, dynamic light styling, dynamic turn signals, RS-specific darkened bezels - Entry LEDs with logo projection - Ambient lighting package plus)
- Radio accessories: Audi sound system (10 speakers including center speaker and subwoofer - 6-channel amplifier - total output of 180 watts)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
2	Documents	Owner's manual - Broken / torn - Replace
3	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
4	Wing mirror - right side	Cap - Scratch(es) - Smart repair
5	Door - front left side	Door edge - Scratch(es) - Smart repair
6	Trim / covers	Brightware / decorative strip (Heck rechts, Nasen gebrochen) - Loose - Replace
7	Door - rear left side	Door - Dent / paintcoat damage - Smart repair
8	Door - front right side	Door - Dent / paintcoat damage - Smart repair
9	Wheel / tyres	Tyre - rear right side (Flanke) - Damaged - Replace
10	Wheel / tyres	Tyre - rear left side (Flanke) - Damaged - Replace
11	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value
12	Wheel / tyres	Alloy rim - rear right side (Materialabtrag) - Scratched - Replace
13	Wheel / tyres	Alloy rim - front right side (Materialabtrag) - Scratched - Replace
14	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Damaged - Replace
15	Front bumper	Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint
16	Side panel - rear left side	Side panel - Dent / paintcoat damage - Repair and paint
17	Mudguard - right side	Mudguard - right side - Dent / paintcoat damage - Repair and paint
18	Bonnet	Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint
19	Vehicle glazing	Windscreen (Rissbildung) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Sill - right side	Trim - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 12 Jun 2026	735,60 €
2	Side right, Provided by user / customer, from 1 Aug 2025	2.054,74 €
3	Side - left, Provided by user / customer, from 16 Apr 2026	3.044,57 €

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
2	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
3	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	163 µm	Side panel - rear right side	299 µm
Door - rear right side	246 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 2: Documents: Owner's manual - Broken / torn - Replace



Damage 2: Documents: Owner's manual - Broken / torn - Replace



Damage 3: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door handle - outside - Scratch(es) - Smart repair



Damage 4: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 4: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 6: Trim / covers: Brightware / decorative strip (Heck rechts, Nasen gebrochen) - Loose - Replace




Damage 6: Trim / covers: Brightware / decorative strip (Heck rechts, Nasen gebrochen) - Loose - Replace



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 7: Door - rear left side: Door - Dent / paintcoat damage - Smart repair



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 8: Door - front right side: Door - Dent / paintcoat damage - Smart repair



Damage 9: Wheel / tyres: Tyre - rear right side (Flanke) - Damaged - Replace



Damage 9: Wheel / tyres: Tyre - rear right side (Flanke) - Damaged - Replace



Damage 10: Wheel / tyres: Tyre - rear left side (Flanke) - Damaged - Replace



Damage 10: Wheel / tyres: Tyre - rear left side (Flanke) - Damaged - Replace



Damage 10: Wheel / tyres: Tyre - rear left side (Flanke) - Damaged - Replace



Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value




Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value



Damage 11: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Loss in value



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 12: Wheel / tyres: Alloy rim - rear right side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 13: Wheel / tyres: Alloy rim - front right side (Materialabtrag) - Scratched - Replace



Damage 14: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 14: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Damaged - Replace



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 15: Front bumper: Front bumper (Steinschlag, sandstrahleffekt) - Scratched - Paint



Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint




Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 16: Side panel - rear left side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint



Damage 17: Mudguard - right side: Mudguard - right side - Dent / paintcoat damage - Repair and paint




Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint




Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint




Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 18: Bonnet: Bonnet (Rostbildung) - Dent / paintcoat damage - Repair and paint



Damage 19: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 19: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace




Damage 19: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Damage 19: Vehicle glazing: Windscreen (Rissbildung) - Stone chips - Replace



Wear and tear 2: Sill - right side: Trim - Scratch(es) - No deduction



Wear and tear 2: Sill - right side: Trim - Scratch(es) - No deduction



Repainting 1: Boot lid / rear door



Repainting 2: Side panel - rear right side



Repainting 3: Door - rear right side