TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

# Expertise

Protocol number: 48502413
Order No. / Reference: 27135598
Inspection date: 2 Nov 2026

| Manufacturer: Opel | Model: Corsa-e Edition |
|---|---|
| VIN: VXKUHZKXZM4301523 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Opel Corsa-e Edition | |
| **Vehicle Identification number** | VXKUHZKXZM4301523 |
| **Mileage** (Read) | 49,676 km |
| **First registration** | 26 Oct 2021 |
| **Number of holders** | 1 |
| **Fuel type** | Electric |
| **Power** | 57 kW |
| **Gearbox / Number of gears** | Direct drive / 1 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Saloon car |
| **Colour / colour code** | Jade Weiß |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Grey-Black |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | Available / complete | **Next maintenance in** | 14,800 km |
| **Last service on / at** | 07/2025 at 39,560 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GC786088 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | No |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 1889 / ABX 00010 | | |
| **Emission standard** | 2017/1151 | **fine dust sticker** | |
| **Permitted total weight** | 1,920 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 195/55 R16 91H | All-season tyres on Steel rim with wheel cover | Goodyear | 7mm / 7mm |
| 2) | 195/55 R16 91H | All-season tyres on Steel rim with wheel cover | Goodyear | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 04/2026 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartments (storage compartment in the center console, front and rear - cup holder in the center console - glove compartment - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 0.5-liter beverage bottles)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Hill Start Assist
- On-board computer
- Braking system: Regenerative
- Electronic brake force distribution (EBD)
- Driver information display 7", color (fully digital)
- Front collision warning with automatic emergency braking and pedestrian detection (Active between 5 and 85 km/h. Monitors the distance to the vehicle ahead; if the vehicle approaches a vehicle or pedestrian too quickly, the driver is alerted by a warning tone and a display in the driver information screen. In case of a collision risk, the braking system is prepared and, if necessary, emergency braking is initiated to minimize the consequences of a potential collision.)
- Headrests (5) (Height adjustable)
- Charging cable: Mode 2 charging cable (Type 2, up to 1.8 kW - for household sockets - 6 meters length)
- Steering column, height and reach adjustable
- Lithium-ion battery (50 kWh storage capacity)
- Driver fatigue detection (Based on steering behavior and driving duration, it detects signs of possible driver fatigue and issues a visual and audible warning (3-stage warning).)
- Electric parking brake
- Pollen filter
- Quickheat rapid heating system
- Radio: Multimedia radio with 7" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, smartphone integration via Apple CarPlay, Android Auto, voice control (e.g., navigation (Google Maps, Apple Maps), music, phone, reading and dictating text messages), 1 USB port in the center console, front, DAB+ digital radio reception, steering wheel controls, 6 speakers)
- Seats: Comfort seats (comfort driver's seat, 6-way manually adjustable (length, height, backrest angle) - comfort passenger seat, 4-way manually adjustable (length, backrest angle))
- Start/Stop system (reinforced starter motor - high-performance battery - switch to deactivate the start/stop function)
- 12V power outlet in the center console, front
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Pre-wiring for child seat mounting system "ISOFIX" (rear outer)
- Heat-insulating glazing, tinted
- Central locking with remote control
- Adaptive brake light
- Airbag: Front airbags, driver and front passenger (front passenger airbag can be manually deactivated)
- Airbag: Front and rear head airbags
- Airbag: Side airbag for driver and front passenger side (side airbag, front passenger, deactivatable)
- Electrically adjustable and heated exterior mirrors for driver and passenger side (manually foldable - exterior mirror housing in black)
- third brake light
- Headliner, Grey
- Electronic Stability Program Plus (ESP Plus)
- Electric front windows (one-touch function - anti-pinch protection)
- Pedestrian protection
- Intelligent speed control and limiter
- Transmission: Automatic electric drive with fixed gear ratio
- Back window, heater
- Rear window wiper (with intermittent function)
- Child safety lock in the rear doors, manual
- Automatic climate control (recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - rear footwell heating)
- Steering wheel: Comfort steering wheel (flattened at the bottom)
- Headlight range adjustment, manual
- Make-up mirrors (driver and passenger side)
- Onboard charger (vehicle-integrated charging unit, single-phase (7.4 kW))
- Opel Connect with telematics services (emergency call/breakdown call - vehicle status and information - route and journey information)
- Upholstery: Cloth
- Radio: Digital radio reception DAB+
- Keyless Start system
- Power steering (speed-dependent)
- Seat belts: Three-point seat belts in all seats (belt force limiter, front and rear outer seats - Double belt tensioners, front seats - Belt tensioners, rear outer seats - Warning tone and light for unfastened seat belts, front and rear seats)
- Visibility equipment (rain sensor, front - automatic dimming headlights with tunnel detection - interior rearview mirror, automatically dimming)
- Seats: Rear seat backrest split 60:40, foldable
- Lane Keeping Assist (warning in case of unintentional lane departure (between 65 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- Daytime running light
- Ambient lighting
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))

### Extra equipment

- Paint finish: Solid special color Jade White
- Navigation system: Multimedia navigation system with 7" color touchscreen display (Multimedia radio, automatic music recognition, Bluetooth hands-free system, Apple CarPlay, Android Auto, voice control, 1 USB port, DAB+, steering wheel remote control, navigation system, road map of Europe (including Russia and Turkey), 3D map display, dynamic route guidance, display of points of interest, tour planning, GPS module, charging station display, OpelConnect, including live navigation services, real-time traffic information, online POI search, map updates (via USB))
- Charging cable: Mode 3 charging cable, single-phase (for public charging (7.4 kW))
- Onboard charger (vehicle-integrated charging unit, 3-phase (11 kW))
- Wheels: Alloy wheels 6.5 J x 16 in 5-spoke design in silver/black (all-weather tires 195/55 R16)
- Wheels: Steel 6.5 J x 16 with all-weather tires 195/55 R16
- Reversing camera: 180-degree panoramic reversing camera including parking pilot, rear parking aid (display of the area behind the vehicle, including steering guidelines, when reverse gear is engaged in the color display of the infotainment system)

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Wheel / tyres | Wheel cover - front right side - Scratched - Replace |
| 2 | Equipment | Tirefit filler - Expired - Replace |
| 3 | Rear bumper | Rear bumper - Scratch(es) - Smart repair |
| 4 | Front bumper | Front bumper - Scratch(es) - Paint |
| 5 | Vehicle glazing | Windscreen - Broken / torn - Replace |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Wing mirror - left side | Cap - Scratch(es) - No deduction |
| 2 | Wheel / tyres | Wheel cover - rear right side - Scratch(es) - No deduction |
| 3 | Side panel - rear right side | Side panel - dent(s) - No deduction |
| 4 | Roof | Roof - dent(s) - No deduction |
| 5 | Side panel - rear left side | Side panel - dent(s) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents




**Figure 16:** Documents




**Figure 17:** Documents





**Figure 18:** Navigation



**Figure 19:** Misc.



**Figure 20:** Misc.




**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.





**Figure 24:** Misc.



**Figure 25:** Misc.



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratched - Replace




**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratched - Replace



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratched - Replace



**Damage 1:** Wheel / tyres: Wheel cover - front right side - Scratched - Replace



**Damage 2:** Equipment: Tirefit filler - Expired - Replace



**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 3:** Rear bumper: Rear bumper - Scratch(es) - Smart repair



**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint



**Damage 4:** Front bumper: Front bumper - Scratch(es) - Paint




**Damage 5:** Vehicle glazing: Windscreen - Broken / torn - Replace




**Damage 5:** Vehicle glazing: Windscreen - Broken / torn - Replace



**Wear and tear 4:** Roof: Roof - dent(s) - No deduction



**Wear and tear 4:** Roof: Roof - dent(s) - No deduction



**Wear and tear 4:** Roof: Roof - dent(s) - No deduction



**Wear and tear 5:** Side panel - rear left side: Side panel - dent(s) - No deduction



**Wear and tear 5:** Side panel - rear left side: Side panel - dent(s) - No deduction



**Wear and tear 5:** Side panel - rear left side: Side panel - dent(s) - No deduction



**Wear and tear 5:** Side panel - rear left side: Side panel - dent(s) - No deduction