ARVAL
BNP PARIBAS GROUP

2AMN105

INSPECTION REPORT

End of contract


GENERAL INFO

File	322322
License plate	2AMN105
Vehicle identification number	WBATS110X09G42622
Dossier	2020 339 052
Make	BMW X3 xDrive30e 120kW Aut.
Mileage	53546
First registration	17/05/2021
client availability date	15/09/2026
inspectionDate	24/09/2026








CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	




2-AMN-105
KEURING
BELCAR

DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
222	Side View Mirror Right // Painting	N
227	Side View Mirror Right / Shell / Replace Not Painted	N
228	Side View Mirror Right / Direction Indicator / Replace	N
13	Bumper Front // Painting	N
54	Headlight / Front left / Replace	N
18	Bumper Front / Spoiler / Replace	Y
38	Front Bonnet / Insulation / Replace	N
40	Windshield // Repair	Y
80	Door Front Left // Smart Repair Small	Y
92	Rocker Panel Left // Painting	Y
104	Door Rear Left // Repair & Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	N
174	Light / Rear Right / Replace	N
175	Light / Rear Right On Rear Bonnet / Replace	Y
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
201	Rocker Panel Right // Smart Repair Medium	Y
210	Door Front Right // Smart Repair Small	Y
236	Wing Front right // Polish	Y
341	Wheel Alloy Front Right // Repair	N

Damage Pictures





Door Front Left // Smart Repair Small-scratch




Rocker Panel Left // Painting-scratch







Wheel Alloy Front Right // Repair-scratch




Wing Front right // Polish-scratch




Light / Rear Right On Rear Bonnet / Replace-scratch


Light / Rear Right / Replace-scratch




Bumper Rear / Lower Cover Not Painted / Replace-scratch






Door Front Right // Smart Repair Small-scratch


Bumper Front / Spoiler / Replace-dent




Rocker Panel Right // Smart Repair Medium-dent


Door Rear Right // Repair & Painting-scratch + dent














Bumper Rear / Spoiler / Replace-scratch + dent






Wing Rear Right // Repair & Painting-scratch + dent

Door Rear Left // Repair & Painting-scratch + dent




Windshield // Repair-glass damage

Front Bonnet / Insulation / Replace-hole







Bumper Rear // Painting-scratch




Wing Rear Left // Painting-scratch

Side View Mirror Right / Shell / Replace Not Painted-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch




Side View Mirror Right // Painting-scratch




Bumper Front // Painting-scratch




Headlight / Front left / Replace-scratch