TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48404349
Order No. / Reference: 27216257
Inspection date: 27 Oct 2026

Manufacturer: Volkswagen	Model: Crafter 35 TDI VA Kasten
VIN: WV1ZZZSYZM9061523	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Crafter 35 TDI VA Kasten	
Vehicle Identification number	WV1ZZZSYZM9061523
Mileage (Read)	92,770 km
First registration	17 Aug 2021
Number of holders	1
Next periodical technical inspection	08/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	130 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Candy White (B9A)
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Re-import	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,400 km
Last service on / at	01/2026 at 79,258 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC362554
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	0603 / CBZ 70802		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	Continental	7mm / 7mm
2)	235/65 R16 115R	Winter tyres on Steel rim with wheel cover	unterschiedliche Hersteller	6mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Driver's side
- Floor coverings: Rubber floor covering in the driver's cab
- Three-point automatic seat belts (with belt height adjustment and belt tensioners for driver and front passenger)
- Total weight: Vehicle registration with a permissible total weight of 3.5 t
- Rear wing door without window cutout
- High roof, painted exterior in car color
- Headrests (2)
- Paint finish: Solid
- Headlight range control
- Particulate filter: Diesel particulate filter (incl. SCR and AdBlue tank)
- Wheels: Steel wheels 6.5 J x 16, in silver (load capacity 1,050 kg)
- Sliding door, on the right in the passenger/cargo area
- Crosswind assist
- Seat belt monitoring system (warning buzzer and light when front seat belts are not fastened)
- Power outlet: 12V socket and 4 cup holders in the dashboard
- Daytime running light
- Lashing eyes for securing cargo
- Heat-insulating glazing (front and rear side windows and rear window in heat-insulating glass (if fitted))
- Registration as a truck (with an N1 registration (up to and including 3.5 t permissible total weight))
- Hill Start Assist
- third brake light
- Electronic Stability Program and ABS
- Omission: Without tachograph
- Electric windows, front
- Transmission: 6-speed transmission
- Weight class front axle (front axle (1,800 kg load capacity))
- Rear doors/tailgate: Hinges for rear doors
- Instrument cluster (km/h) (displays for speed, total/trip distance, engine speed, fuel level and time)
- Steering wheel adjustable in height and reach
- Multifunction display "Plus"
- Upholstery: Seat covers in fabric, design "Austin"
- Wheel cover center
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Keys for locking system: 2 remote control flip keys
- electromechanical power steering
- Seats 1st row: Seat on the right
- Start-stop system (with brake energy recuperation)
- Power outlets: 2 12V sockets in the driver's cab (in the dashboard)
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Central locking with remote control and interior operation
- Accessories: On-board tools

Extra equipment

- Storage compartments (storage compartment above the driver's cab, accessible from the cargo area)
- Storage package 2: Roof gallery with two 1-DIN slots and reading light
- Aluca
- Electrically adjustable and heated exterior mirrors
- Roof rails/roof load carriers: Roof rails for roof load carriers
- Electrical interface for external use (function control unit 1)
- Driver assistance systems: Front Assist area monitoring system with City Emergency Braking function
- Windows: Heated rear window with rear window wiper/washer system
- Cruise control system including speed limiter
- Rear wing doors with window (rear wing doors with window cutouts - rear window)
- Steering wheel: Multifunction steering wheel (3 spokes)
- Marker lights, side
- Radio "Composition Colour" with 4 speakers (Radio "Composition Colour" with 16.5 cm (6.5 inch) touch color display - 2 USB ports (Type C) in the dashboard - illuminated glove compartment with lockable flap - 4 speakers: 2 tweeters, 2 woofers - Car-Net App-Connect - mobile phone interface)
- Rear View reversing camera
- Mud flaps, front and rear
- Seats 1st row: Double passenger seat on the right, with storage compartment, in the 1st row (including headrest, height adjustable)
- Partition walls: Partition wall with fixed window
- Rear step, across half the width
- Storage compartments: Glove compartment with lockable, illuminated flap
- Airbag for driver and front passenger (with passenger airbag deactivation)
- Rigid towbar (including trailer stabilization)
- Batteries: 2nd battery with isolating relay and battery monitoring (AGM battery)
- Deletion: Lettering on the rear (Without lettering for type designation)
- Suspension/damping, reinforced and stabilization, reinforced
- Window: Side window in the passenger/cargo compartment, front right, permanently installed
- air conditioning system with electric control
- LED headlights with LED daytime running lights (headlight range control, automatically regulated)
- Upholstery: Durable fabric seat covers, "Marathon" design
- Radio accessories: Digital radio reception DAB+
- Smoker's version (12V socket with cigarette lighter, ashtray and 4 cup holders in the dashboard)
- Rotating beacons: Preparation of rotating beacon
- Wheels/Tires: Winter tires 235/65 R 16 C 115/113 R mounted on 4 steel wheels
- Hinges for rear doors with an increased opening angle (270°)
- Seats 1st row: "ergoComfort" suspension seat on the left, in the 1st row
- Power outlets in the cab (4 12V sockets in the cab (three in the dashboard, one in the left seat frame))
- Auxiliary water heater (radio remote control)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
3	Front bumper	Front bumper (unpainted) - Scratch(es) - Loss in value
4	Wing mirror - left side	Cap - Scratch(es) - Smart repair
5	Seat - front	Seat cover - left side - Broken / torn - Replace
6	Wheel / tyres	Tyre - rear left side - Porous / cracked - Replace
7	Sill - left side	Sill - Corrosion - Smart repair
8	Door - front left side	Door - dent(s) - Smart repair
9	Body	Body - Glued / labelled - De-glue / neutralise
10	Trim / covers	Trim / covers (Hinten rechts und links) - Broken / torn - Replace
11	Boot lid / rear door	Reflectors - Broken / torn - Replace
12	Door - front left side	Door seal - Broken / torn - Replace
13	Boot lid / rear door	Rear door - left side - Deformed - Repair and paint
14	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
15	Sliding door, right	Sliding door - Dent / paintcoat damage - Repair and paint
16	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Side panel - Dent / paintcoat damage - No deduction
2	Roof	Roof - Dent / paintcoat damage - No deduction
3	Interior	Cargo space partition (Regaleinbauten) - Differs from the original configuration - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Roof - Stub aerial

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 21 Jul 2025	223,98 €
2	Front, Provided by user / customer, from 10 Dec 2025	1.251,73 €
3	Roof, Provided by user / customer, from 14 Jul 2022	1.280,00 €

Accident damages

No.	Accident
1	Rear

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Misc.



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 2: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 3: Front bumper: Front bumper (unpainted) - Scratch(es) - Loss in value



Damage 4: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 4: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 5: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 5: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 5: Seat - front: Seat cover - left side - Broken / torn - Replace



Damage 6: Wheel / tyres: Tyre - rear left side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - rear left side - Porous / cracked - Replace




Damage 6: Wheel / tyres: Tyre - rear left side - Porous / cracked - Replace



Damage 7: Sill - left side: Sill - Corrosion - Smart repair



Damage 7: Sill - left side: Sill - Corrosion - Smart repair



Damage 8: Door - front left side: Door - dent(s) - Smart repair



Damage 8: Door - front left side: Door - dent(s) - Smart repair



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise



Damage 9: Body: Body - Glued / labelled - De-glue / neutralise




Damage 10: Trim / covers: Trim / covers (Hinten rechts und links) - Broken / torn - Replace



Damage 10: Trim / covers: Trim / covers (Hinten rechts und links) - Broken / torn - Replace



Damage 10: Trim / covers: Trim / covers (Hinten rechts und links) - Broken / torn - Replace



Damage 10: Trim / covers: Trim / covers (Hinten rechts und links) - Broken / torn - Replace



Damage 11: Boot lid / rear door: Reflectors - Broken / torn - Replace



Damage 11: Boot lid / rear door: Reflectors - Broken / torn - Replace




Damage 12: Door - front left side: Door seal - Broken / torn - Replace



Damage 12: Door - front left side: Door seal - Broken / torn - Replace



Damage 13: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 13: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 13: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint



Damage 13: Boot lid / rear door: Rear door - left side - Deformed - Repair and paint




Damage 14: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 14: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 15: Sliding door, right: Sliding door - Dent / paintcoat damage - Repair and paint



Damage 16: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 16: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 16: Vehicle glazing: Windscreen - Broken / torn - Replace



Missing part 1: Roof: Stub aerial - Missing - Replace



Accident 1: Rear



Accident 1: Rear




Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Accident 1: Rear



Accident 1: Rear