TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48499636
Order No. / Reference: 27235550
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: GLA 180 d 8G-DCT
VIN: W1N4N1AB2PJ504782	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLA 180 d 8G-DCT	
Vehicle Identification number	W1N4N1AB2PJ504782
Mileage (Read)	113,935 km
First registration	18 Apr 2023
Number of holders	1
Next periodical technical inspection	12/2026
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	193 Tag(e)
Last service on / at	05/2026 at 106,059 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GS691338
Previous damage / Accident	None detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATH 00069		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,135 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Pirelli	3mm / 3mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	215/65 R17 99V	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with HOLD function, hill start assist, pre-filling and drying brakes in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags
- Active Lane Keeping Assist
- Traction control (ASR)
- Automatic passenger airbag deactivation
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Diesel particulate filter
- Tachometer
- DYNAMIC SELECT
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis
- electric parking brake
- Velour floor mats
- Transmission: 8G-DCT dual-clutch automatic transmission, 8-speed
- Heated rear window with timer
- ISOFIX child seat anchorages with Top Tether in the rear
- Mechanical child safety lock
- Communication module (LTE) for the use of Mercedes me connect services
- Headrests 5-way
- Cargo area cover
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Package: Light and Visibility Package
- Upholstery: ARTICO leatherette/fabric
- Radio accessories: Digital radio
- Rain and light sensor
- Remote Services Plus
- Service interval indicator ASSYST
- Seat belts GLA-Class
- Seats: Comfort seats
- Cruise control
- Electronic immobilizer
- Central locking
- Adaptive brake light flashing
- Airbag for driver and front passenger
- Airbag: Side airbag for driver and front passenger
- Active Brake Assist
- Anti-lock braking system (ABS)
- Center console armrest for driver and front passenger with integrated storage compartment
- Outdoor temperature display
- Roof rails in polished aluminum
- Double cup holder
- Third brake light in LED technology
- ECO start/stop function
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Windscreen laminated glass
- Speed Limit Assistant
- Illuminated glove box
- Rear window wiper with intermittent function
- Interior headliner fabric crystal grey
- KEYLESS-GO start function
- Climate: THERMATIC automatic climate control (1-zone climate control - automatically controlled air distribution - recirculation function - tunnel mode in conjunction with navigation system - fine dust filter)
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Parameter steering
- Navigation accessories: Extended MBUX functions
- Package: Non-smoking
- Radio: MBUX multimedia system
- Radio accessories: Touchpad
- Tire pressure monitoring system
- Wheels: 43.2 cm (17") alloy wheels, 4-piece set in 10-spoke design (vanadium silver painted with 215/65 R 17 tires on 6.5 J x 17 ET 44 rims)
- Seats: Rear seat backrests foldable
- High-visibility vest for drivers
- Heat-insulating glass, green all around
- Decorative elements with carbon look

Extra equipment

- Active Parking Assist with PARKTRONIC (Active Parking Assist with PARKTRONIC can not only find parking spaces - it also supports you when parking and exiting. It assists you with steering and, in vehicles with automatic transmission, also with accelerating, braking and gear changes.)
- Package: Business (Hard drive navigation - Smartphone integration - Traffic sign assistant - Preparation for digital key handover - Connectivity package navigation - Seat heating for driver and front passenger - Parking assistant with PARKTRONIC - Preparation for live traffic information)
- Towbar with ESP trailer stabilization
- Paint finish: Metallic (according to sample card)
- LED High Performance headlights (low beam in LED projection technology - high beam with LED reflector technology - daytime running lights, position lights and direction indicators in LED technology - automatic adjustment of the light intensity of the rear lights to the surroundings)
- Heated windshield washer system
- Type designation removed from luggage compartment lid

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Side panel - rear right side	Wheel well extension (Zierleiste) - Deformed - Replace
2	Sill - right side	Sill - dent(s) - Smart repair
3	Sill - left side	Sill - dent(s) - Smart repair
4	Vehicle glazing	Windscreen seal - Broken / torn - Replace
5	Rear bumper	Rear bumper - Deformed - Repair and paint

Repainting

No.	Repainting
1	Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	319 µm	Side panel - rear right side	207 µm
Door - rear right side	164 µm	Door - front left side	158 µm
Door - front right side	224 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Damage 1: Side panel - rear right side: Wheel well extension (Zierleiste) - Deformed - Replace




Damage 1: Side panel - rear right side: Wheel well extension (Zierleiste) - Deformed - Replace



Damage 2: Sill - right side: Sill - dent(s) - Smart repair



Damage 2: Sill - right side: Sill - dent(s) - Smart repair



Damage 3: Sill - left side: Sill - dent(s) - Smart repair




Damage 3: Sill - left side: Sill - dent(s) - Smart repair



Damage 4: Vehicle glazing: Windscreen seal - Broken / torn - Replace



Damage 4: Vehicle glazing: Windscreen seal - Broken / torn - Replace



Damage 5: Rear bumper: Rear bumper - Deformed - Repair and paint



Damage 5: Rear bumper: Rear bumper - Deformed - Repair and paint



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side




Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side



Repainting 1: Boot lid / rear door, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side