TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48374745
Order No. / Reference: 27174487
Inspection date: 27 Oct 2026

Manufacturer: Ford	Model: Transit Connect 220 L1 Autm. Trend Kasten
VIN: WF0RXXWPGRPD77419	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit Connect 220 L1 Autm. Trend Kasten	
Vehicle Identification number	WF0RXXWPGRPD77419
Mileage (Read)	82,192 km
First registration	11 Sept 2023
Number of holders	1
Next periodical technical inspection	01/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	73 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	4 / 2
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Vehicle with smoke odor	no
readiness to drive	Roadworthy

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	9 %
Last service on / at	01/2026 at 63,944 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT896231
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / BUU 01007		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,185 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Continental	4mm / 4mm
2)	205/60 R16 96H	Summer tyres on Steel rim with wheel cover	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Steel	Continental	6mm / 6mm
2)	205/60 R16 96H	Winter tyres on Steel	Continental	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS with EBD
- Exterior mirrors, electrically adjustable and heated
- Battery, reinforced
- Rubberized flooring, front
- Front overhead storage shelf (across the entire width of the interior, including side grab handles)
- Double-leaf rear doors without windows
- Third brake light
- Front electric windows (with one-touch down function for driver's side)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Transmission: 8-speed automatic
- Glove compartment with lid
- Front interior lighting with delay function
- Front air conditioning including semi-electronic recirculation system
- Cargo area lining, side, half-height
- Alternator/Generator
- Fog light
- Emergency brake light (hazard warning flashing activated during heavy braking)
- Wheels: Tire repair kit
- Wheels: Steel wheels 6.5 J x 16 with 205/60 R 16 tires and wheel trims
- Electro-mechanical power steering (EPAS - Electric Power Assisted Steering)
- Automatic security door lock (45 sec.) (Automatic relocking if no door is opened within 45 seconds of unlocking via remote control)
- Sun visor for driver and front passenger
- Front spoiler lip
- Start-stop system
- Dust and pollen filter
- Power outlet: 12-volt connection on the front center console
- Front bumper and rear bumper end caps painted in body color
- Child safety lock on sliding doors
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Driver's side airbag
- Exterior mirrors, narrow mirror format
- Hill start assist
- On-board computer including outside temperature display
- Diesel particulate filter (DPF) (with SCR catalyst and AdBlue tank)
- Tachometer
- Electronic Stability Program (ESP) (with Traction Control (TCS) including Torque Vectoring Control and Adaptive Load Control)
- FordPass Connect (information about the current status or location of the vehicle as well as control of selected vehicle functions via smartphone with the FordPass app - incl. live traffic information in real time (in conjunction with Ford navigation system incl. Ford SYNC 3) - incl. Wi-Fi hotspot)
- Paint finish: Solid
- Cargo area floor protection, plastic, molded
- Steering column, adjustable in height and reach
- Center console, front (open with storage area, 2 cup holders)
- Radio: Ford Audio System 2 (DAB/DAB+ radio - FM/AM radio - USB port - Bluetooth interface - Steering wheel audio remote control)
- Sliding door at rear, right
- Side protection strips, plastic
- Emergency Brake Assist (EBA)
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened seat belts for driver and front passenger)
- Seats: Seat package 4 (driver's seat, 3-way manually adjustable (forward/backward, height, backrest) - single passenger seat, 2-way manually adjustable (forward/backward/backrest) - headrests, height-adjustable - lumbar support, manual (driver's seat) - "Capitol/City" fabric in Ebony (black))
- Daytime running light
- Partition to the cargo area without window
- Door handles, black
- Electronic immobilizer (EPATS)
- Central locking with remote control (door lock only on driver's door - 2 keys, one of which is a remote control key)

Extra equipment

- Electrically adjustable and heated exterior mirrors with blind spot assist (blind spot assist including cross traffic alert)
- Radio: Ford Audio System 9 (Ford navigation system incl. Ford SYNC 3 with AppLink, 6" touchscreen radio (FM/AM), 2 USB ports, audio remote control on the steering wheel, Bluetooth hands-free system and audio streaming, emergency call assistant, SMS text-to-speech function, SMS sending function, voice control, reversing camera, phase diversity antenna, DAB/DAB+, acoustic and visual route guidance, road map for Europe, Apple CarPlay, Android Auto, live traffic, detailed 3D visualization, Michelin travel guide for Europe)
- Floor covering: Front floor mats, all-weather floor mats (2-piece set)
- Cargo area lighting, LED
- Seats: Seat package 35 (driver's seat, 3-way adjustable (forward/backward, backrest, height) - single passenger seat, 2-way adjustable (forward/backward, backrest) - height-adjustable headrests - seat heating for driver and passenger - manually adjustable lumbar support in driver's seat - "Capitol/City" fabric in Ebony (black))
- SORTIMO installation
- SORTIMO vehicle floor
- Xenon: Bi-xenon headlights with LED daytime running lights (with automatic headlight range control)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Wheel cover set - complete - Scratch(es) - Replace
2	Front bumper	Front bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - dent(s) - No deduction
2	Mudguard - left side	Mudguard - left side - dent(s) - No deduction
3	Door - front left side	Door - dent(s) - No deduction
4	Rear bumper	Rear bumper (unpainted) - Dent / paintcoat damage - No deduction
5	Documents	Log book - Missing - No deduction
6	Interior	Cargo space partition (Sortimo Regaleinbau) - Differs from the original configuration - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Equipment - Tirefit complete
Equipment - Vehicle key

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)




Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents



Figure 16: Documents



Figure 17: Documents



Figure 18: Additional tyres



Figure 19: Navigation



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Damage 1: Wheel / tyres: Wheel cover set - complete - Scratch(es) - Replace



Damage 1: Wheel / tyres: Wheel cover set - complete - Scratch(es) - Replace



Damage 1: Wheel / tyres: Wheel cover set - complete - Scratch(es) - Replace



Damage 1: Wheel / tyres: Wheel cover set - complete - Scratch(es) - Replace



Damage 2: Front bumper: Front bumper - Scratch(es) - Paint



Damage 2: Front bumper: Front bumper - Scratch(es) - Paint



Damage 2: Front bumper: Front bumper - Scratch(es) - Paint



Damage 2: Front bumper: Front bumper - Scratch(es) - Paint



Damage 2: Front bumper: Front bumper - Scratch(es) - Paint



Wear and tear 5: Documents: Log book - Missing - No deduction



Missing part 1: Equipment: Tirefit complete - Missing - Replace



Missing part 2: Equipment: Vehicle key - Missing - Replace