MACADAM

BMW X3


Vehicle information

Brand:	**BMW**	License plate:	**2DQG727**
Gearbox:		Body color:	
Model:	**X3**	LEVEL:	**WBA61DP0209R73362**
Fuel type:		Power:	**120 kW**
Version:	**2.0 XDRIVE30E (120KW) AUTO**	First registration	**24/05/2023**
Mileage:	**51238 km**	Number of doors:	


Summary of damages


Back	3
RIGHT	1
Interior	1
Roof & other	2


Commercial photos




















Equipment corresponding to the VIN according to the manufacturer's information

Center armrest	Airbag	Roof bars	Automatic transmission
Rain sensor	Distance control	Battery current	Power steering
Electrical operation of windows	GPS	Alloy wheels	Electrically adjustable mirrors
Sport Seats	Phone	Central locking	Leather steering wheel
Multifunction steering wheel	Sports steering wheel		

Options according to the inspector

GPS	**Yes**

Damages

Bodywork
Damaged - Acceptable.
Roof & other





Damaged **Bodywork**
E - Replace
Roof & Others





Rear bumper trim
dent(s)
E - Replace
Rear





Damaged **Interior**
- Acceptable
Interior






Rear bumper molding -
Dent(s) and scratch(es)
- Repair and paint (complete)
Rear






Rear Bumper Dent
(s)
LI - Repair and Paint (Complete)
Rear







Right rear door
dent(s) - Paintless dent repair




Tires

Front Left
Summer
Aluminum
225/60/18/104/W
Yokohama
8.0 mm
Front Right
Summer
Aluminum
225/60/18/104/W
Yokohama
7.0 mm
Left Back
Summer
Aluminum
225/60/18/104/W
Yokohama
6.0 mm
Rear Right
Summer
Aluminum
225/60/18/104/W
Yokohama
6.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**Yes**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**P/A**	Jack	**P/A**
Interview	**OK**	Interview	**over 6000 km**
Galette	**P/A**	Repair kit	**P/A**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**0**
Nbre clés total	**2**	Réinitialisation des paramètres d'usine	**Oui, le véhicule a été réinitialisé aux paramètres d'usine**
Roue de secours	**P/A**	Runflat	**P/A**
Type de carnet d'entretien	**Entretien digital**		

Détails du NIV

ABS (antiblocage des freins)	Accoudoir central arrière avec 2 porte-boissons	Accoudoir central avant avec compartiment de rangement
Actionnement automatique du hayon	Active Guard	Active Park Distance Control
Affichage de la pression de gonflage	Air Breather en Schwarz mat	Airbag conducteur
Airbag passager	Airbags latéraux avant	Airbags tête avant et arrière
Antidémarrage électronique (EWS III)	Attention Assist	Avertisseur acoustique pour piétons
Batterie haute tension garantie 6 ans 100.000 km	BMW Live Cockpit Navigation Plus	BMW TeleServices
Boîte de vitesses automatique Steptronic	Boulons antivol	Bouton start/stop
Brake Energy Regeneration	Câble de charge rapide+câble standard	Caméra de recul
CBC (cornering brake control)	Check Control	Climatisation à réglage électronique 3 zones
Climatiseur indépendant	Colonne de direction réglable en hauteur et en longueur	Combiné d'instrumentation avec écran 5.1''
Concierge Services (info Callcenter BMW) via SIM	Connected Music (3 ans)	Connected Parking (3 ans)
ConnectedDrive Services (BMW Online) via SIM	Console centrale avec compartiment de rangement et 2 porte-boissons	Cruise Control
DAB-tuner	Démarrage sans clé	Désactivation airbag passager
Deux sorties échappement gauche/droite chromées	Direction assistée	Dossier de siège arrière rabattable 40/20/40
Driving Experience Control incl. ECO PRO	DSC - Contrôle dynamique de la stabilité	DTC (Contrôle Dynamique de Traction)
Eclairage d'accompagnement ''Follow-Me-Home''	Eclairage d'accueil	eDrive Services
Extérieur Line Aluminium satiné	Feux stop dynamiques	Filet de séparation du compartiment à bagages
Filtre à charbon actif	Filtre à particules Otto (OPF)	Fixation Isofix sièges enfants AR
Fonction Auto start/stop	Frein de stationnement électrique avec Autohold	Garantie jusqu'à 3 ans sans limite de kilométrage
Gicleurs de lave-glace chauffants	Haut-parleurs AV/AR (6)	HDC (hill descent control)
iDrive avec 8 touches de raccourci programmables	iDrive Controller sur console centrale	Indicateur de crevaison
Inserts Schwarz hochglänzend+Perglanz Chrom	Intelligent emergency call	JAV rayons en V 618 7Jx18''+225/60 R18 104W
Kit mains-libres Bluetooth avec connexion USB	Kit sécurité (triangle-trousse-extincteur-veste)	Lateral Parking Aid
LED Headlights	Lève-vitres électriques à l'arrière	Lève-vitres électriques à l'avant
Limiteur de vitesse	Littérature de bord en néerlandais	Logo 'X' panneaux porte AV+'X3' console centrale
Logo 'X3' dans le montant B	Naseaux contours chromés+barreaux Schwarz hochgl.	Park Assist
Park Distance Control (PDC) avant et arrière	Peinture métallisée	Peinture unie Schwarz
Personal Profile	Apple CarPlay preparation	Preparation for High Beam Assist
Power outlet (12V) in luggage compartment	Power outlet in the center console	Passive protection of pedestrians
Radio Professional RDS	Satin aluminum roof mounting rails	Real Time Traffic Information - RTTI
Automatic adjustment of passenger-side mirror as a parking aid	Remote Services (remote vehicle functions)	Driver's side rearview mirror with automatic anti-glare function
Auto-dimming interior rearview mirror.	Electric and heated exterior mirrors	Electrically folding exterior mirrors
Reversing Assistant	Perforated Sensatec interior lining	Rain sensor and light sensor
Servotronic	BMW sport seats for driver and passenger	Smartphone integration
Velvet carpeting at the front and rear	Comfort telephony + extended smartphone connectivity	Central locking with remote control
German language version including English and French	Heat-insulating windows tinted green	Leather steering wheel
Multifunction steering wheel	Sports steering wheel	

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.